

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHB44895

DATE: 23. Jan. 2020

MAKE : HYUNDAI

MODEL : i40

DOA: 23. Jan. 2020

CHINA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	Front Bumper Cover Br ✓			\$544.50
1	Front Bumper Side Bracket – RH xnn			\$24.60
1	Front Bumper Top Bracket – RH xnn ?			\$22.40
10	Front Bumper Clips nec ✓		\$2.20	\$22.00
1	Front Bumper Grille – RH xnn			\$41.60
1	Headlamp – RH Br ✓			\$1,388.00
1	Headlamp Support Panel xnn			\$907.40
1	Front Fender – RH Br ✓			\$566.30
1	Front Fender Shield – RH xnn			\$174.90
1	Front Wheel Cover – RH Scr ✓			\$107.10
1	Bonnet x(R)			\$2,265.90
1	Bonnet Hinge – RH xnn			\$41.00
1	Steering Tie Rod End – RH ?			\$62.60
SUB TOTAL				\$6,168.30
LESS 20%				\$1,233.66
DISCOUNTED TOTAL				\$4,934.64
				2627.9
				2102.32
1 Advertisement – LHF Fender nec ✓				\$100.00
Acknowledged by Repairer				Nett
Signature:				
Date:				
Labour Charge				
1	Panel Beating			\$600.00
1	Spray Painting Charge			\$500.00
1	Tuff Kote			\$50.00
1	Wiring Charge			\$50.00
1	Front Wheel Alignment			\$120.00
TOTAL LABOUR				\$1,320.00
ESTIMATE TOTAL				\$6,354.64
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Larry Ng

Ram (LKK)
 24/1/2020 1130 hrs
 Panasura maitra to ram
 88622728 hp
 L/S
 after repair photo
 3 repair days

\$560
 \$400
 \$30
 \$80