

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SMF348L
TP/MSIG

M/S : MSIG INSURANCE (S) PTE LTD (SGX)
16 RAFFLES QUAY
#24-01 HONG LEONG BUILDING
SINGAPORE 048581

TEL: 68277660 FAX: 62257402
ATTN: Motor Claim Department

Estimate No: ES2090405/WS
Date: 19 May 2020
Policy No: 5104425902-01
Veh Reg No: SMF348L
Make/Model: HYUNDAI ELANTRA
AD 1.6 GLS
Chassis No: KMHD841CMJU756636
Engine No:
Reg. Date: 26/10/2018

WS Ref: TP/MSIG
Claim Type: Third Party
Accident Date: 11/01/2020
TP Veh Reg No: SJN5845D

Not Withain
Recovery B4 paint
3 days

8 2132-16

Estimate Repair Cost to Vehicle No :SMF348L

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 FRONT BUMPER	474.40	1 PC	474.40	✓
2 FRONT BUMPER LH SIDE RETAINER	28.50	1 PC	28.50	✓
3 FRONT BUMPER LH FOG LAMP	265.00	1 PC	265.00	X
4 FRONT BUMPER LH FOG LAMP GARNISH	115.40	1 PC	115.40	X
5 FRONT BUMPER LH DAY LIGHT	193.20	1 PC	193.20	X
6 FRONT BUMPER CLIP	3.50	6 PC	21.00	✓
7 HEADLAMP LH	1,198.80	1 PC	1,198.80	✓
			2,296.30	
		Less 20%	459.26	1,837.04
Labour				
8 REMOVE & REFIX FRT BUMPER ASSY, HEADLAMPS, FOG LAMPS, GRILLE; KNOCKING & REPAIR FRT BUMPER REINFORCEMENT & REALIGN THE SAME	400.00	1 LA	400.00	300h
9 PUTTY & RESPRAY ON FRT BUMPER, LOWER SKIRT, FRT LH FENDER	450.00	1 LA	450.00	400h
			850.00	850.00

2741.04 Total S\$ 2,687.04
Add GST @ 7% 188.09
Total Amount Payable S\$ 2,875.13

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE