

# AERO GARAGE PTE LTD

Blk 160, Sin Ming Drive, #08-07 Sin Ming AutoCity, Singapore 575722

Tel : 6266 9511 Fax : 6266 9512

Vehicle No : SKU8239K  
Vehicle Model : Volkswagen Touran

## Estimate Repair Cost

No.	Qty	<u>Parts List Items</u>		
1	1	Rear bumper	\$	971.50
2	2	Rear bumper retainers	\$	88.90
3	1 set	Rear bumper clips	\$	40.00
4	2	Rear bumper brackets	\$	128.10
5	1	Rear bumper reflectors	\$	118.40
6	1	Rear tailgate	\$	1,723.90
7	1	Rear tailgate centre logo	\$	87.00
8	2	Rear tailgate "TOURAN" emblem	\$	80.00
9	1	Rear tailgate "TSI" emblem	\$	54.00
10	2	Rear tailgate number plate lamp	\$	62.30
11	2	Rear tailgate hinges	\$	244.80
12	1	Rear tailgate lock	\$	167.10
13	1	Rear tailgate weatherstrip	\$	359.10
14	1	Rear tailgate inner trim board	\$	301.90
15	1	Rear tailgate inner trim clips	\$	40.00
16	2	Taillamps (inner & outer)	\$	801.20
17	1	Rear end panel	\$	411.70
18	1	Rear end panel top garnish	\$	183.40
19	1	Rear spare tyre top board	\$	350.80
20	1	Rear floor panel	\$	841.50
21	1	Rear exhaust silencer	\$	899.30
22	1	Rear exhaust silencer mounting	\$	92.10
			Total	<u>\$ 8,047.00</u>

## Parts Special Nett Items

23	1	Rear number plate	\$	60.00
24	1	Reverse camera	\$	250.00
25	1 set	Reverse sensor	\$	250.00
				<u>\$ 560.00</u>
			Total Parts	<u>\$ 8,607.00</u>

Labour

1	Labour charge to remove, cut out damage portion, jack out, straighten, panel beating, welding, align and renew replaced parts.	\$ 1,500.00
2	To putty and respray painting on affected areas.	\$ 1,200.00
3	To remove, replace rear tailgate fittings to facilitate repair.	\$ 300.00
4	To remove, replace rear windscreen glass.	\$ 150.00
5	To remove, replace rear reverse sensor.	\$ 150.00
6	To remove, replace rear exhaust silencer.	\$ 150.00
7	To check wiring and lightings.	\$ 80.00
	Total Labour	<u>\$ 3,530.00</u>
	Total Parts and Labour	<u>\$ 12,137.00</u>