

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Feb 2020		04 Feb 2020 09:52 Edit Adj Rpt	S\$3,200.00 Edit Estimates	S\$3,200.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	JONG FRESH SUPPLIES PTE LTD , Co. Reg. No.: 200107204H								
Main Claimant:	NIENTRADE PTE LTD , Co. Reg. No.: 201910533W								
Vehicle Reg. No.:	SKU8239K	Date of Loss:	18/01/2020 07:00 - :59 [53 Months From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 618855	Policy/Cover Note No.:	B29116806TMV (Third Party Only) Coverage: 08/03/2019 - 07/03/2020						
Vehicle Reg. No. (Insured):	GBB7945T	Policy No. (Claimant):							
		Excess:							
Repairer:	Heng Yap Seng Auto Services - (sin Ming Drive) (HQ) BLK 160 SIN MING DRIVE, #08-13 SIN MING AUTOCITY, 575722 Sin Ming - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 05/03/2020]								
Driver/Custodian (Insured):	CHUA CHEOW MENG (52 / Male), NRIC: S1821202A, Tel: +6596218467 Email:								
Adj Asg. Remarks:	on WP. Liab: clear. Agree on SJE. Assign: Kenneth Kong from LKK Auto Consultants Pte Ltd. Contact: Mr Chong Han Meng @ 9183 3008.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKU8239K (618855)**
[GBB7945T]
TP
NIENTRADE PTE LTD
Jan 18 2020 7:00AM
[JONG FRESH SUPPLIES PTE LTD]
Heng Yap Seng Auto Services - (sin Ming Drive)

Upload Documents		Upload Photos	Compose New Letter	View View in Browser <input type="button" value="v"/>
Assessment Reports				1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/03/20 10:45	Adjuster Immediate Advice	Load HTM	<input type="checkbox"/>
Photos/Images				3 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/03/20 10:38	General View	Load JPG	<input checked="" type="checkbox"/>
2	17/03/20 10:38	General View	Load JPG	<input checked="" type="checkbox"/>
3	17/03/20 10:38	General View	Load JPG	<input checked="" type="checkbox"/>
4	17/03/20 10:38	General View	Load JPG	<input checked="" type="checkbox"/>
5	17/03/20 10:38	General View	Load JPG	<input checked="" type="checkbox"/>
6	17/03/20 10:38	General View	Load JPG	<input checked="" type="checkbox"/>
7	17/03/20 10:38	General View	Load JPG	<input checked="" type="checkbox"/>
8	17/03/20 10:38	General View	Load JPG	<input checked="" type="checkbox"/>
9	17/03/20 10:38	General View	Load JPG	<input checked="" type="checkbox"/>
10	17/03/20 10:38	General View	Load JPG	<input checked="" type="checkbox"/>
11	17/03/20 10:38	General View	Load JPG	<input checked="" type="checkbox"/>
12	17/03/20 10:38	General View	Load JPG	<input checked="" type="checkbox"/>
13	17/03/20 10:39	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
14	17/03/20 10:39	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	03/02/20 15:17	TPD SKU8239K GIA REPORT <small>From: SC - Reg. No: GBB7945T, Claimant: JONG FRESH SUPPLIES PTE LTD</small>	Load PDF	<input type="checkbox"/>
2	03/02/20 15:18	TPD SKU8239K - PRI	Load PDF	<input type="checkbox"/>
3	03/02/20 15:58	Agree on SJE	Load PDF	<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No.199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20001859/KVF3E2

Date: 30/03/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No: B29116806TMV
Claimant Vehicle No : SKU8239K	Insured Vehicle No : GBB7945T
Date of Loss: 18/01/2020	Nature of Claim: TP Claim No: 618855

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKU8239K	Engine No:	CAYAU0581
Make & Model:	VOLKSWAGEN TOURAN, 1.6 TDI (A)	Chassis No:	WVGZZZ1TZFW046588
Reg. Date:	18/08/2015 (Man. Year: 2014)	Odometer:	84944 km
Colour:	Metallic Dark Blue		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,607.00	2,860.76	5,746.24	66.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,530.00	1,250.00	2,280.00	64.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,137.00	4,110.76	8,026.24	66.13
Approved Total (Overridden) (S\$)		3,200.00		
(S\$)	12,137.00	3,200.00	8,937.00	73.63
+ GST 7.00/7.00% (S\$)	849.59	224.00	625.59	73.63
Nett Amount (S\$)	12,986.59	3,424.00	9,562.59	73.63

INSPECTION

Date of Assignment:	04/02/2020	
Date Inspected:	04/02/2020 Inspected At:	BLK 160 SIN MING DRIVE, #08-13 SIN MING AUTOCITY Singapore 575722 Repairer: Aero Garage Pte Ltd
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 30 Mar 2020)
Parts: M1-MPV	VOLKSWAGEN TOURAN 1.6 TDI (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKU8239K)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	971.50 F	*971.50 FL
2	2		*REAR BUMPER RETAINERS	Serviceable	88.90 F	*- FL
3	1		*SET REAR BUMPER CLIPS	Necessary	40.00 F	*40.00 FL
4	2		*REAR BUMPER BRACKETS	Repair	128.10 F	*- FL
5	1		*REAR BUMPER REFLECTORS	Serviceable	118.40 F	*- FL
6	1		*REAR TAILGATE	Bent	1,723.90 F	*1,723.90 FL
7	1		*REAR TAILGATE CENTRE LOGO	Necessary	87.00 F	*87.00 FL
8	2		*REAR TAILGATE TOURAN EMBLEM	Necessary	80.00 F	*80.00 FL
9	1		*REAR TAILGATE TSI EMBLEM	Necessary	54.00 F	*54.00 FL
10	2		*REAR TAILGATE NUMBER PLATE LAMP	Serviceable	62.30 F	*- FL
11	2		*REAR TAILGATE HINGES	Repair	244.80 F	*- FL
12	1		*REAR TAILGATE LOCK	Repair	167.10 F	*- FL
13	1		*REAR TAILGATE WEATHERSTRIP	Serviceable	359.10 F	*- FL
14	1		*REAR TAILGATE INNER TRIM BOARD	Serviceable	301.90 F	*- FL
15	1		*REAR TAILGATE INNER TRIM CLIPS	Not Necessary	40.00 F	*- FL
16	2		*TAILLAMPS (INNER & OUTER)	Serviceable	801.20 F	*- FL
17	1		*REAR END PANEL	Repair	411.70 F	*- FL
18	1		*REAR END PANEL TOP GARNISH	Serviceable	183.40 F	*- FL
19	1		*REAR SPARE TYRE TOP BOARD	Serviceable	350.80 F	*- FL
20	1		*REAR FLOOR PANEL	Repair	841.50 F	*- FL
21	1		*REAR EXHAUST SILENCER	Repair	899.30 F	*- FL
22	1		*REAR EXHAUST SILENCER MOUNTING	Serviceable	92.10 F	*- FL
23	1		*REAR NUMBER PLATE	Serviceable	60.00 FS	*- FS
24	1		*REVERSE CAMERA	Serviceable	250.00 FS	*- FS
25	1		*SET REVERSE SENSOR	Dented	250.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,607.00	3,156.40
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	295.64
Total Parts (\$\$)	8,607.00	2,860.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGE TO REMOVE, CUT OUT DAMAGE PORTION, JACK OUT, STRAIGHTEN, PANEL BEATING, WELDING, ALIGN AND RENEW REPLACED PARTS	New	1,500.00	500.00
2	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREAS	New	1,200.00	500.00
3	TO REMOVE, REPLACE REAR TAILGATE FITTINGS TO FACILITATE REPAIR	New	300.00	60.00
4	TO REMOVE, REPLACE REAR WINDSCREEN GLASS	New	150.00	120.00
5	TO REMOVE, REPLACE REAR REVERSE SENSOR	New	150.00	50.00
6	TO REMOVE, REPLACE REAR EXHAUST SILENCER	New	150.00	0.00
7	TO CHECK WIRING AND LIGHTINGS	New	80.00	20.00
Gross Labour Cost (S\$)			3,530.00	1,250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >