

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) for survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed
- is subject to final approval from Insurance Company

Acknowledged by Repairer

Vehicle number: SFE7987J

Date:

YSK Auto Workshop

No. 1 Raki Bukit Avenue 6, #01-49 (Autobay), Singapore 417883

H/P: 9640 2541

Email: dannyskyeo@gmail.com

WDD2120342A817067

Vehicle Made & Model: MERCEDES-BENZ E200

7P China

Jia Le

Qty	List Items	Amount \$
1	Rear bumper <i>deformed</i>	1,831.50 /630
1	Rear bumper tow cover <i>deformed</i>	41.20 ✓
2	Rear bumper chrome mouldings @ 110.25 <i>RH crumpled</i>	220.50 110.25
4	Rear bumper PDC sensors @ 313.75 <i>1 piece damaged</i>	1,255.00 313.75
1	Rear bumper difusser <i>deformed</i>	280.60 ✓
1	Rear bumper CTR guide <i>crumpled</i>	181.50 ✓
1	Rear bumper reinforcement <i>dented</i>	765.50 ✓
1	Rear boot M/B logo	68.85 +
1	Rear boot emblem "E200"	86.90 +
1	Rear boot emblem "7G TRONIC" <i>HP</i>	89.90 +
2	Rear boot lamps - L/R @ 310.50 <i>Nec</i>	621.00 +
1	Rear boot w/strip	211.40 +
1	Rear boot lock	370.50 +
1	Rear end panel <i>Repair</i>	1,018.50 X
2	Rear taillamps - L/R @ 685 <i>RH crumpled</i>	1,370.00 685
2	Rear taillamp lower brackets - L/R @ 86.50 <i>RH crumpled</i>	173.00 41
Sub-total		8,585.85
Less 10%		858.59
Total List		7,727.27

4048.80

3643.92

Labour charges

To check rear electrical wiring	50.00 30
To remove, refix rear interior trim to assist repair	120.00 50
To reinstall PDC sensor, reset & check proper function	180.00 60
To respray undercoating	80.00 40
To respray painting and etc	1,080.00 400
Panel beating, cut, weld remove & replacing above parts	1,050.00 400
Total Labour	2,560.00

780

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$

10,287.27

total: 4623.92

4/5: 3.7K