

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Feb 2020 Edit Reg		03 Feb 2020 00:00 Edit Adj Rpt	S\$8,400.00 Edit Estimates	S\$8,400.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS				[Created by adjuster]					
Insured:	EDU-VENTURE PTE LTD, Co. Reg. No.: 199306489K								
Main Claimant:	BIS MOTORING PTE LTD								
Vehicle Reg. No.:	SMF3619K	Date of Loss:	31/01/2020 17:00 - :59 [14 Months and 24 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 8910570525SG	Policy/Cover Note No.:	2100264260 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKB8298P	Policy No. (Claimant):	Excess:						
Repairer:	Tan Lim Motor Pte Ltd (Defu) 1 Defu Lane 6, 539365 Defu Lane - Tel: 6858 5151								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 13/02/2020]								
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
<ul style="list-style-type: none"> AIG_SG_EXPRESS (02/09/2020): Alert - Adj Mandate Approved (S\$8990.00) - SMF3619K - Claim Handler: Lee, Ming-Y... AIG_SG (05/02/2020): TP GIA report 									
ALL ASSOCIATED TASKS				View All Search Tasks Create New Task Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SMF3619K (8910570525SG)**
[SKB8298P]
TP
BIS MOTORING PTE LTD
Jan 31 2020 5:00PM
[EDU-VENTURE PTE LTD]
Tan Lim Motor Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser
Video			1 per page v <input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print
1	06/02/20 16:01	Video - Accident (TP)	1 Load MP4
Letters/Correspondences			1 per page v <input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	1 Edit
Photos/Images			3 per page v <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print
1	05/02/20 09:28	Chassis Number	1 Load JPG <input checked="" type="checkbox"/>
2	05/02/20 09:28	Odometer Reading	1 Load JPG <input checked="" type="checkbox"/>
3	05/02/20 09:29	General View	1 Load JPG <input checked="" type="checkbox"/>
4	05/02/20 09:29	General View	1 Load JPG <input checked="" type="checkbox"/>
5	05/02/20 09:29	General View	1 Load JPG <input checked="" type="checkbox"/>
6	05/02/20 09:29	General View	1 Load JPG <input checked="" type="checkbox"/>
7	05/02/20 09:29	General View	1 Load JPG <input checked="" type="checkbox"/>
8	05/02/20 09:29	General View	1 Load JPG <input checked="" type="checkbox"/>
9	05/02/20 09:29	General View	1 Load JPG <input checked="" type="checkbox"/>
10	05/02/20 09:29	General View	1 Load JPG <input checked="" type="checkbox"/>
11	05/02/20 09:29	General View	1 Load JPG <input checked="" type="checkbox"/>
12	05/02/20 09:29	General View	1 Load JPG <input checked="" type="checkbox"/>
13	05/02/20 09:29	General View	1 Load JPG <input checked="" type="checkbox"/>
14	05/02/20 09:29	General View	1 Load JPG <input checked="" type="checkbox"/>
15	05/02/20 09:29	General View	1 Load JPG <input checked="" type="checkbox"/>
16	05/02/20 09:29	General View	1 Load JPG <input checked="" type="checkbox"/>
17	05/02/20 09:29	General View	1 Load JPG <input checked="" type="checkbox"/>
18	05/02/20 09:29	General View	1 Load JPG <input checked="" type="checkbox"/>
19	05/02/20 09:29	General View	1 Load JPG <input checked="" type="checkbox"/>
20	05/02/20 09:29	General View	1 Load JPG <input checked="" type="checkbox"/>
21	05/02/20 09:29	General View	1 Load JPG <input checked="" type="checkbox"/>
22	05/02/20 09:29	General View	1 Load JPG <input checked="" type="checkbox"/>
23	05/02/20 09:29	General View	1 Load JPG <input checked="" type="checkbox"/>
24	05/02/20 09:29	General View	1 Load JPG <input checked="" type="checkbox"/>
25	05/02/20 09:29	General View	1 Load JPG <input checked="" type="checkbox"/>
26	05/02/20 09:29	General View	1 Load JPG <input checked="" type="checkbox"/>
27	05/02/20 09:29	General View	1 Load JPG <input checked="" type="checkbox"/>
28	05/02/20 09:29	General View	1 Load JPG <input checked="" type="checkbox"/>
29	05/02/20 09:29	General View	1 Load JPG <input checked="" type="checkbox"/>
30	05/02/20 09:29	General View	1 Load JPG <input checked="" type="checkbox"/>
31	05/02/20 09:29	General View	1 Load JPG <input checked="" type="checkbox"/>
32	05/02/20 09:29	General View	1 Load JPG <input checked="" type="checkbox"/>
33	05/02/20 09:29	General View	1 Load JPG <input checked="" type="checkbox"/>
34	05/02/20 09:29	General View	1 Load JPG <input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
35	05/02/20 09:29	General View		<input checked="" type="checkbox"/>
36	05/02/20 09:29	General View		<input checked="" type="checkbox"/>
37	05/02/20 09:29	General View		<input checked="" type="checkbox"/>
38	05/02/20 09:29	General View		<input checked="" type="checkbox"/>
39	05/02/20 09:29	General View		<input checked="" type="checkbox"/>
40	05/02/20 09:29	General View		<input checked="" type="checkbox"/>
41	05/02/20 09:29	General View		<input checked="" type="checkbox"/>
42	05/02/20 09:29	General View		<input checked="" type="checkbox"/>
43	05/02/20 09:29	General View		<input checked="" type="checkbox"/>
44	05/02/20 09:29	General View		<input checked="" type="checkbox"/>
45	05/02/20 09:29	General View		<input checked="" type="checkbox"/>
46	05/02/20 09:29	General View		<input checked="" type="checkbox"/>
47	05/02/20 09:29	General View		<input checked="" type="checkbox"/>
48	05/02/20 09:29	General View		<input checked="" type="checkbox"/>
49	05/02/20 09:29	General View		<input checked="" type="checkbox"/>
50	05/02/20 09:29	General View		<input checked="" type="checkbox"/>
51	05/02/20 09:29	General View		<input checked="" type="checkbox"/>
52	05/02/20 09:29	General View		<input checked="" type="checkbox"/>
53	05/02/20 09:29	General View		<input checked="" type="checkbox"/>
54	05/02/20 09:29	General View		<input checked="" type="checkbox"/>
55	05/02/20 09:29	General View		<input checked="" type="checkbox"/>
56	05/02/20 09:29	General View		<input checked="" type="checkbox"/>
57	05/02/20 09:29	General View		<input checked="" type="checkbox"/>
58	05/02/20 09:29	General View		<input checked="" type="checkbox"/>
59	05/02/20 09:29	General View		<input checked="" type="checkbox"/>
60	05/02/20 09:29	General View		<input checked="" type="checkbox"/>
61	05/02/20 09:30	General View		<input checked="" type="checkbox"/>
62	05/02/20 09:30	General View		<input checked="" type="checkbox"/>
63	05/02/20 09:30	General View		<input checked="" type="checkbox"/>
64	05/02/20 09:30	General View		<input checked="" type="checkbox"/>
65	05/02/20 09:30	General View		<input checked="" type="checkbox"/>
66	05/02/20 09:30	General View		<input checked="" type="checkbox"/>
67	05/02/20 09:30	General View		<input checked="" type="checkbox"/>
68	05/02/20 09:30	General View		<input checked="" type="checkbox"/>
69	05/02/20 09:30	General View		<input checked="" type="checkbox"/>
70	05/02/20 09:30	General View		<input checked="" type="checkbox"/>
71	05/02/20 09:30	General View		<input checked="" type="checkbox"/>
72	05/02/20 09:30	General View		<input checked="" type="checkbox"/>
73	05/02/20 09:30	General View		<input checked="" type="checkbox"/>
74	05/02/20 09:30	General View		<input checked="" type="checkbox"/>
75	05/02/20 09:30	General View		<input checked="" type="checkbox"/>
76	05/02/20 09:30	General View		<input checked="" type="checkbox"/>
77	05/02/20 09:30	General View		<input checked="" type="checkbox"/>
78	05/02/20 09:30	General View		<input checked="" type="checkbox"/>
79	05/02/20 09:30	General View		<input checked="" type="checkbox"/>
80	05/02/20 09:30	General View		<input checked="" type="checkbox"/>
81	05/02/20 09:30	General View		<input checked="" type="checkbox"/>
82	05/02/20 09:30	General View		<input checked="" type="checkbox"/>
83	05/02/20 09:30	General View		<input checked="" type="checkbox"/>
84	05/02/20 09:30	General View		<input checked="" type="checkbox"/>
85	05/02/20 09:30	General View		<input checked="" type="checkbox"/>
86	05/02/20 09:30	General View		<input checked="" type="checkbox"/>
87	05/02/20 09:30	General View		<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	05/02/20 09:30	General View	 Load JPG	<input checked="" type="checkbox"/>
89	05/02/20 09:30	General View	 Load JPG	<input checked="" type="checkbox"/>
90	05/02/20 09:30	General View	 Load JPG	<input checked="" type="checkbox"/>
91	05/02/20 09:30	General View	 Load JPG	<input checked="" type="checkbox"/>
92	05/02/20 09:30	General View	 Load JPG	<input checked="" type="checkbox"/>
93	05/02/20 09:30	General View	 Load JPG	<input checked="" type="checkbox"/>
94	05/02/20 09:30	General View	 Load JPG	<input checked="" type="checkbox"/>
95	05/02/20 09:30	General View	 Load JPG	<input checked="" type="checkbox"/>
96	05/02/20 09:30	General View	 Load JPG	<input checked="" type="checkbox"/>
97	05/02/20 09:30	General View	 Load JPG	<input checked="" type="checkbox"/>
98	05/02/20 09:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	05/02/20 09:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	05/02/20 09:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	05/02/20 09:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	05/02/20 09:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	05/02/20 09:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	05/02/20 09:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	05/02/20 09:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	05/02/20 09:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	05/02/20 09:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	05/02/20 09:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	05/02/20 09:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	05/02/20 09:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	05/02/20 09:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	05/02/20 09:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	05/02/20 09:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	05/02/20 09:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	05/02/20 09:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	05/02/20 09:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	05/02/20 09:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	05/02/20 09:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	05/02/20 09:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
120	05/02/20 09:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
121	05/02/20 09:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
122	05/02/20 09:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
123	05/02/20 09:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
124	05/02/20 09:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
125	05/02/20 09:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
126	05/02/20 09:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
127	05/02/20 09:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
128	05/02/20 09:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
129	05/02/20 09:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
130	05/02/20 09:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
131	05/02/20 09:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
132	05/02/20 09:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
133	05/02/20 09:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
134	05/02/20 09:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
135	05/02/20 09:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
136	05/02/20 09:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
137	05/02/20 09:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
138	05/02/20 09:32	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
139	05/02/20 09:32	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
140	05/02/20 09:32	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
141	05/02/20 09:32	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
142	05/02/20 09:32	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
143	05/02/20 09:32	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
144	05/02/20 09:32	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
145	05/02/20 09:32	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
146	05/02/20 09:32	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
147	05/02/20 09:32	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
148	05/02/20 09:32	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
149	05/02/20 09:32	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
150	05/02/20 09:32	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
151	05/02/20 09:32	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
152	05/02/20 09:32	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
153	05/02/20 09:32	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
154	05/02/20 09:32	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
155	05/02/20 09:32	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
156	05/02/20 09:32	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
157	09/04/20 17:11	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
158	09/04/20 17:11	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
159	09/04/20 17:11	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
160	09/04/20 17:11	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
161	09/04/20 17:11	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
162	09/04/20 17:11	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/02/20 14:30	TP GIA REPORT	Load PDF	
2	06/02/20 16:03	EMAIL TO OI	Load PDF	
3	11/02/20 11:56	LETTER TO OI	Load PDF	
4	26/02/20 10:38	OI AMENDED GIA REPORT	Load PDF	
5	15/06/20 12:13	Calculation slip	Load PDF	
6	15/06/20 12:24	FINALIZED MARKED ESTIMATE	Load PDF	
7	15/06/20 17:20	LOD, REPAIR BILL, GIA SEARCH, ATA, POLICE INVESTIGATION OUTCOME	Load PDF	
8	15/09/20 11:56	Authorisation to Act	Load PDF	
9	15/09/20 11:56	GIA SEARCH	Load PDF	
10	15/09/20 11:56	LOD	Load PDF	
11	15/09/20 11:56	PIR	Load PDF	
12	15/09/20 11:56	Release Voucher	Load PDF	
13	15/09/20 11:56	WORKSHOP INVOICE	Load PDF	

No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	05/02/20 11:22	OI GIA REPORT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SKB8298P (Insd veh)	Model:	KIA CARENS 1.7 D DCT 5DR FWD (A)
	SMF3619K (TP veh)		
Date of Accident:	31/01/2020		

Global Sum Settlement	:	[] Yes	[X] No
Repair Estimate	:\$		18,437.17
Final Repair Cost	:\$		8,988.00
Loss of Use	:\$		days at \$0.00 per day
Rental (if any)	:\$		days
LTA / GIA Search Fee	:\$		2.00
Others:	:\$		
	:\$		
Final Settlement Sum	:\$		8,990.00

Is Third Party Workshop GIA Registered?		<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	(Kindly indicate below)
A) For <u>Non GIA Registered Workshop</u>:	Agreed Liability _____ (%)			
B) For <u>GIA Registered Workshop</u>:	BOLA Applicable: Yes/ No BOLA Scenario No: <u>28</u>			
BOLA Liability: _____ 100 _____ (%)	Assessed Liability (*): _____ 100 _____ (%)			
<i>* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.</i>				
Remarks _____				

Payment Instruction: Payee's Breakdown			
1)	Tan Lim Motor Pte Ltd	:\$	8,990.00
2)		:\$	

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

15 Sep
2020

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG20001889/HKS3S2**Date:** 15/09/2020REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100264260
Claimant Vehicle No :	SMF3619K	Insured Vehicle No :	SKB8298P
Date of Loss:	31/01/2020	Nature of Claim:	TP
		Claim No:	8910570525SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMF3619K	Engine No:	D4FDJH553906
Make & Model:	KIA CARENS, 1.7 D DCT 5DR FWD (A)	Chassis No:	KNAHU815VJ7211003
Reg. Date:	07/11/2018 (Man. Year: 2018)	Odometer:	117851 km
Colour:	Black		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,971.00	7,424.60	5,546.40	42.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,260.00	3,060.00	1,200.00	28.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,231.00	10,484.60	6,746.40	39.15
Approved Total (Overridden) (S\$)		8,400.00		
(S\$)	17,231.00	8,400.00	8,831.00	51.25
+ GST 7.00/7.00% (S\$)	1,206.17	588.00	618.17	51.25
Nett Amount (S\$)	18,437.17	8,988.00	9,449.17	51.25
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		8,990.00		

INSPECTION

Date of Assignment:	03/02/2020		
Date Inspected:	03/02/2020	Inspected At:	Tan Lim Motor Pte Ltd (Defu) 1 Defu Lane 6 Singapore 539365
Estimated Period of Repair:	9.0 days		

Adjuster: LEE HOCK ANN**Manager:** Khanchna Pothuraj*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Bent	549.00 F	*549.00 FL
2	8	*REAR BUMPER CLIP	Necessary	28.00 F	*20.00 FL
3	1	*REAR BUMPER CENTRAL PAD	Cracked	189.00 F	*168.00 FL
4	1	*REAR BUMPER LOWER DIFFUSION	Cracked	189.00 F	*189.00 FL
5	1	*REAR BUMPER TOW COVER (NPA)	Serviceable	0.00 F	*- FL
6	2	*REAR BUMPER REFLECTOR	Cracked	232.00 F	*232.00 FL
7	4	*REAR BUMPER REVERSE SENSOR	Shorted 3pcs Only	648.00 F	*486.00 FL
8	1	*SET REAR BUMPER REVERSE SENSOR HOLDER	Necessary	5.00 F	*5.00 FL
9	1	*REAR BUMPER BEAM	Cracked	367.00 F	*367.00 FL
10	1	*REAR BUMPER BEAM BRACKET	Crushed	159.00 F	*159.00 FL
11	2	*REAR BUMPER SIDE RETAINER	Necessary	56.00 F	*50.00 FL
12	1	*REAR BUMPER KEYLESS ANTENNA	Serviceable	79.00 F	*- FL
13	2	*REAR BUMPER SPLASH GUIDE (NPA)	Serviceable	0.00 F	*- FL
14	1	*TAILLAMP	N/s Cracked / O/s Serviceable	1,540.00 F	*357.00 FL
15	1	*TAILLAMP CLIP 6pcs	Necessary	36.00 F	*20.00 FL
16	1	*TAILGATE	Cut	1,088.00 F	*1,088.00 FL
17	1	*TAILGATE INNER INNER TRIMBOARD	Crushed	203.00 F	*203.00 FL
18	2	*TAILGATE LAMP LH/RH	Cracked	1,546.00 F	*1,200.00 FL
19	1	*TAILGATE TOP GARNISH (NPA)	Serviceable	0.00 F	*- FL
20	1	*TAILGATE TOP GARNISH OUTER CHROME (NPA)	Serviceable	0.00 F	*- FL
21	1	*TAILGATE INNER TRIMBOARD CLIP	Necessary	20.00 F	*20.00 FL
22	1	*TAILGATE CARENS EMBLEM	Necessary	28.00 F	*28.00 FL
23	1	*TAILGATE C&C EMBLEM	Necessary	31.00 F	*29.00 FL
24	1	*TAILGATE CRDI EMBLEM	Necessary	29.00 F	*29.00 FL
25	1	*TAILGATE KIA LOGO	Necessary	35.00 F	*35.00 FL
26	2	*REAR NUMBER PLATE LAMP	Serviceable	222.00 F	*- FL
27	1	*REAR KEYLESS SWITCH	Serviceable	115.00 F	*- FL
28	1	*TAILGATE LOCK	Jammed	112.00 F	*109.00 FL
29	1	*TAILGATE LOCK ACTUATOR (NPA)	Serviceable	0.00 F	*- FL
30	1	*TAILGATE WIPER MOTOR	Serviceable	401.00 F	*- FL
31	1	*REAR END PANEL	Cut	611.00 F	*453.00 FL
32	1	*REAR END PANEL TOP GARNISH	Crushed	123.00 F	*71.00 FL
33	1	*REAR END PANEL WEATHERSTRIP	Crushed	132.00 F	*131.00 FL
34	1	*REAR FENDER INNER TRIMBOARD R/H	Crushed	474.00 F	*360.00 FL
35	1	*REAR LUGGAGE FLOOR PANEL	Repair	515.00 F	*- FL
36	1	*REAR LUGGAGE FLOOR PANEL TRIMBOARD	Cracked	306.00 F	*306.00 FL
37	1	*REAR SPARE TYRE HOLDER	Bent	221.00 F	*221.00 FL
38	1	*REAR SPARE TYRE HOLDER RELEASER (NPA)	Serviceable	0.00 F	*- FL
39	1	*TOOLS HOLDER - FOAM	Cracked	210.00 F	*150.00 FL
40	1	*TOOLS COMPARTMENT - PLASTIC (NPA)	Serviceable	0.00 F	*- FL
41	1	*TAILGATE INNER TRIM SIDE COVER (NPA)	Serviceable	0.00 F	*- FL
42	1	*TAILGATE OPENER (NPA)	Serviceable	0.00 F	*- FL
43	1	*TAILGATE OPENER COVER	Crushed	79.00 F	*79.00 FL
44	1	*TAILGATE INNER TRIMBOARD - TOP (NPA)	Serviceable	0.00 F	*- FL
45	2	*TAILGATE INNER TRMBOARD - SIDE	Serviceable	0.00 F	*- FL
46	2	*TAILGATE DAMPER (NPA)	Serviceable	0.00 F	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	2		*TAILGATE HINGE (NPA)	Serviceable	0.00 F	*- FL
48	1		*FRONT BUMPER	Cracked	668.00 F	*668.00 FL
49	8		*FRONT BUMPER CLIP	Necessary	40.00 F	*20.00 FL
50	1		*FRONT BUMPER LOWER GRILLE	Cracked	159.00 F	*159.00 FL
51	1		*FRONT BUMPER LOWER DIFFUSION	Cracked	133.00 F	*133.00 FL
52	1		*FRONT BUMPER FOG LAMP (CRACKED)	Not Consistent With The Impact	206.00 F	*- FL
53	1		*FRONT BUMPER FOG LAMP GARNISH	Serviceable	119.00 F	*- FL
54	1		*FRONT GRILLE	Serviceable	428.00 F	*- FL
55	1		*REAR NUMBER PLATE	Scratched	50.00 FS	*35.00 FS
56	1		*FRONT NUMBER PLATE	Scratched	50.00 FS	*35.00 FS
57	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
58	1		*FRONT WINDSCREEN PRIMER	No such part	60.00 FS	*- FS
59	1		*REAR WINDSCREEN INNER SEAL	Necessary	80.00 FS	*30.00 FS
60	1		*SPARE TYRE	Serviceable	350.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	12,971.00	8,234.00
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	809.40
Total Parts (\$)	12,971.00	7,424.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION. (FRONT AND REAR)	New	1,400.00	1,200.00
2	TO RERUN WIRE HARNESS AND CHECK ELECTRICAL LIGHTING CONCERNED. (FRONT AND REAR)	New	80.00	60.00
3	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.	New	120.00	120.00
4	TO TRANSFER OF TAILGATE FITTINGS AND PERFORM WATER SEEPAGE TEST.	New	80.00	40.00
5	TO RUST-PROOFING OF THE AFFECTED AREAS.	New	120.00	50.00
6	TO PERFORM WATER SEEPAGE TEST, WINDNOISE AND TEST-DRIVE.	New	80.00	0.00
7	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH AND OTHER, TO ENABLE REPAIR.	New	100.00	60.00
8	TO REINSTALL OF REAR BUMPER PARKING SENSOR.	New	80.00	30.00
9	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. (FRONT AND REAR)	New	2,200.00	1,500.00
Gross Labour Cost (\$\$)			4,260.00	3,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >