

Re: SMF 3619K FINALIZED CLOSE CASE

Hock Ann (LKK Auto) <HockAnn@lkkauto.com>

Thu 4/9/2020 4:50 PM

To: Wei Shong <wei.shong@tlmotor.com.sg>

Cc: Khanchna (LKK Auto) <khanchna@lkkauto.com>; Admin A <admin-a@lkkauto.com>; caymen@tlmotor.com.sg <caymen@tlmotor.com.sg>

Dear wei shong,

Good day, o.k will be process base on finalized total amount COR \$ 8400 L/SUMP REPAIR and DOR 9 days close.

Noted : All finalized document > LOA ,LOD,DV,LTA need direct send to lkk in charge person (khanchna@lkkauto.com)

Thanks.

Best Regards,

Hock Ann | Assistant Automotive Assessor**LKK Auto Consultants**

Phone: 6741 3061 | Email: HockAnn@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Wei Shong <wei.shong@tlmotor.com.sg>
Sent: Thursday, April 9, 2020 2:14 PM
To: Hock Ann (LKK Auto) <HockAnn@lkkauto.com>
Cc: Khanchna (LKK Auto) <khanchna@lkkauto.com>; Admin A <admin-a@lkkauto.com>; caymen@tlmotor.com.sg <caymen@tlmotor.com.sg>
Subject: RE: SMF 3619K FINALIZED

Dear Hock Ann,

I have discuss with my boss and he confirmed and accepted your amount.

Thank you.

Regards,



Lam Wei Shong
William
wei.shong@tlmotor.com.sg

O. +65 6858 5151
F. +65 6858 0877

Tan Lim Motor Pte Ltd
1 Defu Lane 6
Singapore 539365
<http://www.tlmotor.com.sg>

Confidentiality Notice: This email (including any attachments) is intended for the recipient(s) named above and may contain information that is confidential to Tan Lim Motor Pte Ltd. Any use of the information (including, but not limited to, total or partial reproduction, distribution or dissemination in any form) by persons other than the intended recipient(s) is prohibited. If you are not an intended recipient of this email, please notify the sender immediately and delete it. While Tan Lim Motor has put in place anti-virus programs, we do not accept responsibility for any damage caused by viruses passed on unwittingly.

From: Hock Ann (LKK Auto) {mailto:HockAnn@lkkauto.com}
Sent: Monday, April 6, 2020 2:52 PM
To: Wei Shong <wei.shong@tlmotor.com.sg>

AIGAsia Insured's Veh No : SKB8298P
 Date of Accident : 31 January 2020


TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
 Tel : 68585151 (24 Hours) Fax : 68580877
 GST Regn. No. : M2-8922054-2

Messrs BIS Motoring Pte Ltd

Date : 03 February 2020

Estimate To Repair SMF3619K - KIA CARENS 1.7 DCT DIESEL 5DR FWD
 Chassis No : KNAHU815VJ7211003

| S/No | Quantity | Description | Amount | |
|------|----------------------------------|---|------------------------|--------|
| | | LIST ITEMS | | |
| 01 | 1 pc | rear bumper ✓ BT | \$ 549.00 | ✓ |
| 02 | 8 ps | rear bumper clip @ \$3.50 ✓ ALL | \$ 28.00 | 20 ✓ |
| 03 | 1 pc | rear bumper central pad ✓ CRA | \$ 189.00 | 168 ✓ |
| * 04 | 1 pc | rear bumper lower diffusion ✓ CRA | \$ 285 0.00 | 189 ✓ |
| 05 | 1 pc | rear bumper tow cover X (SVC) | \$ 0.00 | |
| 06 | 2 ps | rear bumper reflector @ \$116.00 ✓ LH (CRA) ✓ RH (CRA) | \$ 232.00 | ✓ |
| 07 | 4 ps ^{3 ps} | rear bumper reverse sensor @ \$162.00 ✓ sensor | \$ 648.00 | 486 ✓ |
| 08 | 1 pc ^{1 set} | rear bumper reverse sensor holder ✓ ALL | \$ 5.00 | ✓ |
| 09 | 1 pc | rear bumper beam ✓ CRA | \$ 367.00 | ✓ |
| 10 | 1 pc | rear bumper beam bracket ✓ CRA | \$ 159.00 | ✓ |
| 11 | 2 ps | rear bumper side retainer @ \$28.00 ✓ ALL | \$ 56.00 | 50 ✓ |
| 12 | 1 pc | rear bumper keyless antenna X (SVC) | \$ 79.00 | |
| 13 | 2 ps | rear bumper splash guide @ \$.00 X (SVC) | \$ 0.00 | |
| 14 | 2 ps ¹ | taillamp @ \$750.00 ✓ CRA LH only RH (SVC) X | \$ 1540.00 | 357 ✓ |
| 15 | 6 ps | taillamp clip @ \$6.00 ✓ ALL | \$ 36.00 | |
| 16 | 1 pc | tailgate ✓ cut | \$ 1,088.00 | ✓ |
| 17 | 1 pc | tailgate inner trimboard ✓ CRA | \$ 203 0.00 | ✓ |
| 18 | 2 ps | tailgate reflector @ \$773.00 ✓ CRA LH / RH | \$ 1546.00 | 1200 ✓ |
| 19 | 1 pc | tailgate top garnish X (SVC) | \$ 0.00 | |
| 20 | 1 pc | tailgate top garnish outer chrome X (SVC) | \$ 0.00 | |
| * 21 | 6 ps | tailgate inner trimboard clip @ \$.00 ✓ ALL | \$ 0.00 | 20 ✓ |
| 22 | 1 pc | tailgate "Carens" emblem ✓ ALL | \$ 28.00 | ✓ |
| 23 | 1 pc | tailgate C&C emblem ✓ ALL | \$ 31.00 | 29 ✓ |
| 24 | 1 pc | tailgate "CRDI" emblem ✓ ALL | \$ 29.00 | ✓ |
| 25 | 1 pc | tailgate KIA logo ✓ ALL | \$ 35.00 | ✓ |
| 26 | 2 ps | rear number plate lamp @ \$111.00 X (SVC) | \$ 222.00 | |
| 27 | 1 pc | rear keyless switch X (SVC) | \$ 115.00 | |
| 28 | 1 pc | tailgate lock ✓ Jm | \$ 112.00 | 109 ✓ |
| 29 | 1 pc | tailgate lock actuator X (SVC) | \$ 0.00 | |
| 30 | 1 pc | tailgate wiper motor X (SVC) | \$ 401.00 | |
| 31 | 1 pc | rear end panel ✓ cut | \$ 611.00 | 453 ✓ |
| 32 | 1 pc | rear end panel top garnish ✓ CRA | \$ 123.00 | 71 ✓ |
| * 33 | 1 pc | rear end panel weatherstrip ✓ CRA | \$ 132 0.00 | 131 ✓ |
| * 34 | 1 pc | rear fender inner trimboard ✓ RH CRA | \$ 474 0.00 | 360 ✓ |
| 35 | 1 pc | rear luggage floor panel X (R) | \$ 515.00 | |
| * 36 | 1 pc | rear luggage floor panel trimboard ✓ CRA | \$ 306.00 | ✓ |
| * 37 | 1 pc | rear spare tyre holder ✓ BT | \$ 221.00 | ✓ |
| 38 | 1 pc | rear spare tyre holder releaser X (SVC) | \$ 0.00 | |
| * 39 | 1 pc | tools holder - foam ✓ CRA | \$ 210 0.00 | 170 ✓ |



TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SKB8298P
Date of Accident : 31 January 2020

Messrs BIS Motoring Pte Ltd

Date : 03 February 2020

Estimate To Repair SMF3619K - KIA CARENS 1.7 DCT DIESEL 5DR FWD
Chassis No : KNAHU815VJ7211003

| S/No | Quantity | Description | Amount |
|-----------------------------------|---------------------|--|----------------------|
| <u>LIST ITEMS</u> | | | |
| 40 | 1 pc | tools compartment - plastic X (SVC) | \$ / 0.00 |
| 41 | 1 pc | tailgate inner trim side cover X (SVC) | \$ / 0.00 |
| 42 | 1 pc | tailgate opener X (SVC) | \$ / 0.00 |
| * 43 | 1 pc | tailgate opener cover ✓ CRA | \$ 79 0.00 ✓ |
| 44 | 1 pc | tailgate inner trimboard - top X (SVC) | \$ / 0.00 |
| 45 | 2 ps | tailgate inner trimboard - side @ \$.00 X (SVC) | \$ / 0.00 |
| 46 | 2 ps | tailgate damper @ \$.00 X (SVC) | \$ / 0.00 |
| 47 | 2 ps | tailgate hinge @ \$.00 X (SVC) | \$ / 0.00 |
| 48 | 1 pc | front bumper ✓ CRA | \$ 668.00 ✓ |
| * 49 | 1 pc 8ps | front bumper clip ✓ new | \$ / 40 5.00 20 ✓ |
| 50 | 1 pc | front bumper lower grille ✓ CRA | \$ 159.00 ✓ |
| * 51 | 1 pc | front bumper lower diffusion ✓ CRA | \$ 133 0.00 ✓ |
| 52 | 1 pc | front bumper fog lamp X (N/C) | \$ / 206.00 |
| 53 | 1 pc | front bumper fog lamp garnish X (SVC) | \$ / 119.00 |
| 54 | 1 pc | front grille X (SVC) | \$ / 428.00 |
| | | | \$ 10,329.00 |
| <u>SPECIAL NETT ITEMS</u> | | | |
| 55 | 1 pc | rear number plate ✓ SCR | \$ / 50.00 35 ✓ |
| 56 | 1 pc | front number plate ✓ SCR | \$ / 50.00 35 ✓ |
| 57 | 1 tube | front windscreen sealant ✓ new | \$ / 50.00 40 ✓ |
| 58 | 1 pc | front windscreen primer X (N/S) | \$ / 60.00 |
| 59 | 1 pc | front windscreen inner seal ✓ new | \$ / 80.00 30 ✓ |
| 60 | 1 pc | spare tyre X (SVC) | \$ / 350.00 |
| | | | \$ 640.00 |
| <u>LABOUR & MISC. CHARGES</u> | | | |
| 01 | | Putty and spray painting of the affected portion. → Put and Run | \$ / 1,400.00 1200 ✓ |
| 02 | | To rerun wire harness and check electrical lighting concerned. ✓ (Put and Run) | \$ / 80.00 60 ✓ |
| 03 | | To remove and refit rear windscreen glass. | \$ / 120.00 ✓ |
| 04 | | To transfer of tailgate fittings and perform water seepage test. | \$ / 80.00 40 ✓ |
| 05 | | To rust-proofing of the affected areas. | \$ / 120.00 50 ✓ |
| 06 | | To perform water seepage test, windnoise and test-drive. X | \$ / 80.00 |
| 07 | | To remove and refit interior fittings, trimmings, garnish and other, to enable repair. | \$ / 100.00 60 ✓ |
| 08 | | To reinstall of rear bumper parking sensor. | \$ / 80.00 30 ✓ |



TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SKB8298P
Date of Accident : 31 January 2020

Messrs BIS Motoring Pte Ltd

Date : 03 February 2020

Estimate To Repair SMF3619K - KIA CARENS 1.7 DCT DIESEL 5DR FWD
Chassis No : KNAHU815VJ7211003

| S/No | Quantity | Description | Amount |
|------|----------|---|--------------|
| 09 | | LABOUR & MISC. CHARGES | |
| | | Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same. | \$ 2,200.00 |
| | | <i>(Part and car)</i> | \$ 4,260.00 |
| | | Total | \$ 15,229.00 |

1500 ✓

*Resurvey done
12.25pm
4/2/20
Hock Ann
1/klh
8531887*

*1/5 repair
with patch
resurvey after part
9 day
Hock Ann
1/klh
3.15pm*

*Hock Ann / 3/2/20
Hock Ann@klhAuto.com*

parts 8094

parts less 100/0

7284.60

spc nett 140

1960

10484.60

1/5 less 200/0

8387.68

*total
1/5 Amt → \$ 8400#*

Our Consultants hence notify the insurer of the following:

- Resurvey before/after spray painting
- Display damaged part(s) during resurvey
- Prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Legal modification(s) is allowed
- Complementary item(s) must be resurveyed and subject to final approval from Insurance Company

Knownledged by Repairer
Signature:
Date: