



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SKB8298P
Date of Accident : 31 January 2020

Messrs BIS Motoring Pte Ltd

Date : 03 February 2020

Estimate To Repair SMF3619K - KIA CARENS 1.7 DCT DIESEL 5DR FWD

Chassis No : KNAHU815VJ7211003

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	rear bumper ✓ B+	\$ 549.00
02	8 ps	rear bumper clip @ \$3.50 ✓ mee	\$ 28.00
03	1 pc	rear bumper central pad ✓ CRA	\$ 189.00
04	1 pc	rear bumper lower diffusion ✓ CRA	\$ 0.00
05	1 pc	rear bumper tow cover X (svc)	\$ 0.00
06	2 ps	rear bumper reflector @ \$116.00 ✓ HH(CRA) ✓ RH (CRA)	\$ 232.00
07	4 ps ^{3 ps}	rear bumper reverse sensor @ \$162.00 ✓ short	\$ 648.00
08	1 pc ^{4 ps}	rear bumper reverse sensor holder ✓ mee	\$ 5.00
09	1 pc	rear bumper beam ✓ - CRA	\$ 367.00
10	1 pc	rear bumper beam bracket ✓ CRA	\$ 159.00
11	2 ps	rear bumper side retainer @ \$28.00 ✓ mee	\$ 56.00
12	1 pc	rear bumper keyless antenna X (svc)	\$ 79.00
13	2 ps	rear bumper splash guide @ \$.00 X (svc)	\$ 0.00
14	2 ps 1	taillamp @ \$770.00 ✓ CRA HH only RH (svc) X	\$ 1,540.00
15	6 ps	taillamp clip @ \$6.00 ✓ mee	\$ 36.00
16	1 pc	tailgate ✓ cut	\$ 1,088.00
17	1 pc	tailgate inner trimboard ✓ CRA	\$ 0.00
18	2 ps	tailgate reflector @ \$773.00 ✓ CRA HH / RH	\$ 1,546.00
19	1 pc	tailgate top garnish X (svc)	\$ 0.00
20	1 pc	tailgate top garnish outer chrome X (svc)	\$ 0.00
21	6 ps	tailgate inner trimboard clip @ \$.00 ✓ mee	\$ 0.00
22	1 pc	tailgate "Carens" emblem ✓	\$ 28.00
23	1 pc	tailgate C&C emblem ✓	\$ 31.00
24	1 pc	tailgate "CRDI" emblem ✓	\$ 29.00
25	1 pc	tailgate KIA logo ✓	\$ 35.00
26	2 ps	rear number plate lamp @ \$111.00 X	\$ 222.00
27	1 pc	rear keyless switch X	\$ 115.00
28	1 pc	tailgate lock ✓ ✓	\$ 112.00
29	1 pc	tailgate lock actuator X	\$ 0.00
30	1 pc	tailgate wiper motor X	\$ 401.00
31	1 pc	rear end panel ✓ cut	\$ 611.00
32	1 pc	rear end panel top garnish ✓ CRA	\$ 123.00
33	1 pc	rear end panel weatherstrip ✓ CRA	\$ 0.00
34	1 pc	rear fender inner trimboard ?	\$ 0.00
35	1 pc	rear luggage floor panel X (R)	\$ 515.00
36	1 pc	rear luggage floor panel trimboard X (svc)	\$ 0.00
37	1 pc	rear spare tyre holder ?	\$ 0.00
38	1 pc	rear spare tyre holder releaser X (svc)	\$ 0.00
39	1 pc	tools holder - foam ✓ CRA	\$ 0.00



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SKB8298P
Date of Accident : 31 January 2020

Messrs BIS Motoring Pte Ltd

Date : 03 February 2020

Estimate To Repair SMF3619K - KIA CARENS 1.7 DCT DIESEL 5DR FWD

Chassis No : KNAHU815VJ7211003

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
40	1 pc	tools compartment - plastic X (svc)	\$ 0.00
41	1 pc	tailgate inner trim side cover X (svc)	\$ 0.00
42	1 pc	tailgate opener X (svc)	\$ 0.00
43	1 pc	tailgate opener cover ✓ CRM	\$ 0.00
44	1 pc	tailgate inner trimboard - top X (svc)	\$ 0.00
45	2 ps	tailgate inner trimboard - side @ \$.00 X (svc)	\$ 0.00
46	2 ps	tailgate damper @ \$.00 X (svc)	\$ 0.00
47	2 ps	tailgate hinge @ \$.00 X (svc)	\$ 0.00
48	1 pc	front bumper ?	\$ 668.00
49	1 pc	front bumper clip ✓ RM	\$ 5.00
50	1 pc	front bumper lower grille ✓ LRA	\$ 159.00
51	1 pc	front bumper lower diffusion ✓ LRA	\$ 0.00
52	1 pc	front bumper fog lamp 44 ?	\$ 206.00
53	1 pc	front bumper fog lamp garnish X (svc)	\$ 119.00
54	1 pc	front grille ?	\$ 428.00
			\$ 10,329.00
<u>SPECIAL NETT ITEMS</u>			
55	1 pc	rear number plate ✓ SCR	\$ 50.00
56	1 pc	front number plate ✓ SCR	\$ 50.00
57	1 tube	front windscreen sealant ✓ RM	\$ 50.00 40
58	1 pc	front windscreen primer X (not used)	\$ 60.00
59	1 pc	front windscreen inner seal ✓ RM	\$ 80.00 30
60	1 pc	spare tyre X (svc)	\$ 350.00
			\$ 640.00
<u>LABOUR & MISC. CHARGES</u>			
01		Putty and spray painting of the affected portion. (Fit and Rev)	\$ 1,400.00 1200 ✓
02		To rerun wire harness and check electrical lighting concerned. (Fit and Rev)	\$ 80.00 50 ✓
03		To remove and refit rear windscreen glass. → out Rev	\$ 120.00 ✓
04		To transfer of tailgate fittings and perform water seepage test.	\$ 80.00 40 ✓
05		To rust-proofing of the affected areas.	\$ 120.00 50 ✓
06		To perform water seepage test, windnoise and test-drive. X	\$ 80.00
07		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 100.00 60 ✓
08		To reinstall of rear bumper parking sensor.	\$ 80.00 30 ✓



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SKB8298P
Date of Accident : 31 January 2020

Messrs BIS Motoring Pte Ltd

Date : 03 February 2020

Estimate To Repair SMF3619K - KIA CARENS 1.7 DCT DIESEL 5DR FWD

Chassis No : KNAHU815VJ7211003

S/No	Quantity	Description	Amount
09		<u>LABOUR & MISC. CHARGES</u> Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same. <i>(Frt and Rr)</i>	\$ 2,200.00
			\$ 4,260.00
		Total	\$ 15,229.00

1500 ✓

*2/5 repair
with preparation
Resurge after part
9 day
Hook ANW
HKL
3.15pm / 3/2/20
Hook ANW @ HKL Auto.com*

Auto Consultants hence notify
Repairer of the following:
 - Resurvey before/after spray painting
 - Display damaged part(s) during resurvey
 - All prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - Illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and
 subject to final approval from Insurance Company
 Acknowledged by Repairer
 Signature:
 Date: