



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLW 4386 Y

Not Authorized

Parts	(a) Cost / List Price Items	_____
	Plus/Less	_____
	Total of Cost / List	=====
	(b) Nett Price Items	_____
	Less	_____
	Total of Nett Item	=====
	(c) Special Nett Items	_____
Total Parts Cost		=====
Labour	\$	1,370.00
Total	\$	1,370.00

The above total will be subjected to 7% G.S.T.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Name of Surveyor	:	<u>Kenneth</u>
Company	:	<u>LKK</u>
Survey conducted on	:	<u>4/2/20</u> at <u>10.30am</u>
Remarks By Surveyor		
(a)	The repair of this vehicle is <u>not</u> authorized / is not authorized until further notice.	
(b)	Recommended Days of Repair	: <u>02</u> day(s)
(c)	Resurvey	: Required / <u>Not</u> Required
(d)	Excess	: \$ _____
(e)	Signature of surveyor	: <u>Sc</u> Date: <u>4/2/2020</u>

