

CT AUTO PTE LTD

160 Sin Ming Drive, #02-14, Sin Ming AutoCity, Singapore 575722

Tel: 62666727 Fax: 62666358 Email: admin@ctauto.com.sg

Business Registration No. 201420132H

GST Registration No. 201420132H

Not Autharw

Recovery By paint

4 days

ESTIMATE

Date:

4/2/2020

DOA:

3/2/2020

Vehicle No: GBK979U

Make & Model: Toyota Hiace 3.0

S/N	Qty	Item Description	Parts Price	Surveyor
1	1	Bonnet	\$ 903.70	✓
2	1	Bonnet Lock Mechanism	\$ 81.50	X
3	1	Bonnet Lock Brase Panel	\$ 110.40	✓
4	1	Bonnet Centre Logo	\$ 150.00	✓
5	1	Front Grille	\$ 1,944.30	?
6	2	Front Grille WeatherStrip	\$ 342.20	X
7	1	Front Support Panel	\$ 819.80	X
8	1	Front Support Panel Top Garnish	\$ 132.80	X
9	1	Front R/H Head Lamp LED	\$ 2,484.20	✓
10	1	Front R/H Corner Panel	\$ 294.40	X
11	1	Front Wiper Tank	\$ 52.20	X
12	1	Brake Booster	\$ 649.60	X
13	1	Brake Booster Pump	\$ 489.10	X
14	1	Brake Booster Oil Tank	\$ 151.00	X
15	1	Brake Booster Pipe	\$ 225.90	X
16	1	Brake Booster Vacuum Pipe	\$ 117.90	X
17	1	Front Air-Con Condensor	\$ 1,095.70	X
18	1	Front Air Con Blower	\$ 865.80	X
19	2	Front Radiator	\$ 2,654.40	X
20	1	Front Radiator Fan With Motor	\$ 648.60	X
21	1	Front Radiator Fan Cowling	\$ 130.70	X
22	2	Front Radiator Mountings	\$ 115.80	X
23	1	Front Radiator Tank	\$ 303.60	X
24	2	Front Horn	\$ 257.10	X
25	1	Air Cleaner Box Assy	\$ 582.10	X
26	1	Front Inter Cooler	\$ 1,285.10	X
27	1	Front Inter Cooler Housing Garnish	\$ 301.20	X
28	1	Front Inter Cooler Housing Garnish WeatherStrip	\$ 126.50	X
29	2	Front Intercooler Discharge Pipe	\$ 265.60	X
30	2	Front Intercooler Suction Pipe	\$ 556.70	X
31	1	Front Bumper Inner L/H Radiator	\$ 670.60	?
32	1	Front Bumper	\$ 649.60	✓
33	2	Front Bumper Side Retainer	\$ 239.90	✓
34	1	Front Bumper Lower Grille	\$ 264.90	✓
35	2	Front Bumper Reinforcement	\$ 1,239.30	?
36	2	Front Bumper Reinforcement Bracket	\$ 148.20	
			\$ 21,350.40	
		Less 25%	\$ 5,337.60	
			\$ 16,012.80	
		Special Nett Items		
1		Sundries	\$ 50.00	X
2	1 set	Front Grille Clips	\$ 80.00	?
3	1	Front Bonnet Sticker	\$ 250.00	?
4	1	Front Support Panel Sealant	\$ 120.00	X
5	1 set	Front Support Panel Top Garnish Clips	\$ 80.00	X
6	2 set	Front Head Lamp Clips	\$ 80.00	✓

7	2	Front Head Lamp Sealant	nn	\$ 120.00	X
8	1	Brake Booster Fluid	nn	\$ 180.00	X
9	2	Front Radiator Coolant	nn	\$ 160.00	X
10	1 set	Front Inter Cooler Housing Garnish Clips	nn	\$ 50.00	X
11	1 set	Front Bumper Clips	nn	\$ 50.00	✓
12	1 set	Front Bumper Lower Grille Clips		\$ 50.00	✓
13	1 set	Front No. Plate	nn	\$ 80.00	X
				\$ 1,350.00	
		Total parts		\$ 17,362.80	
S/N	Labour Description		Amount		Amount
1	Labour for panel beating, cut, weld, straighten and replace front damaged parts.		\$ 1,800.00		4501
2	To putty and spray painting front portion.		\$ 1,600.00		5001
3	To remove and install air con system to facilitate the repair and refill gas.		\$nn 120.00		X
4	To remove and install cooling system to facilitate the repair and check for leakage.		\$nn 120.00		X
5	To remove and install intercooler to facilitate the repair.		\$nn 120.00		X
6	To remove and install front dashboard to facilitate the repair.		nn \$ 350.00		X
7	To remove and install front windscreen to facilitate the repair.		nn \$ 250.00		X
8	To perform 4 wheel alignment and balancing.		nn \$ 150.00		X
9	To check wiring and focus front head lamp.		\$ 80.00		201
10	To remove and install front bonnet lock mechanism.		nn \$ 120.00		X
11	To apply anti rust proofing to front affected area.		\$ 250.00		301
	Total labour :		\$ 4,960.00		
	Total parts :		\$ 17,362.80		
	Total labour :		\$ 4,960.00		
	Total repair cost (Before GST) :		\$ 22,322.80		

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: