

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 30-Jan-20

MODEL: HYUNDAI I40

VEHICLE NO.: SHD6814M

INSURANCE: FWD

DESCRIPTION	QTY	LIST PRICE	AMOUNT
REAR BUMPER <i>NH</i>	1 <input checked="" type="checkbox"/>	\$1,106.00	\$1,106.00
REAR BUMPER CLIP <i>NH</i>	1 <input checked="" type="checkbox"/>	\$19.00	\$19.00
REAR DOOR (LH/RH) <i>right Door</i>	1 <input checked="" type="checkbox"/>	\$2,201.10	\$2,201.10
REAR TYRE RIM (LH/RH) <i>2 set</i>	1 <input checked="" type="checkbox"/>	\$650.60	\$650.60
REAR TYRE WHEEL CAP <i>ols NH</i>	1 <input checked="" type="checkbox"/>	\$214.20	\$214.20
REAR TRAILING ARM (LH/RH) <i>disturb</i>	1 <input checked="" type="checkbox"/>	\$384.00	\$384.00
REAR ASSIST (LH/RH) <i>disturb</i>	1 <input checked="" type="checkbox"/>	\$219.40	\$219.40
REAR UPPER ARM (LH/RH) <i>disturb</i>	1 <input checked="" type="checkbox"/>	\$335.75	\$335.75
REAR LOWER ARM (LH/RH) <i>disturb</i>	1 <input checked="" type="checkbox"/>	\$353.80	\$353.80
REAR KNUCKLE ARM (LH/RH) <i>disturb</i>	1 <input checked="" type="checkbox"/>	\$545.60	\$545.60
FRONT BUMPER COVER <i>cut (PDA) many crack</i>	1 <input checked="" type="checkbox"/>	\$1,052.20	\$1,052.20
FRONT BUMPER BRACKET TOP (LH/RH) <i>NH</i>	1 <input checked="" type="checkbox"/>	\$44.80	\$44.80
FRONT BUMPER BRACKET (LH/RH) <i>NH</i>	1 <input checked="" type="checkbox"/>	\$49.20	\$49.20
FRONT BUMPER SIDE BRACKET <i>NH</i>	1 <input checked="" type="checkbox"/>	\$4.60	\$4.60
FRONT BUMPER RETAINER MOUNTING <i>NH</i>	1 <input checked="" type="checkbox"/>	\$8.00	\$8.00
FRONT BUMPER GRILLE AIR DUCT <i>NH</i>	1 <input checked="" type="checkbox"/>	\$26.20	\$26.20
HEADLAMP (LH/RH) <i>NH</i>	1 <input checked="" type="checkbox"/>	\$2,776.00	\$2,776.00
FRONT FENDER (LH/RH) <i>vt</i>	1 <input checked="" type="checkbox"/>	\$566.30	\$566.30
FRONT FENDER APRON PANEL (LH/RH) <i>NH</i>	1 <input checked="" type="checkbox"/>	\$637.00	\$637.00
FRONT FENDER SHIELD (LH/RH) <i>NH</i>	1 <input checked="" type="checkbox"/>	\$174.90	\$174.90
FRONT FENDER MUDFLAP (LH/RH) <i>NH</i>	1 <input checked="" type="checkbox"/>	\$13.50	\$13.50
FRONT FENDER RETAINER <i>NH</i>	1 <input checked="" type="checkbox"/>	\$3.00	\$3.00
FRONT DOOR (LH/RH) <i>right vt</i>	1 <input checked="" type="checkbox"/>	\$2,256.40	\$2,256.40
FRONT DOOR HINGE UPPER (LH/RH) <i>NH</i>	1 <input checked="" type="checkbox"/>	\$44.50	\$44.50
FRONT DOOR HINGE LOWER (LH/RH) <i>NH</i>	1 <input checked="" type="checkbox"/>	\$44.50	\$44.50
FRONT DOOR CHECK (LH/RH) <i>NH</i>	1 <input checked="" type="checkbox"/>	\$91.80	\$91.80
FRONT DOOR INNER LOCK (LH/RH) <i>NH</i>	1 <input checked="" type="checkbox"/>	\$290.80	\$290.80
ROCKER PANEL OUTER GARNISH <i>cut ops</i>	1 <input checked="" type="checkbox"/>	\$403.00	\$403.00
FRONT WHEEL RIM (LH/RH) <i>vt o/s N/S disturb</i>	2 <input checked="" type="checkbox"/>	\$650.60	\$1,301.20
FRONT WHEEL HUB CAP (LH/RH) <i>cut</i>	2 <input checked="" type="checkbox"/>	\$214.20	\$428.40
FRONT WHEEL NUT <i>NH</i>	2 <input checked="" type="checkbox"/>	\$5.70	\$11.40
FRONT WHEEL BEARING <i>2 o/s Disturb</i>	2 <input checked="" type="checkbox"/>	\$301.80	\$603.60
FRONT WHEEL HUB ASSY <i>NH</i>	2 <input checked="" type="checkbox"/>	\$153.60	\$307.20

03/02/2020 e17 form
N/A Antenna 8 d
Lbanel ~~6~~ 8 days
Tyan LKK Auto

Date: