

Lpc:  
L/H: Khonchna

not Authorized  
L/H

Page No. 1

VEHICLE NO. GBG 860Z

NISSAN NV 200

1/5 & 7000

6 days.

| QTY                       | DESCRIPTION                                  | CONDITION    | REPAIRER'S ESTIMATE(\$\$) | SURVEYOR'S ADJUSTMENT |
|---------------------------|----------------------------------------------|--------------|---------------------------|-----------------------|
| <b>PARTS (NETT ITEMS)</b> |                                              |              |                           |                       |
| 1                         | Rear RH door 1053.70                         | body         | 1850.00                   |                       |
| 1                         | Rear RH door inner board                     | 11           | 245.00                    | X                     |
| 1                         | Rear LH door 1462.30                         | body         | 2150.00                   |                       |
| 1                         | Rear LH door inner board                     | 11           | 345.00                    | X                     |
| 1                         | Rear weatherstrip                            | 11           | 285.00                    |                       |
| 1                         | Rear LH door centre garnish 289.50           | 11           | 385.00                    |                       |
| 2                         | RH & LH Taillamp @598.50 285 x 2 = 570       | 11           | 1197.00                   |                       |
| 1                         | Rear bumper 652.00                           | 11           | 1240.00                   |                       |
| 1                         | Rear bumper sponge 145.00                    | 11           | 220.00                    |                       |
| 1                         | Rear end panel outer 485.00                  | 11           | 940.00                    |                       |
|                           |                                              |              | 8857.00                   |                       |
|                           |                                              | 102 less 30% | 2657.10                   | 30%                   |
|                           |                                              |              | 6199.90                   |                       |
| <b>PARTS NETT ITEMS</b>   |                                              |              |                           |                       |
| 1                         | Rear LH door centre badge                    | 11           | 78.20                     |                       |
| 1                         | Rear LH door NV200 emblem                    | 11           | 72.00                     |                       |
| 1                         | Rear LH door glass                           | 11           | 0.00                      | X                     |
| 1                         | Rear LH door wiper motor                     | 11           | 0.00                      | X                     |
| 2                         | Rear LH door inner lock @\$310 165 x 2 = 330 | 11           | 620.00                    |                       |
| 2                         | Rear LH door hinges @129.50                  | 11           | 259.00                    | X                     |
| 2                         | Rear LH door stopper guide                   | 11           | 98.00                     | X                     |
| 1                         | Rear RH door inner lock guide                | 11           | 298.00                    | X                     |
| 2                         | Rear RH door outer hinges @129.50            | 11           | 259.00                    | X                     |
| 1                         | Rear end panel top garnish 198.60            | 11           | 234.70                    |                       |
|                           |                                              |              | 1918.90                   |                       |
|                           |                                              | less 10%     | 191.89                    | 10%                   |
|                           |                                              |              | 1727.01                   |                       |
| <b>SPECIAL NETT ITEMS</b> |                                              |              |                           |                       |
| 1                         | Reverse sensor 1set                          | shocked      | 280.00                    | 200                   |
| 1                         | Rear view camera (fitted on LH rear door)    | shocked      | 480.00                    | 300                   |
| 1                         | Rear number plate w/holder                   | 11           | 75.00                     | X                     |
| 1set                      | Rear door inner board clips                  | 11           | 40.00                     | X                     |
| 1                         | Rear RH door company sticker**               | 11           | 450.00                    | 250                   |
| 1                         | Rear LH door company sticker**               | 11           | 300.00                    | 250                   |
| 1                         | Rear doors lower company advert sticker**    | 11           | 480.00                    | 300                   |
| 1                         | RH door 6pax sticker                         | 11           | 20.00                     | 10                    |
| 1                         | 70km/h sticker                               | 11           | 20.00                     | 10                    |
| 2                         | Rear door glass inner seal                   | 11           | 200.00                    | 80                    |
|                           | (** sticker with labour pricing)             |              |                           |                       |
| TOTAL PARTS               |                                              |              | 10271.91                  |                       |

561.3  
102  
5059.17

VEHICLE NO. GBG 860Z NISSAN NV 200

| S/N                     | DESCRIPTION                                                                                                                              | REPAIRER'S<br>ESTIMATE (S\$) | SURVEYOR'S<br>ADJUSTMENT |
|-------------------------|------------------------------------------------------------------------------------------------------------------------------------------|------------------------------|--------------------------|
|                         | <b>LABOUR</b>                                                                                                                            |                              |                          |
| 1                       | To remove the affected parts to commence repairs; panel beat & reshape the affected areas; and replace the damaged parts and components. | 1400.00                      | 1000                     |
| 2                       | To supply paint materials, expandable items & putty, respray paint on parts replaced                                                     | 1200.00                      | 800                      |
| 3                       | To remove and refix/replace inner fittings etc. so as to facilitate repairs at rear                                                      | 350.00                       | - 100                    |
| 4                       | To remove and refix rear door glass                                                                                                      | 140.00                       | - ✓                      |
| 5                       | To remove & replace reverse sensor and check for proper function                                                                         | 120.00                       | -                        |
| 6                       | To remove and replace rear camera and check for proper function                                                                          | 120.00                       | - 50                     |
| 7                       | To remove and refix wiring                                                                                                               | 120.00                       | - 30                     |
| 8                       | To perform anti rust treatment on affected areas                                                                                         | 180.00                       | - 100                    |
| Labour Total :          |                                                                                                                                          | 3630.00                      |                          |
| TOTAL (PARTS & LABOUR): |                                                                                                                                          | 13901.91                     |                          |

**NOTE: The parts listed in this PRELIMINARY ESTIMATE will be checked for damage after the vehicle is disassembled (dismantle). Additional damaged parts (if any) will be submitted as supplementary parts**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

P-5059.17  
S.N-1480.00  
L-2220.00  

---

8259.17  
296  

---

700733