

LPC K

not Authorized
N/A

Page No. 1

VEHICLE NO. GBG 860Z

NISSAN NV 200

1/5 & 7000

6 days.

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR'S ADJUSTMENT
PARTS (EST ITEMS)				
1	Rear RH door 1053.70	body	1850.00	
1	Rear RH door inner board	11	245.00	X
1	Rear LH door 1462.30	body	2150.00	
1	Rear LH door inner board	11	345.00	X
1	Rear weatherstrip	7w	285.00	
1	Rear LH door centre garnish 289.50	del torn	385.00	
2	RH & LH Taillamp @598.50 285x2=570	Cra	1197.00	
1	Rear bumper 652.00	DE	1240.00	
1	Rear bumper sponge 145.00	Torn	220.00	
1	Rear end panel outer 485.00	body	940.00	
			8857.00	
		102 less 30%	2657.10	30%
			6199.90	
PARTS NETT ITEMS				
1	Rear LH door centre badge	REFIX	78.20	
1	Rear LH door NV200 emblem	REFIX	72.00	
1	Rear LH door glass	11	0.00	X
1	Rear LH door wiper motor	11	0.00	X
2	Rear LH door inner lock @\$310 165x2=330	7w	620.00	
2	Rear LH door hinges @129.50	11	259.00	X
2	Rear LH door stopper guide	11	98.00	X
1	Rear RH door inner lock guide	11	298.00	X
2	Rear RH door outer hinges @129.50	11	259.00	X
1	Rear end panel top garnish 198.60	Torn	234.70	
			1918.90	
		less 10%	191.89	10%
			1727.01	
SPECIAL NETT ITEMS				
1	Reverse sensor 1set	shorted	280.00	200
1	Rear view camera (fitted on LH rear door)	shorted	480.00	380
1	Rear number plate w/holder	11	75.00	X
1set	Rear door inner board clips	11	40.00	X
1	Rear RH door company sticker**	rec	450.00	250
1	Rear LH door company sticker**	rec	300.00	250
1	Rear doors lower company advert sticker**	rec	480.00	300
1	RH door 6pax sticker	rec	20.00	10
1	70km/h sticker	rec	20.00	10
2	Rear door glass inner seal	rec	200.00	80
	(** sticker with labour pricing)			
TOTAL PARTS			10271.91	

561.3

102
5049.17

VEHICLE NO. GBG 860Z NISSAN NV 200

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
1	LABOUR To remove the affected parts to commence repairs; panel beat & reshape the affected areas; and replace the damaged parts and components.	1400.00	1000
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1200.00	800
3	To remove and refix/replace inner fittings etc. so as to facilitate repairs at rear	350.00	- 100
4	To remove and refix rear door glass	140.00	- ✓
5	To remove & replace reverse sensor and check for proper function	120.00	- 50
6	To remove and replace rear camera and check for proper function	120.00	
7	To remove and refix wiring	120.00	- 30
8	To perform anti rust treatment on affected areas	180.00	- 100
Labour Total :		3630.00	
TOTAL (PARTS & LABOUR):		13901.91	

NOTE: The parts listed in this PRELIMINARY ESTIMATE will be checked for damage after the vehicle is disassembled (dismantle). Additional damaged parts (if any) will be submitted as supplementary parts

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-5059.17
S.N-1480.00
L-2220.00
8259.17
296
70733