

KK

Lian Her Motors

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541
Tel : 64817221

Fax : 64816131

L H Car Rental Pte Ltd
Blk 5038 #01-405
Ang Mo Kio Industrial Pk 2
Singapore 569541

Not Authorized
1/1 Lny @ 1150p
Rummy After Rain
3 days

Vehicle No : SLN 7200 C
Make/Model : Honda Vezel 1.5 X A
Year : 2017

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Rear o/s tail-lamp assy	
1 pc	Rear bumper	photo
1 pc	Rear o/s side bumper	195.20
1 pc	Rear o/s bumper side retainer	
1 pc	Rear o/s bumper reflector	
1 pc	Rear o/s fender arch protector	✓ photo

SL	\$688.10	X
Mgim	\$825.60	?
Bv/nd	\$335.70	✓
Nil	\$45.80	✓
SL	\$110.50	X
R	\$175.20	X
	\$2,180.90	
Less 20 %	\$436.18	
	\$1,744.72	

S Nett

1 pc	Rear reverse sensor	photo
10 pcs	Rear bumper clip	

SL	\$200.00	X
M	\$20.00	?
	\$220.00	

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.

\$600.00 250

To putty and spray paint

\$700.00 300

Check & reconnect wiring.

\$30.00 100

To respray anti-rust proofing treatment

SL \$120.00 X
\$3,414.72

Total

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: