

Lian Her Motors

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541
Tel : 64817221

Fax : 64816131

L H Car Rental Pte Ltd
Blk 5038 #01-405
Ang Mo Kio Industrial Pk 2
Singapore 569541

Vehicle No : SLN 7200 C
Make/Model : Honda Vezel 1.5 X A
Year : 2017

Not Authorized
1/1/2018
Putty After Paint
3 days

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Rear o/s tail-lamp assy	
1 pc	Rear bumper	<i>photo</i>
1 pc	Rear o/s side bumper	
1 pc	Rear o/s bumper side retainer	
1 pc	Rear o/s bumper reflector	
1 pc	Rear o/s fender arch protector	<i>photo</i>

<i>SL</i>	\$688.10	<i>X</i>
	\$825.60	<i>?</i>
<i>Bul/Ad</i>	\$335.70	<i>✓</i>
<i>MT</i>	\$45.80	<i>✓</i>
<i>SL</i>	\$110.50	<i>X</i>
	\$175.20	<i>?</i>
	\$2,180.90	
Less 20 %	\$436.18	
	\$1,744.72	

S Nett

1 pc	Rear reverse sensor	<i>photo</i>
10 pcs	Rear bumper clip	

<i>SL</i>	\$200.00	<i>X</i>
\$2.00	\$20.00	<i>?</i>
	\$220.00	

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.

\$600.00 *250*

To putty and spray paint

\$700.00 *300*

Check & reconnect wiring.

\$30.00 *100*

To respray anti-rust proofing treatment

SL \$120.00 *X*
\$3,414.72

Total

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: