

Lion City Rentals Pte Ltd  
CARROS CENTER  
60 JALAN LAM HUAT #04-01 S(737869)  
Main +65 62524991

Ms: AIG Asia Pacific Insurance Pte Ltd

Date: 4/2/2020

Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO. SLM1174P

Chassis No: JM6BN22A8H0145738

MAKE / MODEL : Mazda 3 Sedan 1.5 AT

DATE OF ACCIDENT : 31/01/2020

YOUR INSURED VEHICLE NUMBER :SLZ6999A

MILEAGE : 240047 km

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PARTS DESCRIPTION

	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1 Rear bumper / DD	1PC	\$ 1,129.00	\$ 1,129.00
2 Rear bumper reinforcement ?	1PC	\$ 564.20	\$ 564.20
			\$ 1,693.20
	10% DISCOUNT S\$:	\$	169.32
			\$ 1,523.88
S/Nett			
1 Reverse sensor X sm			\$ 240.00
2 Rear bumper clips / Neg			\$ 100.00
	Total	\$	340.00

LABOUR CHARGES

To labour charge for removing rear bumper out to facilitate repairs and replacement of damaged parts			
1		\$	600.00 250
2	To respray rear bumper		
		\$	600.00 200
LABOUR TOTAL S\$:		\$	1,200.00
TOTAL S\$:		\$	2,723.88
7% GST		\$	190.67
GRAND TOTAL S\$:		\$	2,914.55

Repair day - 2 days

Lump-sum  
After paint photo

04/01/2020

Sun Pm (LKK)

TP without prejudice