

First (Call/PA) - LKK



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLN 5653 S

Parts	(a) Cost / List Price Items	\$	5,519.12
	Plus/Less 25%	\$	1,379.78
	Total of Cost / List	\$	4,139.34
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	200.00
Total Parts Cost		\$	4,339.34
Labour		\$	2,710.00
Total		\$	7,049.34

The above total will be subjected to 7% G.S.T.

Not Authorized
Resurvey Repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Name of Surveyor : Kenneth
Company : LKK
Survey conducted on : 4/2/20 at 1.10pm

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 03 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$

(e) Signature of surveyor : Lc Date: 4/2/20



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SLN 5653 S**
Make & Model : **TOYOTA PRIUS**
Chassis No : **JTDKB3FU603557668**

Submit By : **JENNY**
Year Manufacture : **2017**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor	1	\$200.00	S.N	✓
2	Rear bumper	1	\$497.50		✓
3	Rear bumper clip	10	\$40.00		✓
4	Rear bumper side retainer LH	1	\$112.70		X
5	Rear bumper side retainer RH	1	\$112.70		X
6	Rear bumper reinforcement	1	\$398.90		✓
7	Rear bumper lower garnish centre	1	\$582.60		✓
8	Rear bumper lower garnish RH	1	\$149.70		✓
9	Rear bumper tow cover	1	\$31.70		X
10	Rear bumper under cover	1	\$355.20		X
11	Rear bumper under cover RH	1	\$187.60		X
12	Rear bumper under cover clip	4	\$14.00		X
13	Wording "PRIUS"	1	\$51.90		✓
14	Wording "HYBRID"	1	\$55.47		✓
15	Tail door plate garnish	1	\$782.50		X
16	Tail end panel	1	\$596.60		X
17	Tail end panel garnish	1	\$151.60		X
18	Tail end panel garnish clip	10	\$35.00		X
19	Boot weatherstrip	1	\$353.10		X
20	Tail lamp RH - UPPER	1	\$498.75		X
21	Tail lamp RH - LOWER	1	\$511.60		X
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SLN 5653 S** Submit By : **Carmen Lim**
Make & Model : **TOYOTA PRIUS** Year of Manufacture : **2017**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, TAIL DOOR, END PANEL)	\$1,000.00	2501
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, TAIL DOOR, END PANEL)	\$1,000.00	504
3	TO Check wiring	\$50.00	152
4	To tuff coat. <i>nn</i>	\$150.00	X
5	To transfer boot mechanism to new boot <i>nn</i>	\$120.00	X
6	To conduct water leakage tests to ensure proper air and sealing <i>nn</i>	\$120.00	X
7	To remove & refit spare tyre, spare tyre board, carpet trim <i>nn</i> to assist work load.	\$150.00	X
8	To remove & refit reverse sensor	\$120.00	501

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.