## SM &UTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883 Email: SM\_AUTOMOTIVE@HOTMAIL.COM Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

MIKE TAN GIM SIANG Blk 1 Kaki Bukit Ave 6

# 01-43

293

Singapore 417883

Accident date: 02/02/2020

Estimated repair cost for vehicle no: SJE2679J HONDA STREAM 1.8 RSZ A '08

TP A16

Jinte

CHASSIS: RN61061093

Otv	Items	U/price	Amount
	2		\$686.10
	,	\$6.50	\$6.50 X
		\$28.40	\$56.80 ∠
			\$295.00
1			\$58.00
1			\$1,369.80 687
1			\$36.80
1			\$486.20 🗸
1	5 C lin		\$182.70 *
10	Front R/H Fender Cowling Clip	\$6.50	\$65.00
1	Front R/H Rim Cut		\$850.00 450(5~)
1	Front R/H Tyre Not New		\$350.00 ×
1	Front R/H Lower Arm Bex		\$328.20
1	Front R/H Knuckle Arm Dend		\$267.40
1	Front R/H Knuckle Arm Bearing		\$142.60
1	Front R/H Shock Absorber Sect		\$315.50
1	Front R/H Drive Shaft 2 Apr		\$997.40
1	Front Steering Rack		\$1,459.30
	1 1 1 1 10 1 1 1 1 1 1	1 Front Bumper Clip 2 Front Bumper Side Retainer 1 Front R/H Bumper Fog Lamp 1 Front R/H Bumper Fog Lamp Cover 1 Front R/H Head Lamp Lower Bracket 1 Front R/H Head Lamp Lower Bracket 1 Front R/H Fender Cowling 1 Front R/H Fender Cowling 10 Front R/H Fender Cowling Clip 1 Front R/H Rim 1 Front R/H Tyre 1 Front R/H Lower Arm 1 Front R/H Knuckle Arm Bearing 1 Front R/H Knuckle Arm Bearing 1 Front R/H Shock Absorber 1 Front R/H Drive Shaft 2	1 Front Bumper Clip \$6.50 2 Front Bumper Side Retainer \$28.40 1 Front R/H Bumper Fog Lamp \$28.40 1 Front R/H Bumper Fog Lamp Cover \$1 1 Front R/H Head Lamp \$1 1 Front R/H Head Lamp Lower Bracket \$1 1 Front R/H Fender \$2000 \$1 1 Front R/H Fender Cowling \$1 10 Front R/H Fender Cowling Clip \$6.50 1 Front R/H Rim \$1 1 Front R/H Tyre \$1 1 Front R/H Lower Arm \$1 1 Front R/H Knuckle Arm \$2000 \$1 1 Front R/H Shock Absorber \$2000 \$1 1 Front R/H Shock Absorber \$2000 \$1 1 Front R/H Drive Shaft \$2000 \$1 1 Front R/H Shock Absorber \$2000 \$1 1 Front R/H Drive Shaft \$2000 \$1 1 Front R/H Shock Absorber \$2000 \$1 1

Subtotal :- \$7,953.30

07/02/2020

S.N: 450

2265.70

## **Labour charges**

	To remove & refit front R/H undercarriage		2とい <sup>.</sup> \$3 <b>80.00</b>
	To remove & refit R/H drive shaft & steering rack		\$450.00 🗡
	To check wheel alignment		\$150,00 &
	To check wiring		\$80,0030
	Towing fee		\$100.00 🔨
	Tuff kote	1260	\$150.00 .30
•	Panel beating		\$150.00 30 \$1,000.00 500 \$1,000.00 400
	Spray painting		\$1,000.00 400
		Subtotal:-	\$3,310.00
		- Total:-	\$11,263.30

LKK Auto Consultants hence notify the Repairer of the following:

• To resurvey before/after spray painting

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 3522:56 L/s: 2.8K 05Days

