

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

31-Jan-20

ESTIMATE REPAIR BILL FOR HYUNDAI I30A REGN NO: SHD 1410 C

1 pc	Front bumper <i>xnn</i>	\$	811.11
1 pc	Front bumper emblem <i>xnn</i>	\$	27.80
1 pc	Front n/s fog lamp <i>xnn</i>	\$	840.90
1 pc	n/s head lamp <i>xnn</i>	\$	1,531.57
1 pc	Front n/s side bracket <i>xnn</i>	\$	32.51
1 pc	Front n/s fender <i>Buc</i>	\$	514.02
1 pc	Front n/s fender inner shield <i>xnn</i>	\$	176.72
1 pc	Front n/s fender signal lamp ?	\$	32.10
1 pc	Front n/s rim <i>scr</i>	\$	246.00
1 pc	Front n/s door <i>DD</i>	\$	1,723.60
1 pc	Front n/s door upper hinge ?	\$	36.10
1 pc	Front n/s door lower hinge ?	\$	36.10
1 pc	n/s mirror assy <i>X(R)</i>	\$	749.49

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Less 20%

S/NETT

1 set	Front bumper clips <i>xnn</i>	\$	48.00
1 pc	Front n/s fender sticker <i>nes</i>	\$	30.00
1 pc	Front n/s fender inner shield clips <i>xnn</i>	\$	28.00
1 set	n/s door sticker <i>nes</i>	\$	100.00

Sundry

To check wheel alignment

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the n/s rocker panel garnish

To putty and spray painting on front bumper, front n/s fender, n/s side mirror, front n/s door, n/s rocker panel garnish

To apply rustproofing on the repaired and replaced panels.

\$	50.00	<i>\$30</i>
\$	80.00	<i>\$60</i>
\$	750.00	<i>\$540</i>
\$	1,000.00	<i>\$400</i>
\$	120.00	<i>\$50</i>
\$	7,612.42	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Ram/LKK
3/02/2020
Parasuram LKK Auto. com
8862778
Annapindys
Ref paint photo