

ASS. REC. BY:

REF: CS/CTI 20001931 / Ktd316

Special Instruction: ok

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Maximen Adeline chng

of CTI

Date/Time: 4/2/2020 @ 4:22pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKR 6331 E

Insured:

SMP 320M

at Workshop m/s

8 Three Automotive

Tel:

9662 0282

of

Blk 8 Sln Ming Ind. Estate # 01-64/66

Policy No: DMHCSNA00000561900

Claim No: SNM20D200608, C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 29/01/2020

CA / REV / REP. / REV 24 HRS

(up)

5/2/2020

H.O.D. Endorsement:

Date/Time:

4:35pm @ 4/2/2020

Person Contacted:

Jey

Vehicle

IN / OUT

Date/Time

Action/Instruction

Estimate /

SKR 6331 E - X

SMP 320M - X

4/3 61 Rm 847501 Con. Form Cred: 10053-62: 67%

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Est. Adjusted	Status
Main	03 Feb 2020		04 Feb 2020 16:45 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
CLAIM SUBFOLDER DETAILS				
Insured:		[Created by insurer]		
Main Claimant:	NATIONAL CAR RENTALS PTE LTD			
Vehicle Reg. No.:	SKR6331E	Date of Loss:	24/01/2020 08:00 - :59	
Claim Type:	TP / SNM20D200608C02	Policy/Cover Note No.:	DMHCSNA00000561900	
Vehicle Reg. No. (Insured):	SMP320M	Policy No. (Claimant):		
		Excess:	S\$500.00	
Repairer:	S Three Automotive Recovery Pte Ltd (HQ) Bldg 8 Sin Ming Industrial Estate, #01-64/66 Sector C, 575643 Sin Ming - Tel: 62841542 / 62841575			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Adeline Chng Pei Wen]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 13/02/2020]			
Adj. Asg. Remarks:	survey revert.			
ASSOCIATED MAIL RECEIVED				
There are no mail for this case. View All Compose Case Mail				
ALL ASSOCIATED TASKS				
View All	Search Tasks	Create New Task	Complete	
Due Date	Priority	Type	Task Group	Subject
				Handler
				Assigned By
				Completed On
				Created On
				Done?
No results.				

Nivitha (LKK Auto)

From: Adeline Chng <adeline.chng@sg.cntaiping.com>
Sent: Tuesday, 4 February 2020 4:22 PM
To: assignments
Cc: Serene Chui Yoke Har
Subject: FW: YOUR REF: SNM20D200608/SMP320M/ADELINE & OUR REF: .CS/1014/20/S3 - Pre-Repair Survey for SKR 6331E.

Dear Lkk

Please refer to below email and liaise with third party workshop accordingly.

Thank you.

Adeline Chng

Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6155 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

From: Serene Chui Yoke Har [mailto:serene@libertylaw.com.sg]
Sent: Tuesday, 4 February 2020 4:10 PM
To: Adeline Chng <adeline.chng@sg.cntaiping.com>
Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: Re: YOUR REF: SNM20D200608/SMP320M/ADELINE & OUR REF: .CS/1014/20/S3 - Pre-Repair Survey for SKR 6331E.

Dear Adeline Chng,

We refer to your letter dated 4 February 2020.

Kindly arrange for **Kenneth Kong**, to carry out the pre-repair survey of our client's vehicle SKR 6331E as a 'single joint expert'.

Please be informed that the said vehicle can be surveyed / inspected at:

Venue : **S Three Automotive Recovery Pte Ltd**

Blk 8 Sin Ming Industrial Estate

**#01-64/66
Singapore 575643**

Contact / Tel : **Ms. Joey / 9662 0282**

Kindly acknowledge receipt hereof.

Regards,

Serene

for and on behalf of Christine Sekhon

Liberty Law Practice LLP

10 Hoe Chiang Road

#13-03A Keppel Towers

Singapore 089315

DID: 3152 0980

Privileged and/or confidential information may be contained in this email or its attachments. If you are not the intended recipient, you must not disclose, copy or distribute the contents therein or take any action in reliance of such contents. Communication of any information in this email or its attachments to an unauthorized person is prohibited

Please consider the environment before printing this e-mail!

On Tue, Feb 4, 2020 at 2:48 PM Adeline Chng <adeline.chng@sg.cntaiping.com> wrote:

Without Prejudice

Dear Sirs

We refer to your email of 03/02/2020 pertaining to the above matter.

Attached herewith PRS letter for your next action.

Thank you.

Adeline Chng

Executive

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 6389 6155 | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

From: Claims Dept of CTI

Sent: Tuesday, 4 February 2020 2:38 PM

To: Adeline Chng <adeline.chng@sg.cntaiping.com>; serene@libertylaw.com.sg

Subject: OUR REF: SNM20D200608/SMP320M/ADELINE & YOUR REF: .CS/1014/20/S3 - Pre-Repair Survey for SKR 6331E.

Dear Adeline,

Please conduct PRS-SKR6331E -soonest possible.

Office in charge -Adeline Chng -DID 6389 6155

Dear Serene,

**** kindly quote our reference number when replying. ****

Thank you.

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

Tel: 6389 6116

Fax (65) 6224 7175 / 6224 7478

Email : claimsdept@sg.cntaiping.com

Website:www.sg.cntaiping.com

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Serene Chui Yoke Har <serene@libertylaw.com.sg>

Sent: Monday, February 3, 2020 2:57 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: Your insured: SMP 320M. Pre-Repair Survey for SKR 6331E. Our ref no.: CS/1014/20/S3

Accident on 24.01.2020 involving SKR 6331E and SMP 320M at the carpark of Floridian Condominium, 965 Bukit Timah Road.

Dear Sirs,

We refer to the above matter.

Please find the attached copy of the Notice to Conduct Pre-Repair Survey dated 3 February 2020 together with our client's Accident Statement /Traffic Police Report and accident scene photographs for your necessary action.

Kindly acknowledge receipt hereof.

Regards,

Serene

for and on behalf of Christine Sekhon
Liberty Law Practice LLP
10 Hoe Chiang Road
#13-03A Keppel Towers
Singapore 089315

DID: 3152 0980

Privileged and/or confidential information may be contained in this email or its attachments. If you are not the intended recipient, you must not disclose, copy or distribute the contents therein or take any action in reliance of such contents. Communication of any information in this email or its attachments to an unauthorized person is prohibited

Please consider the environment before printing this e-mail!

Personal Particulars of Owner & Driver (Vehicle A)

Date of Accident: 24/01/20 (dd/mm/yy) Time of Accident: 12:00 (24-HR-FORMAT)
Vehicle No.: SR6331E Vehicle Make & Model: Joyce Camry
Exact location of Accident: 965 BT Timah Rd Floridian Condo
Policyholder's Name: National Car Rental Pte Ltd NRIC/FIN/REG No.: campat
Driver's Name: Zhou Jing NRIC/FIN/REG No.: G1999386N
Driver's Contact No.: 94871251 Company Contact No.: _____
Date of birth: 30/3/86 Driving Pass Date: 28/3/2011
Driver's Address: 390A Havelock Rd Northpoint Plaza #01-07
Insurance Company: NTC 5169664
Policy No.: _____ Type of Coverage: Comprehensive / Third Party / Third Party, Fire & Theft

Relationship between Owner & Driver: (Please **CIRCLE** one only)

Owner / Spouse / Children / Friend / Parents / Sibling / Relative / Employee / Hiree / Others specify: _____

What do you wish to claim? (Please **TICK** one only)

☒ Own Insurance / ☐ Other Vehicle (The one you want to claim against) / ☐ Reporting (For Record Purpose)

Exact purpose for which the vehicle
Was being used at time of accident?

Occupation (nature job) ☒ Indoor / ☐ Outdoor

☒ Private Use / ☐ Work purpose

*No. of Passengers / Including Driver: 1

*Passanger Name: _____

Gender: Male / Female

*Passanger Name: _____

Gender: Male / Female

Weather condition & Road conditions? (On the day of accident)

☒ Clear & Dry / ☐ Raining & Wet / ☐ After-Rain & Wet / ☐ Drizzling & Wet / Others: _____

Was there any video captured by your car Car camera? ☐ Yes / ☒ No

Any Injuries: ☐ Yes / ☐ No (If YES) Injured Person's Name: _____

Injuries Sustain: _____ Injured Person in Which Vehicle: _____

Police Report filed: ☐ Yes / ☐ No (If YES) Which Police Station: _____

The Other Party (S) Details:

1. Driver's Name / IC No: _____ Vehicle No: 5MF 320M

Driver's Contact No: _____ Insurance Company: _____

2. Driver's Name / IC No (If Any): _____ Vehicle No: _____

Driver's Contact No: _____ Insurance Company: _____

*Independent Witness (If Any): _____ Contact No: _____

Preferred Workshop Name: _____ Contact No: _____

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



SKETCH PLAN

Floridian Condo Carpan



A - SKP6331E
B - SMP 320M

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My vehicle was parked stationary in the parking lot when vehicle B reversed and hit the front left portion of my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Not authorized
61 km @ 4750k
Purvey After Paint
4 days

TO :
ATTN : MOTOR CLAIM DEPT. ----- T/P VEH. NO. : SMP320M -----

ESTIMATE REPORT 1st QUOTATION

JOB NO. : _____

OWNER'S PARTICULAR

NAME : NATIONAL CAR RENTALS PTE LTD
ADDRESS : _____

CONTACT : _____

LICENSE NO. : SKR6331E TRANS. :
MAKE / MODEL : TOYOTA CAMRY
OWNER'S INSURER :
JOB-CODE : TP S/A : JOEY

CHASSIS NO. :
ENGINE NO. : _____

ACCIDENT DATE : 24-Jun-20

CLAIM DETAIL

MATERIALS

		QTY	QUO-PRICE	DISC- %	DISC- PRICE	SUR- DISP	REV. PRICE
1	FRONT BUMPER SPONGE	1.00	CM 283.50	25.00	212.63	Y	✓
2	FRONT BUMPER	1.00	543.20 Bu 691.00	25.00	518.25	Y	✓
3	FRONT BUMPER RETAINER LH	1.00	0.7 60.00	25.00	45.00	Y	✓
4	FRONT BUMPER RETAINER RH	1.00	5 60.00	25.00	45.00	Y	X
5	FRONT BUMPER REINFORCMENT	1.00	Ar 421.79	25.00	316.34	Y	✓
6	FRONT BUMPER FOG LAMP LH	1.00	231.70 266.98	25.00	200.24	Y	✓
7	FRONT BUMPER LOWER GRILLE	1.00	5 126.50	25.00	94.88	Y	X
8	FRONT BUMPER LOWER GARNISH	1.00	CM 182.10	25.00	136.58	Y	✓
9	FRONT BUMPER BRACKET LH	1.00	R 102.00	25.00	76.50	Y	X
10	FRONT BUMPER BRACKET RH	1.00	R 102.00	25.00	76.50	Y	X
11	RADIATOR GRILLE	1.00	mycm 530.50	25.00	397.88	Y	✓
12	FRONT GRILLE LOGO	1.00	me 56.00	25.00	42.00	Y	✓
13	FOG LAMP COVER CHROME LH	1.00	5 228.00	25.00	171.00	Y	X
14	FOG LAMP BRACKET	1.00	R 124.00	25.00	93.00	Y	X
15	HEADLAMP ASSY HID RH	1.00	5 2925.25	25.00	2193.94	Y	X
16	HEADLAMP ASSY HID LH	1.00	2309 CM 2925.25	25.00	2193.94	Y	✓
17	HEADLAMP PANEL RH	1.00	R 201.78	25.00	151.34	Y	X
18	HEADLAMP PANEL LH	1.00	R 201.78	25.00	151.34	Y	X
19	FRONT FENDER LH	1.00	737.35 Bu 761.45	25.00	571.09	Y	✓
20	FRONT FENDER INNER SHILED LH	1.00	CM 146.50	25.00	109.88	Y	✓
21	FRONT FENDER EMBLEM - VVTI	1.00	me 57.75	25.00	43.31	Y	✓
22	RADIATOR SIDE GARNISH RH	1.00	5 79.80	25.00	59.85	Y	X
23	BONNET	1.00	R 1186.20	25.00	889.65	Y	X
24	RADIATOR	1.00	5 1478.00	25.00	1108.50	Y	X
25	AIRCON CONDENSOR	1.00	5 1379.50	25.00	1034.63	Y	X
26	FRONT BUMPER TOP GUARD	1.00	5 146.50	25.00	109.88	Y	X
27	NUMBER PLATE HOLDER	1.00	5 80.70	25.00	60.53	Y	X
TOTAL (PARTS) :			14804.83		11103.62		

SPECIAL NETT ITEM

1	FRONT BUMPER CLIPS 1SET	1.00	me 50.00	0.00	50.00	Y	✓
2	FRONT BUMPER SENSOR RH	1.00	245 280.00	0.00	280.00	Phan	✓

Not Noted
 11 Day 8?
 Running After Paint
 4 days

TO :
 ATTN : MOTOR CLAIM DEPT. ----- T/P VEH NO : SMP320M -----

ESTIMATE REPORT 1st QUOTATION JOB NO : _____

OWNER'S PARTICULAR
 NAME : NATIONAL CAR RENTALS PTE LTD CONTACT :
 ADDRESS :

LICENSE NO : SKR6331E TRANS : CHASSIS NO :
 MAKE / MODEL : TOYOTA CAMRY ENGINE NO :
 OWNER'S INSURER :
 JOB CODE : TP S/A : JOEY ACCIDENT DATE : 24-Jan-20

CLAIM DETAIL

MATERIALS	QTY	QUO-PRICE	DISC %	DISC-PRICE	SUR-PRICE	REV PRICE
1 FRONT BUMPER SPONGE	1.00	283.50	25.00	212.63	Y	✓
2 FRONT BUMPER Bu	1.00	691.00	25.00	518.25	Y	✓
3 FRONT BUMPER RETAINER LH D17	1.00	60.00	25.00	45.00	Y	X
4 FRONT BUMPER RETAINER RH Lu	1.00	60.00	25.00	45.00	Y	✓
5 FRONT BUMPER REINFORCMENT	1.00	421.79	25.00	316.34	Y	✓
6 FRONT BUMPER FOG LAMP LH	1.00	266.98	25.00	200.24	Y	✓
7 FRONT BUMPER LOWER GRILLE Pu	1.00	126.50	25.00	94.88	Y	X
8 FRONT BUMPER LOWER GARNISH	1.00	182.10	25.00	136.58	Y	✓
9 FRONT BUMPER BRACKET LH	1.00	102.00	25.00	76.50	Y	✓
10 FRONT BUMPER BRACKET RH R	1.00	102.00	25.00	76.50	Y	X
11 RADIATOR GRILLE	1.00	530.50	25.00	397.88	Y	✓
12 FRONT GRILLE LOGO	1.00	56.00	25.00	42.00	Y	✓
13 FOG LAMP COVER CHROME LH	1.00	228.00	25.00	171.00	Y	X
14 FOG LAMP BRACKET R	1.00	124.00	25.00	93.00	Y	X
15 HEADLAMP ASSY HID RH Lu	1.00	2925.25	25.00	2193.94	Y	X
16 HEADLAMP ASSY HID LH CM	1.00	2925.25	25.00	2193.94	Y	✓
17 HEADLAMP PANEL RH R	1.00	201.78	25.00	151.34	Y	X
18 HEADLAMP PANEL LH R	1.00	201.78	25.00	151.34	Y	✓
19 FRONT FENDER LH Bu	1.00	761.45	25.00	571.09	Y	✓
20 FRONT FENDER INNER SHIELD LH CM	1.00	146.50	25.00	109.88	Y	✓
21 FRONT FENDER EMBLEM - VVTI R	1.00	57.75	25.00	43.31	Y	✓
22 RADIATOR SIDE GARNISH RH Lu	1.00	79.80	25.00	59.85	Y	X
23 BONNET R	1.00	1186.20	25.00	889.65	Y	X
24 RADIATOR Lu	1.00	1478.00	25.00	1108.50	Y	X
25 AIRCON CONDENSOR Lu	1.00	1379.50	25.00	1034.63	Y	X
26 FRONT BUMPER TOP GUARD Pu	1.00	146.50	25.00	109.88	Y	X
27 NUMBER PLATE HOLDER Lu	1.00	80.70	25.00	60.53	Y	X
TOTAL (PARTS) :		14804.83		11103.82		

SPECIAL NET ITEM

1 FRONT BUMPER CLIPS 1SET R	1.00	50.00	0.00	50.00	Y	✓
2 FRONT BUMPER SENSOR RH	1.00	280.00	0.00	280.00	Y	✓

3	FRONT FENDER INNER SHIELD CLIPS 1SET	1.00	50.00	0.00	50.00	Y	✓
4	FRONT NUMBER PLATE	1.00	50.00	0.00	50.00	Y	45.00
5	RADIATOR COOLANT	1.00	80.00	0.00	80.00	Y	X
TOTAL (PARTS) :			510.00		510.00		

LABOUR

1	STRAIGHTEN & PANEL BEAT ACCIDENT AREA	1.00	1200.00	0.00	1200.00	Y	550.00
2	SPRAY PAINTING ON AFFECTED AREA	1.00	1600.00	0.00	1600.00	Y	900.00
3	CHECK WIRING SYSTEM & RESET HEADLAMP SYS	1.00	120.00	0.00	120.00	Y	20.00
4	RESPRAY TUFF KOTE ON ACCIDENT AREA	1.00	120.00	0.00	120.00	Y	30.00
6	R&R AIRCON CONDENSOR & TOP UP AIR CON GAS	1.00	150.00	0.00	150.00	Y	X
TOTAL (LABOUR) :			3190.00		3190.00		
TOTAL PARTS & LABOUR			18504.83		14803.62		

EXCESS : \$

NO. OF DAY :

RE-SURVEY : ☒ BEFORE / AFTER PAINTING

PART ☒ BY-PART OR LUMP-SUM : \$

DATE OF SURVEY : 3, 2, 2020

SURVEY BY : Kenneth

CONTACT NO : 96910663

FAX NO :

NOTE : LUMP-SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Feb 2020		04 Feb 2020 16:45 Edit Adj Rpt	S\$4,750.00 Edit Estimates	S\$4,750.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	Co. Reg. No.: -								
Main Claimant:	NATIONAL CAR RENTALS PTE LTD								
Vehicle Reg. No.:	SKR6331E	Date of Loss:	24/01/2020 08:00 - :59 [59 Months and 23 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM20D200608C02	Policy/Cover Note No.:	DMHCSNA00000561900						
Vehicle Reg. No. (Insured):	SMP320M	Policy No. (Claimant):							
		Excess:	S\$500.00						
Repairer:	S Three Automotive Recovery Pte Ltd (HQ) Blk 8 Sin Ming Industrial Estate, #01-64/66 Sector C, 575643 Sin Ming - Tel: 62841542 / 62841575								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Adeline Chng Pei Wen]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 13/02/2020]								
Adj Asg. Remarks:	survey revert.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKR6331E (SNM20D200608C02)
[SMP320M]
TP
NATIONAL CAR RENTALS PTE LTD
Jan 24 2020 8:00AM
[-]
S Three Automotive Recovery Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View			View in Browser		
Photos/Images									3 per page			<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print			
1	05/03/20 10:01	General View								Load JPG	<input checked="" type="checkbox"/>			
2	05/03/20 10:01	General View								Load JPG	<input checked="" type="checkbox"/>			
3	05/03/20 10:01	General View								Load JPG	<input checked="" type="checkbox"/>			
4	05/03/20 10:01	General View								Load JPG	<input checked="" type="checkbox"/>			
5	05/03/20 10:01	General View								Load JPG	<input checked="" type="checkbox"/>			
6	05/03/20 10:01	General View								Load JPG	<input checked="" type="checkbox"/>			
7	05/03/20 10:01	General View								Load JPG	<input checked="" type="checkbox"/>			
8	05/03/20 10:01	General View								Load JPG	<input checked="" type="checkbox"/>			
9	05/03/20 10:01	General View								Load JPG	<input checked="" type="checkbox"/>			
10	05/03/20 10:01	General View								Load JPG	<input checked="" type="checkbox"/>			
11	05/03/20 10:01	General View								Load JPG	<input checked="" type="checkbox"/>			
12	05/03/20 10:01	General View								Load JPG	<input checked="" type="checkbox"/>			
13	05/03/20 10:01	General View								Load JPG	<input checked="" type="checkbox"/>			
14	05/03/20 10:01	General View								Load JPG	<input checked="" type="checkbox"/>			
15	05/03/20 10:01	General View								Load JPG	<input checked="" type="checkbox"/>			
16	05/03/20 10:01	General View								Load JPG	<input checked="" type="checkbox"/>			
17	05/03/20 10:01	General View								Load JPG	<input checked="" type="checkbox"/>			
18	05/03/20 10:01	General View								Load JPG	<input checked="" type="checkbox"/>			
19	05/03/20 10:03	Reinspection Photo								Load JPG	<input checked="" type="checkbox"/>			
20	05/03/20 10:03	Reinspection Photo								Load JPG	<input checked="" type="checkbox"/>			
21	05/03/20 10:03	Reinspection Photo								Load JPG	<input checked="" type="checkbox"/>			
22	05/03/20 10:03	Reinspection Photo								Load JPG	<input checked="" type="checkbox"/>			
23	05/03/20 10:03	Reinspection Photo								Load JPG	<input checked="" type="checkbox"/>			
24	05/03/20 10:03	Reinspection Photo								Load JPG	<input checked="" type="checkbox"/>			
25	05/03/20 10:03	Reinspection Photo								Load JPG	<input checked="" type="checkbox"/>			
26	05/03/20 10:03	Reinspection Photo								Load JPG	<input checked="" type="checkbox"/>			
27	05/03/20 10:03	Reinspection Photo								Load JPG	<input checked="" type="checkbox"/>			
28	05/03/20 10:03	Reinspection Photo								Load JPG	<input checked="" type="checkbox"/>			
29	05/03/20 10:03	Reinspection Photo								Load JPG	<input checked="" type="checkbox"/>			
30	05/03/20 10:03	Reinspection Photo								Load JPG	<input checked="" type="checkbox"/>			
Documentation									1 per page			<input checked="" type="checkbox"/>		
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)								Thumbnail	Print			
1	04/02/20 16:46	Singapore Accident Statement								Load PDF	<input checked="" type="checkbox"/>			
2	04/02/20 16:46	Pre-Repair Survey								Load PDF	<input checked="" type="checkbox"/>			

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer			
<small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20001931/KTD3E2

Date: 11/03/2020

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMHCSNA00000561900

Claimant Vehicle
No : SKR6331E

Insured Vehicle
No : SMP320M

Date of Loss: 24/01/2020

Nature of Claim: TP

Claim
No: SNM20D200608C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKR6331E	Engine No:	HIDDEN
Make & Model:	TOYOTA CAMRY, 2.0 (A)	Chassis No:	MR053BK5104025456
Reg. Date:	01/02/2015 (Man. Year: 2015)	Odometer:	65619 km
Colour:	Metallic Silver		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Falken 6 mm	Rear Left Side:	Yokohama 9 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,613.62	4,488.07	7,125.55	61.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,190.00	1,500.00	1,690.00	52.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,803.62	5,988.07	8,815.55	59.55
Approved Total (Overridden) (S\$)		4,750.00		
(S\$)	14,803.62	4,750.00	10,053.62	67.91
+ GST 7.00/7.00% (S\$)	1,036.25	332.50	703.75	67.91
Nett Amount (S\$)	15,839.87	5,082.50	10,757.37	67.91

INSPECTION

Date of Assignment: 04/02/2020

Date Inspected: 05/02/2020 Inspected At:

S Three Automotive Recovery Pte Ltd
(HQ)
Blk 8 Sin Ming Industrial Estate, #01-64/66
Sector C
Singapore 575643

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 11 Mar 2020)
Parts: 143	TOYOTA CAMRY 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKR6331E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER SPONGE	Cracked	283.50 FL	*188.20 FL
2	1		*FRONT BUMPER	Buckled	691.00 FL	*543.20 FL
3	1		*FRONT BUMPER RETAINER LH	Distorted	60.00 FL	*60.00 FL
4	1		*FRONT BUMPER RETAINER RH	Serviceable	60.00 FL	*- FL
5	1		*FRONT BUMPER REINFORCEMENT	Bent	421.79 FL	*421.79 FL
6	1		*FRONT BUMPER FOG LAMP LH	Mtg Cracked	266.98 FL	*231.70 FL
7	1		*FRONT BUMPER LOWER GRILLE	Serviceable	126.50 FL	*- FL
8	1		*FRONT BUMPER LOWER GARNISH	Cracked	182.10 FL	*182.10 FL
9	1		*FRONT BUMPER BRACKET LH	Repair	102.00 FL	*- FL
10	1		*FRONT BUMPER BRACKET RH	Repair	102.00 FL	*- FL
11	1		*RADIATOR GRILLE	Mtg Cracked	530.50 FL	*530.50 FL
12	1		*FRONT GRILLE LOGO	Necessary	56.00 FL	*56.00 FL
13	1		*FOG LAMP COVER CHROME LH	Serviceable	228.00 FL	*- FL
14	1		*FOG LAMP BRACKET	Repair	124.00 FL	*- FL
15	1		*HEADLAMP ASSY HID RH	Serviceable	2,925.25 FL	*- FL
16	1		*HEADLAMP ASSY HID LH	Cracked	2,925.25 FL	*2,309.00 FL
17	1		*HEADLAMP PANEL RH	Repair	201.78 FL	*- FL
18	1		*HEADLAMP PANEL LH	Repair	201.78 FL	*- FL
19	1		*FRONT FENDER LH	Buckled	761.45 FL	*737.35 FL
20	1		*FRONT FENDER INNER SHIELD LH	Cracked	146.50 FL	*146.50 FL
21	1		*FRONT FENDER EMBLEM - VVTI	Necessary	57.75 FL	*57.75 FL
22	1		*RADIATOR SIDE GARNISH RH	Serviceable	79.80 FL	*- FL
23	1		*BONNET	Repair	1,186.20 FL	*- FL
24	1		*RADIATOR	Serviceable	1,478.00 FL	*- FL
25	1		*AIRCON CONDENSOR	Serviceable	1,379.50 FL	*- FL
26	1		*FRONT BUMPER TOP GUARD	Serviceable	146.50 FL	*- FL
27	1		*NUMBER PLATE HOLDER	Serviceable	80.70 FL	*- FL
28	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
29	1		*FRONT BUMPER SENSOR RH	Shorted	280.00 FS	*245.00 FS
30	1		*SET FRONT FENDER INNER SHIELD CLIPS	Necessary	50.00 FS	*50.00 FS
31	1		*FRONT NUMBER PLATE	Dented	50.00 FS	*45.00 FS
32	1		*RADIATOR COOLANT	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,314.83	5,854.09
- List Item Discount on L Items 25.00/25.00% (\$\$)	3,701.21	1,366.02
Total Parts (\$\$)	11,613.62	4,488.07

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	STRAIGHTEN & PANEL BEAT ACCIDENT AREA	New	1,200.00	550.00
2	SPRAY PAINTING ON AFFECTED AREA	New	1,600.00	900.00
3	CHECK WIRING SYSTEM & RESET HEADLAMP SYS	New	120.00	20.00
4	RESPRAY TUFF KOTE ON ACCIDENT AREA	New	120.00	30.00
5	R&R AIRCON CONDENSOR & TOP UP AIR CON GAS	New	150.00	0.00
Gross Labour Cost (\$\$)			3,190.00	1,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >