

ESTEEM PERFORMANCE

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/252
Tel: +65-6484 1221 Fax: +65-6484 7829

Repair Estimates

GBJ 7776 Y

Finalized

Parts (a) Cost / List Price Items	\$ <u>467.75</u>	606.25
Plus/Less 25%	\$ <u>116.94</u>	151.56
Total of Cost / List	\$ <u>350.81</u>	454.69
(b) Nett Price Items		
Less		
Total of Nett Item		
(c) Special Nett Items	\$	200.00
Total Parts Cost	\$	654.69
Labour	\$ <u>450.00</u>	2,090.00
Total	\$ <u>800.81</u>	2,744.69

The above total will be subjected to 7% G.S.T.

0 • C
386 • 95 +
32 • 1 +
48 • 7 =
467 • 75 *
467 • 75 x
75 • %
350 • 8125 *
0 • C
200 • +
200 • +
50 • =
450 • *
0 • C
350 • 81 +
450 • =
800 • 81 *
800 • 81 x
80 • %
640 • 648 *
0 • C

45 \$650

*201.
\$640.65*

Name of Surveyor

Kenneth

Company

KKK

Survey conducted on

4/2/20

at

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 02 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor

Sc

Date:

4/2/20