

**CAS GARAGE PTE LTD**

(Reg No: 201828067M)

1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY, SINGAPORE 417883

VEHICLE REPAIR ESTIMATE

Insurance Company: AXA INSURANCE

Address: NO 8, SHENTON WAY, #24-01

AXA TOWER, S(068811)

Telephone: 68804888

Fax: 68804740

Email: motor.survey@axa.com.sg*Cecilia.*

Make/ Model : HYUNDAI TUCSON

Date: 03.02.2020

Chassis No : KMHJ3813MHU292856

Vehicle No: SFS7240G

Date/Time of Accide 29.01.2020/1825

Date of Reg: 28.10.2016

Materials Cost/ Spare Parts Cost**TO BE COMPLETED BY SERVICE ADVISOR**

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE FOR ONE		FINAL PRICE \$
1	FRONT BUMPER <i>reband</i>	1	\$ 785.60		\$ ✓ 785.60
2	FRONT BUMPER SIDE GARNISH RH <i>it</i>	1	\$ 185.20		\$ ✓ 185.20
3	FRONT BUMPER LOWER <i>new</i>	1	\$ 597.60		\$ + 597.60
4	FRONT BUMPER LIP <i>new</i>	1	\$ 127.30		\$ + 127.30
5	FRONT RADIATOR GRILLE <i>new</i>	1	\$ 953.70		\$ + 953.70
6	FRONT RADIATOR GRILLE TOP COVER <i>new</i>	1	\$ 108.30		\$ + 108.30
7	FRONT BUMPER SPONGE	1	\$ 256.30		\$ + 256.30
8	FRONT BUMPER REINFORCEMENT <i>new</i>	1	\$ 788.90		\$ + 788.90
9	FRONT BUMPER LOWER GRILLE	1	\$ 288.70		\$ + 288.70
10	FRONT BUMPER STIFFENER <i>new</i>	1	\$ 192.50		\$ + 192.50
11	FRONT BUMPER RETAINER <i>new</i>	1	\$ 89.60		\$ ✓ 89.60
12	FRONT FOGLAMPS LOWER COVER RH <i>new</i>	1	\$ 132.60		\$ + 132.60
13	FRONT FOGLAMPS UPPER COVER RH <i>new</i>	1	\$ 138.60		\$ + 138.60
14	FRONT DAYLIGHT RH <i>new</i>	1	\$ 629.50		\$ + 629.50
15	FRONT NUMBER PLATE GARNISH <i>new</i>	1	\$ 87.90		\$ + 87.90
16	FRONT HEADLAMP RH <i>new</i>	1	\$ 2,698.50		\$ ✓ 2,698.50
17	FRONT HEADLAMP BRACKET <i>new</i>	1	\$ 95.80		\$ ✓ 95.80
18	FRONT FOGLAMP RH <i>new</i>	1	\$ 268.50		\$ + 268.50
19	FRONT BONNET	1	\$ 1,852.30		\$ + 1,852.30
20	FRONT BONNET LOCK	1	\$ 198.20		\$ + 198.20
21	FRONT SUPPORT PANEL	1	\$ 1,056.70		\$ + 1,056.70
22	FRONT SUPPORT PANEL TOP GARNISH <i>new</i>	1	\$ 265.80		\$ + 265.80
23	FRONT FENDER INNER COWLING RH <i>new</i>	1	\$ 156.30		\$ + 156.30
24	FRONT FENDER RH <i>new</i>	1	\$ 966.80		\$ + 966.80
25	FRONT FENDER ARCH GARNISH RH <i>new</i>	1	\$ 198.50		\$ + 198.50
Total List Price Cost					\$ 13,119.70

PARTS DISCOUNT 20% \$ 10,495.76

Front Foglamp chrome Garnish RN (Top) New 120 60
 Front Foglamp chrome Garnish RN (Bottom) New 120 60.

3974.7
 3179.76

SPECIAL NETT	PARTS DESCRIPTION	QTY	PRICE \$	FINAL PRICE \$
1	FRONT BUMPER CLIPS* New	1SET	\$ 30.00	\$ 30.00
2	FRONT RADIATOR GRILLE CLIPS New	1SET	\$ 30.00	\$ 30.00
3	FRONT REVERSE SENSORS New	1 SET	\$ 250.00	\$ 250.00
4	FRONT FENDER COWLING SET New	1 SET	\$ 30.00	\$ 30.00
5	FRONT FENDER OUTER GARNISH CLIPS New	1 SET	\$ 30.00	\$ 30.00
Total Special Nett Items				\$ 370.00
Labour Works/ Panel Beating Related Works				
Job Scope				Quotation
TO RENEW DAMAGED PARTS, REPLACE, BEAT, WELD, REALIGN AND ALIGNE ALL PARTS				\$ 1,600.00
Spray Painting				300.
Job Scope				Quotation
TO RESPRAY AFFECTED AREAS				\$ 1,600.00
Others Cost (Accident Repair Related Expenses)				250.
Job Scope				Quotation
TO TUFFCOAT AFFECTED AREA				\$ 200.00
TO REMOVE AND REPLACE SENSORS AND DISTANCE SETTLING				\$ 150.00
TO REMOVE AND REFIT CONDENSER /RADIATOR AND TOP UP AIR CON GAS				\$ 120.00
TO CONDUCT WIRING CHECK ON FRONT HEADLAMPS				\$ 120.00
Total Others Cost				\$ 590.00
GRAND TOTAL				\$ 14,655.76

CAS GARAGE PTE LTD
 UEN 201828067M
 1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY,
 SINGAPORE 417883

CAS GARAGE PTE LTD

Person Incharge: Allan
 Direct Contact: +65 8782 7171
 Email: allan@casgarage.sg
 Fax : 6509 9501

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Adrian L
 L/S 04/02/20.
 04 days.

total: 3789.76
 L/S: 3K ✓