



新福德車廠私人有限公司

FIRST CAP
UKK

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

JIA YI CAR LEASING PTE LTD

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

03/02/2020

TP 1st Cap

Vic

Accident date: 30/01/2020

Estimated repair cost for vehicle no: SMN4841K TOYOTA CAMRY HYBRID 2.5 A '19

CHASSIS: AXVH701038450

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid		\$972.50 ✓
2	2	Rear Boot Lid Hinge	\$174.50	\$349.00 +
3	2	Rear Boot Lid Shock Absorber	\$371.90	\$743.80 +
4	1	Rear Boot Lid Emblem Logo		\$121.10 +
5	1	Rear Boot Lid Camry Logo		\$134.45 +
6	1	Rear Boot Lid Hybrid Synergy Drive Logo		\$121.50 +
7	1	Rear Boot Lid Center Moulding		\$587.90 +
8	1	Rear Boot Lid Lock		\$531.40 +
9	1	Rear Boot Lid Weatherstrip		\$371.90 +
10	2	Rear Boot Lid Side Reflector		\$381.90 +
11	1	Rear Bumper Distorted		\$731.40 ✓
12	1	Rear Bumper Lower Lid Deformed		\$581.10 ✓
13	10	Rear Bumper Clip New	\$6.50	\$65.00 30
14	2	Rear Bumper Side Retainer Outer 2 RH coated	\$171.40	\$342.80 171.40
15	2	Rear Bumper Side Retainer Inner	\$182.30	\$364.60 182.30
16	2	Rear Bumper Side Reflector RH coated	\$171.70	\$343.40 171.70
17	1	Rear Bumper Top Camry Chrome Moulding Not new		\$231.40 x
18	1	Rear Bumper Under Cover Deformed		\$274.60 ✓
19	1	Rear Bumper Reinforcement 2 new		\$371.90 x
20	1	Rear Bumper Inner Foam new		\$271.10 ✓
21	1	Rear Bumper Reverse Sensor Dented		\$380.00 ✓
22	1	Rear End Panel Repair		\$731.40 x
23	1	Rear End Panel Top Garnish Not new		\$374.10 x
24	1	Rear R/H Taillamp lit		\$381.90 ✓
25	2	Rear R/H Taillamp Clip New	\$8.00	\$16.00 ✓
26	1	Rear R/H Taillamp Lower Bracket Not new		\$174.00 x
27	1	Rear R/H Taillamp Panel Distorted		\$271.70 ✓

28	1	Rear R/H Fender <i>Distorted</i>		\$1,178.10	✓
29	1	Rear R/H Fender Inner Panel <i>Repis</i>		\$472.20	X
30	1	Rear R/H Fender Air Duct <i>Delund</i>		\$181.90	✓
31	1	Rear R/H Fender Cowling <i>torn</i>		\$371.90	171
32	8	Rear R/H Fender Cowling Clip <i>nee</i>	\$6.50	\$52.00	30
33	1	Rear R/H Fender Inner Trim Board <i>torn</i>		\$731.40	350
34	8	Rear R/H Fender Inner Trim Board Clip <i>nee</i>	\$6.50	\$52.00	30
35	1	Rear R/H Battery <i>Damaged</i>		\$455.00	250/50
36	1	Rear R/H Battery Top Sensor <i>Damaged</i>		\$371.90	✓
37	1	Rear Exhaust		\$831.90	+
38	1	Rear Exhaust Mounting <i>nee</i>	\$61.10	\$61.10	✓
39	1	Rear Center Exhaust		\$971.40	+
40	1	Rear Windscreen Moulding <i>nee</i>	135 ✓		
41	1	Rear Wheel Rim <i>let</i>	1050 650(SN)		
				Subtotal :-	\$15,952.65

Labour charges

To remove & refit cushion & trim board	\$280.00	80
To remove & refit reverse sensor	\$100.00	50
To remove & refit reverse camera	\$180.00	X
To remove & refit rear windscreen	\$200.00	120
Gum	\$80.00	60
To remove & refit rear battery & reset computer	\$280.00	50
To check wiring	\$100.00	30
Tuff kote	\$150.00	80
Towing fee	\$150.00	60
Panel beating	\$2,000.00	800
Spray painting	\$1,800.00	800

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Subtotal :- \$5,320.00

Total:- \$21,272.65

total 7260

4/5: 5-8K

5-8K

of Day