



潘發展私人有限公司
A. S. PHOON PTE LTD
'cos no one else

Head Off : 399, Changi Road S'pore 419846. Tel: (65) 6747 0770 Fax: (65) 6841 1263
Ubi : Blk 3007 #01-432/436 Ubi Road 1, S'pore 408701. Tel: (65) 6744 0770 Fax: (65) 6742 0250
Toh Guan : Blk 36 Toh Guan Road East #01-35 S'pore 608580 Tel: (65) 6515 0770 Fax: (65) 6515 0779
Website : www.asphoon.com Email: Enquiry@asphoon.com Co Reg No: 197701213H

FBF9530Y HONDA CB125 REPAIR ESTIMATE 04FEB2020

ITEM	DESCRIPTION	AMOUNT SGD
1	REAR FENDER	\$115.00 <i>ant</i>
2	REAR LICENCE PLATE	\$20.00 <i>bt</i>
3	REAR LICENCE PLATE LIGHT	\$85.00 <i>ant</i>
4	STAY. REAR LICENCE PLATE LIGHT	\$60.00 <i>bt</i>
5	EXHAUST ASSY	\$390.00 <i>Rx</i>
6	EXHAUST GASKET	\$8.00 <i>del x nn</i>
7	REAR CAP MUFFLER	\$55.00 <i>del</i>
8	HEAT PROTECTION	\$85.00 <i>ant</i>
9	FRONT FENDER	\$78.00 <i>ant</i>
10	TO RE-ALIGNMENT FRONT FORK <i>Labour</i>	\$150.00 <i>100 SW</i>
11	FRONT SIGNAL LH	\$60.00 <i>ant</i>
12	CLUTCH LEVER	\$28.00 <i>ant</i>
13	IU UNIT	\$160.00 <i>ant</i>
14	IU BRACKET	\$40.00 <i>bt</i>
15	HANDLE BAR	\$110.00 <i>Ran</i>
16	FUEL TANK	\$395.00 <i>Rx</i>
17	GEAR PEDAL	\$60.00 <i>bt</i>
18	REAR SIGNAL LH	\$60.00 <i>ant</i>
19	REAR FOOTREST	\$48.00 <i>ant</i>
20	REAR FOOTREST BRACKET LH	\$85.00 <i>bt</i>
21	REAR TOP BOX	\$250.00 <i>ant</i>
22	WORKMANSHIP	\$300.00 <i>200</i>
23	TRANSPORTATION TP-IDAC-WORKSHOP @\$50	\$100.00 <i>80</i>
24	BODY CHASSIS REPAIR	\$280.00 <i>150 points</i>
25	TRANSPORTATION 2 WAY TO REPAIR CHASSIS @\$50	\$100.00 <i>80 x an</i>
26	SPRAY PAINTING	\$350.00 <i>200</i>

TOTAL \$ \$3,472.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Tauhin 97495749
WP 1289
4/2/20 e 530 10% - 1160.10
580
1740.10
Repair after repair 4/5/20 1400 #
5 days 05 days
5/13/20 Confirm with Mr Kee thru phone.
J. P. H. H.