

# AUTOWORX HOUSE

176 SIN MING DRIVE #02-01 SINGAPORE 575721  
 TEL: 6452 8211 FAX: 6451 7420

## ESTIMATE

*Not Authored*

*Rummy Bepain*

*4. [unclear]*

*11/27 @ 2900h*

*Accura*

Date: 3/2/2020

### EXCHANGE LEASING

Lentor Plain  
 Phone 786548

QUANTITY	PARTICULARS	AMOUNT (\$)
	<b>RE: TOYOTA VOXY / SMH 7281 M</b>	
	Rear tail door <i>1561.90</i>	<del>1,983.90</del>
	Rear tail door lock	<del>242.50</del> X
	Rear tail door lock catch	<del>86.50</del> X
	Rear tail door windscreen glass moulding	242.20
	Rear tail door emblem "HYBRID SYNERGY DRIVE"	78.40
	Rear tail door inner trim	<del>364.50</del> X
	Rear tail door lock sensor	CMT 274.30
	Rear bumper <i>736.95</i>	<del>1,065.30</del>
	Rear bumper park sensor	<del>550.80</del> X
	Rear bumper reflector	<del>153.30</del> X
	Rear bumper impact sponge	NIP 364.70
	Rear bumper reinforcement beam	<del>374.40</del> X
	Rear bumper side retainer	<del>68.60</del> X
	Rear end panel - outer	<del>564.30</del> X
	Rear end panel - inner	<del>658.20</del> X
	Rear end panel top trim	<del>263.20</del> X
	Rear end panel weatherstrip	<del>311.40</del> X
	sub-total	7,646.50
	less 25%	1,911.63
	sub-total	5,734.88
	windscreen glass sealant	nett @ 120.00
		<i>400h</i> 240.00
	sub-total	5,974.88

*P = 2887.75 - 25%  
 = 2165.81*

*SN - 40 @ 275.40*

*L - 1410*

*2892.64*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey.
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature: \_\_\_\_\_  
 Date: \_\_\_\_\_

Page 1 of 2

balance brought forward	5,974.88	
To remove and replace the parts mentioned above, panel beat and realign the necessary affected areas.	1,200.00	500
To check wiring system.	60.00	20
To apply rust proofing on affected areas.	120.00	30
To apply waterproof sealant on affected areas.	<del>120.00</del>	<del>30</del>
To remove rear windscreen glass(es) to enable repair.	150.00	120
To install reverse sensors & reverse camera.	80.00	50
To remove carpet, trimming to enable repair.	120.00	30
To apply putty and spray painting on affected areas.	770.00	660
Total	8,594.88	