



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM20001955/R1pa3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:KITTY

Date : 25-09-2020



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMD 6084T	Veh. Inspected	SJE 7377Y
Policy No.	VPA/P2170117	Coverage (\$)	0.00
Claim No.	S0M02EKV	Excess (\$)	0.00
Assign From		Assign Date	04/02/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA RUSH 1.5X A	c.c	1495
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	J200E0019538	Colour	BLACK
Odometer	205484	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/55 R17	KINFOREST	6 mm
L/H Front Tyre	215/55 R17	KINFOREST	6 mm
R/H Rear Tyre	215/55 R17	KINFOREST	6 mm
L/H Rear Tyre	215/55 R17	KINFOREST	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	25/01/2020	Inspection Date	06/02/2020
Survey held at	42 TOH GUAN ROAD EAST #01-78		
Repairer	MTM PERFORMANCE AUTO PTE. LTD.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **7 Working Days**