

ESTIMATE FOR VEHICLE NUMBER: SJE7377Y

ITEM	ESTIMATION COST	REMARKS
Rear door <i>bt-</i>	\$1,006.50	
Rear tyre cover <i>br-</i>	\$675.60	
Rear bumper <i>de-</i>	\$421.30	
Rear reflector LH <i>X</i>	\$55.30	
Rear reflector RH <i>X</i>	\$55.30	
Rear tail light LH <i>X</i>	\$231.60	
Rear tail light RH <i>?</i>	\$231.60	
Rear panel <i>repair</i>	\$655.10	
Labour to dismantle & install with glass	\$1,200.00	<i>800</i>
Spray Painting	\$1,000.00	<i>800</i>
Number Plate <i>ca/</i>	\$30.00	
Number Plate Holder <i>de/</i>	\$25.00	

Company Name: LKK AUTO

Name of Surveyor: RASUL

Contact Number: 90010068

Date of Survey: 06/02/2020 @ 1430

*45 / 7 days
Ready after repair*