

143100 TORCH

ESTIMATE FOR VEHICLE NUMBER: SJE7377Y

ITEM	ESTIMATION COST	REMARKS
Rear door <i>bt</i>	\$1,006.50	
Rear tyre cover <i>bro</i>	\$675.60	
Rear bumper <i>de</i>	\$421.30	
Rear reflector LH <i>X su</i>	\$55.30	X
Rear reflector RH <i>X su</i>	\$55.30	X
Rear tail light LH <i>X su</i>	\$231.60	X
Rear tail light RH <i>? X su</i>	\$231.60	X
Rear panel <i>repair bt</i>	\$655.10	
Labour to dismantle & install with glass	\$1,200.00	<i>800 } 850</i>
Spray Painting	\$1,000.00	<i>800 } 1600/1650</i>
Number Plate <i>ca</i>	\$30.00	
Number Plate Holder <i>de</i>	\$25.00	<i>S/N - 55</i>

2758.50
258
2068.87

Compay Name: LKK AUTO
 Name of Surveyor: RASUL
 Contact Number: 90010068
 Date of Survey: 06/02/2020 @ 1430

*45/7 days
Resy after repair*

2068.87

1650.00

55.00

3773.87

15%

3207.78

45-3200

7 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: