

SJE : _____
 Date of Survey : _____
 Date of ReSurvey: _____ After-Paint: _____
 Contacts : _____

Vehicle Nos : **SJD 9924 K**
 Model : Honda FIT
 Year : _____
 Chassis No : 2008

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$	
1	Tailgate	1	\$ 984.20	\$ 796.60 984.20	DDV
2	Tailgate logo	1	\$ 95.40	\$ 42.00 95.40	NECV
3	Tailgate inner lock	1	\$ 288.60	\$ 232.40 288.60	JANV
4	Tailgate striker	1	\$ 48.90	\$ 48.90	NDX
5	Tailgate weatherstrip	1	\$ 165.60	\$ ✓ 165.60	TNV
6	Tailgate inner trim board	1	\$ 296.30	\$ 192.30 296.30	DLV
7	Tailgate inner handle	1	\$ 36.00	\$ 36.00	NDX
8	Tailgate outer garnish	1	\$ 198.00	\$ 120.60 198.00	CUTV
9	Tailgate no plate lamp	2	\$ 88.50	\$ 177.00	NDX
10	Tailgate solenoid switch	1	\$ 235.00	\$ 235.00	XND
11	Tailgate windscreen	1	\$ 1,124.00	\$ 1,124.00	NDX
12	Tailgate windscreen moulding	1	\$ 90.50	\$ ✓ 90.50	NECV
13	Rear bumper	1	\$ 856.90	\$ 566.30 856.90	DDV
14	Rear bumper side retainer	2	\$ 48.60	\$ ✓ 97.20	NECV
15	Rear bumper bracket	2	\$ 39.60	\$ 79.20	XNSP
16	Rear end panel	1	\$ 525.60	\$ 422.50 525.60	?DDV
17	Rear end panel top garnish	1	\$ 124.80	\$ ✓ 124.80	DLV
18	Rear bumper lower lid	1	\$ 368.00	\$ 368.00	NSPX
19	Rear bumper reflector	2	\$ 194.00	\$ 388.00	NSPX
20	Rear lower lid garnish	3	\$ 65.00	\$ 195.00	NSPX
21	Taillamp rh	1	\$ 684.50	\$ 610.00 684.50	?BRV
22	Taillamp lower bracket rh	1	\$ 87.00	\$ 87.00	XNSP
23	Taillamp lh	1	\$ 684.50	\$ 610.00 684.50	?BRV
24	Taillamp bracket lh	1	\$ 87.00	\$ 87.00	XNSP
25	Exhaust pipe	1	\$ 728.20	\$ 728.20	}NDX
26	Exhaust pipe mounting	2	\$ 58.00	\$ 116.00	
27	Exhaust pipe heat shield	1	\$ 156.00	\$ 156.00	
Parts Sub Total :				\$ 4070.80 8,917.40	
20% Discount				\$ 814.16 1,783.48	
PARTS TOTAL :				\$ 3256.64 7,133.92	

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$	
1	Sundries	1	\$ 60.00	\$ 60.00	NNX
2	Tailgate inner trim board clips	1	\$ 50.00	\$ 30.00 50.00	NEC
3	Tailgate outer garnish clips	1	\$ 50.00	\$ 30.00 50.00	
4	Tailgate windscreen clips	1	\$ 50.00	\$ 30.00 50.00	
5	Tailgate primer and cleaner	1	\$ 80.00	\$ 80.00	NNX
6	Tailgate windscreen sealant	1	\$ 100.00	\$ 40.00 100.00	NEC
7	Rear no plate with cover	1	\$ 80.00	\$ 50.00 80.00	BT
8	Rear bumper reverse sensor	2	\$ 200.00	\$ 200.00 400.00	4UTV
9	Rear bumper clips	1	\$ 50.00	\$ 30.00 50.00	NECV
10	Reverse camera	1	\$ 350.00	\$ 250.00 350.00	?4UTV
11	Rear end panel sealant	1	\$ 100.00	\$ 30.00 100.00	?NECV
12	Taillamp clips	1	\$ 50.00	\$ 30.00 50.00	NEC
13	Rear end panel top garnish clips	1	\$ 50.00	\$ 30.00 50.00	NEC
14	Taillamp inner seal	2	\$ 80.00	\$ 160.00	NNX
15	Towing cap	1	\$ 100.00	\$ 60.00 100.00	DL
SPECIAL NETT TOTAL :				\$ 810.00 1,730.00	

Nos.	LABOUR	S\$
1	R&R tailgate component	\$ 80.00 100.00
2	R&R rear windscreen	\$ 120.00 250.00
3	R&R exhaust pipe assy	\$ 250.00
4	R&R reverse sensor with drill hole in bumper	\$ 60.00 120.00
5	R&R reverse camera	\$ 60.00 150.00
6	Disconnect wire harness to facilitate repair, reconnect and check function	\$ 50.00 100.00
7	Panel beat	\$ 1,600.00 1,600.00
8	Rust proofing	\$ 60.00 150.00
9	Spray painting	\$ 800.00 1,600.00
LABOUR TOTAL :		\$ 2 230.00 4,320.00

Survey 4/2/2020 5/2/2020 Resurvey
 1500hrs 1500hrs
 Taim Min Taim Min
 Lump sum repair
 Repair days 7

PARTS TOTAL : \$ 3256.64 7,133.92
 SPECIAL NETT TOTAL : \$ 810.00 1,730.00
 LABOUR TOTAL : \$ 2230.00 4,320.00
 GRAND TOTAL : \$ 6296.64 13,183.92

@ 20% 1259.33
 5037.3

4/5 (5000/2)

Taim Min
 14/2/2020

ANK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: