

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 28350

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0138/2020/NS
Date : 6-Feb-20

Vehicle NOT IN workshop. Please arrange for survey.

Your insured veh no : SLZ 7309 K

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Chong Guo Qian
Address : 547 East Coast Road
#05-17
Singapore 429073
Telephone : (HP) +65 96263470
Type of Claim : Third Party Claims
Policy No. : 1800092412-01
Vehicle No : **SME 418 Z**
Model Code : A6 1.8 TFSI S TRONIC
Model / Year : 10/8/2018
Engine No : CYG 023783
Chassis No : WAUZZZ4G4JN046604
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 3-Feb-20
Place of Accident : KK Women's And Children's Hospital

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SME 418 Z

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$	480.00	✓
2	To dismantle and renew front bumper, lhs front fender and headlight. Re-organise front crash management components. Reinstall all parts removed.	500 \$	2,800.00	1250
3	To repray front bumper and lhs front fender.	550 \$	1,900.00	1100
4	To renew lhs front ACC control unit and carry out calibration.	S/N \$	280.00	✓
SUB TOTAL LABOUR CHARGES		:	<u>\$ 5,460.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SME 418 Z

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
5	To renew lhs front wheelhub and bearing.	S/N \$	280.00	X {nn
6	To renew lhs front rim. Carry out wheel alignment.	S/N \$	280.00	X
7	To carry out diagnostic check.	S/N \$	192.00	✓
TOTAL LABOUR CHARGES		:	<u><u>\$ 6,212.00</u></u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SME 418 Z

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER / Cut	\$ 2,877.00	
2	FRONT BUMPER GRILLE - LOWER CENTRE X NN	\$ 120.00	
3	LOCKING CLIP ? 14	\$ 52.00	
4	FRONT BUMPER FIXING PARTS ?	\$ 511.00	
5	FRONT BUMPER ADAPTER - LH ? mis X NN	\$ 36.00	
6	FRONT BUMPER AIR GUIDE GRILLE - LH/RH	\$ 537.00	
7	FRONT BUMPER COVER - LH ?	\$ 48.00	
8	FRONT PARKING AID SENSOR - OUTER X NN	TBC	
9	DISTANCE REGULATION CONTROL UNIT ?	\$ 5,553.00	
10	RADAR SENSOR COVER FRAME ?	\$ 12.00	
11	FRONT BUMPER GUIDE PIECE - LH / dl	\$ 36.00	
12	FRONT BUMPER BRACE - LH ?	\$ 28.00	
13	FRONT FENDER - LH / Bul	\$ 1,310.00	
14	FRONT FENDER ATTACHMENT PARTS ?	\$ 97.00	
15	STONE GUARD FILM - LH / Mc	\$ 114.00	
16	FRONT FENDER BRACE - LH ?	\$ 90.00	
17	WHEEL HOUSING LINER - LH ?	\$ 259.00	
18	WHEEL HOUSING LINER ATTACHMENT PARTS X NN	\$ 69.00	
19	FRONT WHEEL SPOILER - LH ?	\$ 249.00	
20	LED HEADLIGHT - LH / CFA	\$ 8,888.00	
SUB TOTAL SPARE PARTS		: \$ 20,886.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SME 418 Z

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
21	HEADLIGHT MOUNTING - LH ?	\$ 112.00	
22	TURN SIGNAL POWER MODULE ?	\$ 532.00	
23	DIPPED BEAM POWER MODULE ?	\$ 524.00	
24	HEADLAMP ASSEMBLY SPACER ? 2	\$ 79.00	
25	HEADLAMP ADJUSTMENT ELEMENT ?	\$ 43.00	
26	LIFT CYLINDER - LH ?	\$ 223.00	
27	HEADLIGHT WASHER COVER CAP - LH X	\$ 54.00	
28	FRONT ALUMINIUM RIM - LH X	\$ 741.00	
29	WHEEL HUB X	\$ 441.00	
30	WHEEL BEARING X	\$ 542.00	
31	SUNDRIES ?	\$ 400.00	

TOTAL SPARE PARTS : \$ 24,577.00

TOTAL LABOUR CHARGES : \$ 6,212.00

GRAND TOTAL : \$ 30,789.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

4 Days.

Eno Q:af - 82880282

10/2/2020

before paint & photos.

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant