

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 28080

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0131/2020/NS
Date : 3-Feb-20

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Kwok Tian Chee
Address : Blk 6 Lorong Lew Lian
#03-120
Singapore 531006
Telephone : HP +65 98529823
Type of Claim : Own Damage Claims
Policy No. : 1800088216
Vehicle No : **SJJ 3920 D**
Model Code : Audi A3 Sedan 1.0 TFSI 8V
Model / Year : Jul-18
Engine No : CHZ 466306
Chassis No : WAUZZZ8V9J1069554
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 31-Jan-20
Place of Accident : Bishan Flyover Towards Bradell

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJJ 3920 D

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓	✓
2	To dismantle and renew front bumper assy, bonnet and lhs headlight. Re-organise front crash management components. Reinstall all parts removed.	\$ 2,450.00 1250	✓
3	To respray front bumper and bonnet.	\$ 1,800.00 1100	✓
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	✓
SUB TOTAL LABOUR CHARGES		: \$ 4,802.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJJ 3920 D

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	Remarks
1	FRONT BUMPER <i>Regis</i>	\$ 1,894.00	+
2	FRONT BUMPER GRILLE - CENTRE <i>could</i>	\$ 151.00	✓ 120.40
3	RADIATOR GRILLE <i>could</i>	\$ 1,338.00	✓ 1076.40
4	RADIATOR GRILLE CLOSING ELEMENT <i>could</i>	\$ 180.00	✓ 143.60
5	AIRCON STICKER <i>3 per</i>	NEC \$ 7.00	✓ 5.36
6	CAUTION SIGN STICKER	NEC \$ 13.00	✓ 10.24
7	FRONT BUMPER COVER ?	\$ 115.00	?
8	FRONT BUMPER FOAM FILLER PIECE ?	\$ 178.00	?
9	FRONT BUMPER SIDE REINFORCEMENT BEAM ?	\$ 681.00	?
10	BONNET <i>Dented</i>	\$ 2,988.00	✓ 2390.40
11	BONNET ATTACHMENT PARTS ?	\$ 155.00	?
12	BONNET SAFETY CATCH <i>new</i>	\$ 84.00	✓
13	BONNET STRIKER - LH / RH <i>new</i>	2 \$ 208.00	+
14	BONNET EDGE PROTECTION <i>could</i>	\$ 26.00	✓ 20.80
15	BONNET CATCH HOOK <i>new</i>	\$ 60.00	+
16	LED HEADLIGHT - LH <i>could</i>	\$ 5,193.00	✓ 4154.40
17	FRONT NO PLATE <i>Dented</i>	S/N \$ 40.00	✓ 40
18	SUNDRIES ?	\$ 300.00	?

TOTAL SPARE PARTS CHARGES	:	\$ 13,611.00
TOTAL LABOUR CHARGES	:	\$ 4,802.00
GRAND TOTAL	:	\$ 18,413.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

: Adrian

Surveyed Date

: 02/02/20

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

: are authorised, 05 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant