

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 28080

## Telefax

|            |   |                    |
|------------|---|--------------------|
| Estimate   | : | Accident Repairs   |
| Workshop   | : | Ubi Road 1         |
| Contact No | : | 6366 2323          |
| Fax No     | : | 6841 1183          |
| Reference  | : | PA/OD/0131/2020/NS |
| Date       | : | 3-Feb-20           |

**Vehicle NOT IN workshop. Please arrange for survey**

## AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

**Attn: Mr. Adrian Ling - Motor Claims Dept**

**Tel: 6841 0055 - Fax: 6256 4315**

|                   |   |                                                      |
|-------------------|---|------------------------------------------------------|
| Owner's Name      | : | Ms Kwok Tian Chee                                    |
| Address           | : | Blk 6 Lorong Lew Lian<br>#03-120<br>Singapore 531006 |
| Telephone         | : | HP +65 98529823                                      |
| Type of Claim     | : | Own Damage Claims                                    |
| Policy No.        | : | 1800088216                                           |
| Vehicle No        | : | <b>SJJ 3920 D</b>                                    |
| Model Code        | : | Audi A3 Sedan 1.0 TFSI 8V                            |
| Model / Year      | : | Jul-18                                               |
| Engine No         | : | CHZ 466306                                           |
| Chassis No        | : | WAUZZZ8V9J1069554                                    |
| Mileage           | : | -                                                    |
| Date In           | : | -                                                    |
| Estimated By      | : | Johnny Boo / Allan Wu                                |
| Accident Date     | : | 31-Jan-20                                            |
| Place of Accident | : | Bishan Flyover Towards Bradell                       |

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SJJ 3920 D

| S/N                      | Nature of Jobs                                                                                                                                  | Estimated Charges    | Surveyor's Recommendations |
|--------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------|----------------------|----------------------------|
| 1                        | To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.               | S/N \$ 360.00 ✓      |                            |
| 2                        | To dismantle and renew front bumper assy, bonnet and lhs headlight. Re-organise front crash management components. Reinstall all parts removed. | \$ 2,450.00 1250 ✓   |                            |
| 3                        | To respray front bumper and bonnet.                                                                                                             | \$ 1,800.00 1100 ✓   |                            |
| 4                        | To carry out diagnostic check.                                                                                                                  | S/N \$ 192.00 ✓      |                            |
| SUB TOTAL LABOUR CHARGES |                                                                                                                                                 | : <u>\$ 4,802.00</u> |                            |

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SJJ 3920 D

| S/N | Parts Description                                   | Damage Parts & Prices |          | Remarks   |
|-----|-----------------------------------------------------|-----------------------|----------|-----------|
|     |                                                     | S/NETT                |          |           |
| 1   | FRONT BUMPER <i>Regis</i>                           | \$                    | 1,894.00 | +         |
| 2   | FRONT BUMPER GRILLE - CENTRE <i>crushed</i>         | \$                    | 151.00   | ✓ 120.40  |
| 3   | RADIATOR GRILLE <i>crushed</i>                      | \$                    | 1,338.00 | ✓ 1076.40 |
| 4   | RADIATOR GRILLE CLOSING ELEMENT <i>crushed</i>      | \$                    | 180.00   | ✓ 142.60  |
| 5   | AIRCON STICKER <i>Yes</i>                           | NEC \$                | 7.00     | ✓ 5.36    |
| 6   | CAUTION SIGN STICKER                                | NEC \$                | 13.00    | ✓ 10.24   |
| 7   | FRONT BUMPER COVER <i>Not Nec</i>                   | \$                    | 115.00   | X         |
| 8   | FRONT BUMPER FOAM FILLER PIECE <i>Not Nec</i>       | \$                    | 178.00   | X         |
| 9   | FRONT BUMPER SIDE REINFORCEMENT BEAM <i>Not nec</i> | \$                    | 681.00   | X         |
| 10  | BONNET <i>Dented</i>                                | \$                    | 2,988.00 | ✓ 2390.40 |
| 11  | BONNET ATTACHMENT PARTS <i>Not nec</i>              | \$                    | 155.00   | X         |
| 12  | BONNET SAFETY CATCH <i>new</i>                      | \$                    | 84.00    | X         |
| 13  | BONNET STRIKER - LH / RH <i>new</i>                 | 2 \$                  | 208.00   | ✓         |
| 14  | BONNET EDGE PROTECTION <i>crushed</i>               | \$                    | 26.00    | ✓ 20.80   |
| 15  | BONNET CATCH HOOK <i>new</i>                        | \$                    | 60.00    | +         |
| 16  | LED HEADLIGHT - LH <i>crushed</i>                   | \$                    | 5,193.00 | ✓ 4154.40 |
| 17  | FRONT NO PLATE <i>Dented</i>                        | S/N \$                | 40.00    | ✓ 40      |
| 18  | SUNDRIES <i>Not Nec</i>                             | \$                    | 300.00   | X         |

**TOTAL SPARE PARTS CHARGES**

: \$ **13,611.00**

**TOTAL LABOUR CHARGES**

: \$ **4,802.00**

**GRAND TOTAL**

: \$ **18,413.00**

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

: Adrian  
: 02/02/10  
:  
:  
:  
:  
: Not Authorised, 05 Days

|                                                                                                                                                                                                                                                                                                                                                                                |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <p>• This estimate is based on visual inspection of the affected vehicle.</p> <p>• Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.</p> <p>• For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.</p> <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Date:</p> |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|

## Please Note

: This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant