

* LKK RASMI 90010068

Kanchana

Reprint:5

C L Auto Pte Ltd

48 TOH GUAN ROAD EAST #02-125 ENTERPRISE HUB SINGAPORE 608586
 TEL: 6795 6125 FAX: 6795 0920 Email: vincent@clauto.com.sg
 RCB NO:198800292M

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY #07-16
 SINGAPORE 079120

TEL: 6419 3000 FAX: 6835 7416
 ATTN: Motor Claim Department

Your Ref No: GBF5476Y
 Claim Type: Third Party
 Accident Date: 30/01/2020

Estimate No: EST1900320
 Date: 05 Feb 2020
 Policy No: DMCG19011219
 Veh Reg No: GBF5476Y
 Make/Model: TOYOTA KDY231R-
 TLMKY DYNA
 Chassis No: JTFAT35Y60K206575
 Engine No: 1KD-FTV
 Reg. Date: 2016/

Estimate Repair Cost to Vehicle No :GBF5476Y

Description	Quantity	List Price S\$	Amount S\$
Special Net:			
1 DYNA STICKER <i>na</i>	1 PC	20.00 <i>10 s/n</i>	
2 BACK DOOR HINGES <i>bt - (CL) list price @ 120</i>	3 <i>PC</i>	360.00 <i>480.00</i>	
3 BACK DOOR LOCK RH <i>bt - (CL) list price</i>	1 PC	160.00 <i>list price 610</i>	
4 BACK DOOR STOPPER RH <i>cut - (CL) list price</i>	1 PC	90.00 <i>price 252</i>	
5 REAR FLOOR BOARD SUB-FRAME <i>cut X sue</i>	1 PC	800.00 X	<i>457.50</i>
6 BACK DOOR STICKER - 13PAX <i>na</i>	1 PC	12.00 <i>10 s/n</i>	
7 BACK DOOR STICKER - 70/KM/H <i>na</i>	1 PC	12.00 <i>10 s/n</i>	
8 REAR NUMBER PLATE <i>bt</i>	1 PC	45.00 <i>s/n</i>	
9 REVERSE SENSORS <i>short</i>	1 SET	280.00 <i>220 s/n</i>	
10 REVERSE CAMERA <i>cut</i>	1 SET	300.00 <i>150 s/n</i>	<i>s/n-44</i>
		2,199.00	2,199.00
List Price:			
11 BACK DOOR <i>bt</i>	1 PC	2,162.00 <i>1700</i>	
12 BACK DOOR TOYOTA STICKER <i>na</i>	1 PC	189.00	
13 REAR LAMP RH <i>sua</i>	1 PC	189.00	
14 REAR LAMP BRACKET RH <i>bt</i>	1 PC	112.00	
15 REAR NUMBER PLATE LAMP <i>X sue</i>	1 PC	90.00 X	
16 NUMBER PLATE BASE <i>bt</i>	1 PC	132.00	
17 EXHAUST TAIL-PIPE <i>- repair</i>	1 PC	760.00 X	
18 EXHAUST TAIL-PIPE MOUNTING <i>X sue</i>	1 PC	65.00 X	
		3,699.00	
	Less 25%	924.75	2,774.25
Labour Charges:			
19 TO REMOVE & REFIT REAR BACK DOOR, REAR RH TAILLAMP & BRACKETS &, NO. PLATE BASE. CUT/WELD REAR FLOOR BOARD SUB-FRAME.	1 PCS	1,400.00 <i>600</i>	
20 TO SPRAY PAINT BACK DOOR, REAR FLOOR BOARD SUB-FRAME, NO. PLATE BASED & TAILLAMP BRACKETS.	1 PCS	900.00 <i>600</i>	
21 RUST PROOFING	1 PCS	180.00 <i>60</i>	
22 TO REMOVE & REFIT REAR EXHAUST PIPE SILENCER.	1 PCS	120.00 <i>60</i>	
23 TO CHECK WIRING & CHECKING REAR REVERSE SENSOR AND CAMERA.	1 PCS	180.00 <i>80</i>	
		2,780.00	2,780.00

C L Auto Pte Ltd

48 TOH GUAN ROAD EAST #02-125 ENTERPRISE HUB SINGAPORE 608586
 TEL: 6795 6125 FAX: 6795 0920 Email: vincent@clauto.com.sg
 RCB NO:198800292M

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY #07-16
 SINGAPORE 079120

TEL: 6419 3000 FAX: 6835 7416
 ATTN: Motor Claim Department

Your Ref No: GBF5476Y
 Claim Type: Third Party
 Accident Date: 30/01/2020

Estimate No: EST1900320
 Date: 05 Feb 2020
 Policy No: DMC919011219
 Veh Reg No: GBF5476Y
 Make/Model: TOYOTA KDY231R-
 TLMKY DYNA
 Chassis No: JTFAT35Y60K206575
 Engine No: 1KD-FTV
 Reg. Date:

Estimate Repair Cost to Vehicle No :GBF5476Y

Description	Quantity	List Price	Amount
		SS	SS
		Total	SS 7,753.25

TOTAL: SINGAPORE DOLLAR SEVEN THOUSAND SEVEN HUNDRED FIFTY THREE AND CENTS TWENTY FIVE ONLY

For C L Auto Pte Ltd

AUTHORISED SIGNATURE

parts - 457.50
 1741.50
 s/w - 445.00
 L - 1400.00
 T - 4044.00
 20%
 3235.20
 H/s - 3,200
 6 days

Rasul
 Hp 90010068
 6 days
 H/s
 06/02/2020 @ 1010
 Reem after repair

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: