

C L Auto Pte Ltd

48 TOH GUAN ROAD EAST #02-125 ENTERPRISE HUB SINGAPORE 608586
 TEL: 6795 6125 FAX: 6795 0920 Email: vincent@clauto.com.sg
 RCB NO:198800292M

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY #07-16
 SINGAPORE 079120

TEL: 6419 3000 FAX: 6835 7416
 ATTN: Motor Claim Department

Your Ref No: GBF5476Y
 Claim Type: Third Party
 Accident Date: 30/01/2020

Estimate No: EST1900320
 Date: 05 Feb 2020
 Policy No: DMCG19011219
 Veh Reg No: GBF5476Y
 Make/Model: TOYOTA KDY231R-
 TLMKY DYNA
 Chassis No: JTFAT35Y60K206575
 Engine No: 1KD-FTV
 Reg. Date:

Estimate Repair Cost to Vehicle No :GBF5476Y

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
Special Net:			
1 DYNA STICKER <i>na</i>	1 PC	20.00 10	
2 BACK DOOR HINGES <i>bt (CL) list price</i>	3 PC	480.00	
3 BACK DOOR LOCK RH <i>bt (CL) list price</i>	1 PC	160.00	
4 BACK DOOR STOPPER RH <i>cut (CL) list price</i>	1 PC	90.00	
5 REAR FLOOR BOARD SUB-FRAME <i>cut X</i>	1 PC	800.00	
6 BACK DOOR STICKER - 13PAX <i>na</i>	1 PC	12.00 10	
7 BACK DOOR STICKER - 70/KM/H <i>na</i>	1 PC	12.00 10	
8 REAR NUMBER PLATE <i>bt</i>	1 PC	45.00	
9 REVERSE SENSORS <i>short</i>	1 SET	280.00 220	
10 REVERSE CAMERA <i>cut</i>	1 SET	300.00 150	
		2,199.00	2,199.00
List Price:			
11 BACK DOOR <i>bt</i>	1 PC	2,162.00	
12 BACK DOOR TOYOTA STICKER <i>na</i>	1 PC	189.00	
13 REAR LAMP RH <i>sc</i>	1 PC	189.00	
14 REAR LAMP BRACKET RH <i>bt</i>	1 PC	112.00	
15 REAR NUMBER PLATE LAMP <i>X</i>	1 PC	90.00	
16 NUMBER PLATE BASE <i>bt</i>	1 PC	132.00	
17 EXHAUST TAIL-PIPE <i>-repair</i>	1 PC	760.00	
18 EXHAUST TAIL-PIPE MOUNTING <i>X</i>	1 PC	65.00	
		3,699.00	
	Less 25%	924.75	2,774.25
Labour Charges:			
19 TO REMOVE & REFIT REAR BACK DOOR, REAR RH TAILLAMP & BRACKETS &, NO. PLATE BASE. CUT/WELD REAR FLOOR BOARD SUB-FRAME.	1 PCS	1,400.00 600	
20 TO SPRAY PAINT BACK DOOR, REAR FLOOR BOARD SUB-FRAME, NO. PLATE BASED & TAILLAMP BRACKETS.	1 PCS	900.00 600	
21 RUST PROOFING	1 PCS	180.00 60	
22 TO REMOVE & REFIT REAR EXHAUST PIPE SILENCER.	1 PCS	120.00 60	
23 TO CHECK WIRING & CHECKING REAR REVERSE SENSOR AND CAMERA.	1 PCS	180.00 80	
		2,780.00	2,780.00

C L Auto Pte Ltd

48 TOH GUAN ROAD EAST #02-125 ENTERPRISE HUB SINGAPORE 608586
 TEL: 6795 6125 FAX: 6795 0920 Email: vincent@clauto.com.sg
 RCB NO:198800292M

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY #07-16
 SINGAPORE 079120

TEL: 6419 3000 FAX: 6835 7416
 ATTN: Motor Claim Department

Your Ref No: GBF5476Y
 Claim Type: Third Party
 Accident Date: 30/01/2020

Estimate No: EST1900320
Date: 05 Feb 2020
Policy No: DMCG19011219
Veh Reg No: GBF5476Y
Make/Model: TOYOTA KDY231R-TLMKY DYNA
Chassis No: JTFAT35Y60K206575
Engine No: 1KD-FTV
Reg. Date:

Estimate Repair Cost to Vehicle No :GBF5476Y

Description	Quantity	List Price	Amount
		S\$	S\$
		Total	S\$ 7,753.25

TOTAL: SINGAPORE DOLLAR SEVEN THOUSAND SEVEN HUNDRED FIFTY THREE AND CENTS TWENTY FIVE ONLY

For C L Auto Pte Ltd

AUTHORISED SIGNATURE

Rasul
 Hp 90010068
 6 days
 4/3
 06/02/2020 @ 1010
 Ready after repair