

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG/AMK

Claim Type: Third Party

Accident Date: 01/02/2020

TP Veh Reg No: SLL5371R

Estimate No: ES2090104/AMK

Date: 04 Feb 2020

Policy No: GA100767

Veh Reg No: SLB7958M

Make/Model: TOYOTA WISH 1.8 CVT

Chassis No: ZGE206030123

Engine No: 2ZR1728464

Reg. Date: 22/04/2016

Estimate Repair Cost to Vehicle No :SLB7958M

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 REAR BUMPER	491.90	1 PC	491.90	✓
2 REAR BUMPER LH SIDE RETAINER	89.90	1 PC	89.90	✓
3 REAR BUMPER LH CORNER RETAINER	40.40	1 PC	40.40	✓
4 REAR BUMPER LH REINFORCEMENT BRACKET	48.44	1 PC	48.44	TX
5 REAR BUMPER CLIP	3.50	5 PC	17.50	✓
6 REAR TAILGATE	1,175.00	1 PC	1,175.00	✓
7 TAILGATE INNER LOCK	301.60	1 PC	301.60	✓
8 TAILGATE INNER RUBBER	302.60	1 PC	302.60	✓
9 TAILGATE OUTER CHROME	301.60	1 PC	301.60	✓
10 TAILGATE LOGO	66.15	1 PC	66.15	✓
11 TAILGATE EMBLEM 'VALVE MATIC'	35.49	1 PC	35.49	✓
12 TAILGATE LH NO PLATE LAMP	62.10	1 PC	62.10	TX
13 TAILGATE WINDSCREEN GLASS MOULDING	97.20	1 PC	97.20	✓
14 TAILGATE LH REFLECTOR	294.10	1 PC	294.10	✓
15 LH TAILLAMP	354.70	1 PC	354.70	✓
16 REAR END PANEL	453.90	1 PC	453.90	✓
17 REAR END PANEL INNER TOP GARNISH	253.19	1 PC	253.19	✓
18 REAR END PANEL ANTENNA	144.20	1 PC	144.20	✓
19 REAR LH TOOL SPONGE	175.50	1 PC	175.50	✓
			4,705.47	
		Less 25%	1,176.37	3,529.10
Special Net				
20 REVERSE SENSOR	200.00	1 SET	200.00	✓
21 REAR WINDSCREEN GLASS SEALANT	40.00	1 PC	40.00	✓
22 REAR NUMBER PLATE	35.00	1 PC	35.00	✓
			275.00	275.00
Labour				
23 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓
24 REMOVE & REFIX REAR BUMPER & ATTACHMENTS,PARKING SENSORS,TAILGATE & ATTACHMENTS,TAILLAMPS;TO CUT,WELD & RENEW REAR END PANEL;KNOCKING & REPAIR REAR LUGGAGE PANEL & REALIGN THE SAME	800.00	1 LA	800.00	✓
25 PUTTY & RESPRAY REAR BUMPER & PARKING SENSORS,TAILGATE,REAR END PANEL,REAR LUGGAGE PANEL,REAR LH FENDER & ALL AFFECTED AREAS	800.00	1 LA	800.00	✓
26 REMOVE & REFIX REAR GARNISHS,SEATS TO FACILITATE REPAIR	100.00	1 LA	100.00	✓

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG/AMK

Claim Type: Third Party

Accident Date: 01/02/2020

TP Veh Reg No: SLL5371R

Estimate No: ES2090104/AMK

Date: 04 Feb 2020

Policy No: GA100767

Veh Reg No: SLB7958M

Make/Model: TOYOTA WISH 1.8 CVT

Chassis No: ZGE206030123

Engine No: 2ZR1728464

Reg. Date: 22/04/2016

Estimate Repair Cost to Vehicle No :SLB7958M

Description	U/Price	Quantity	List Price	Amount
27 REMOVE & REFIX REVERSE CAMERA,RESET & REPOSITION	50.00	1 PC	<u>S\$</u> 50.00	<u>S\$</u>
28 RUSTPROOFING	90.00	1 LA	90.00	60
			1,960.00	1,960.00
Total				S\$ 5,764.10
Add GST @ 7%				403.49
Total Amount Payable				<u>S\$ 6,167.59</u>

* SURVEY VEHICLE AT ANG MO KIO WORKSHOP.

For Cheng Hoe Motor Pte Ltd

DORLYN LI

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: