

6742 3197

# FIRST AUTOWORKS

## Repair Estimate

Date: 4/02/2020

Reference: SGR8181E

To Whom It May Concern

Make: OPEL  
INSIGNIA

Dear Sir,

TP Budget Direct.  
Denise.

RE: VEHICLE :SGR8181E  
CHASSIS NO.: W0LGS5E58H1015733  
ENGINE NO.: B1162576HB4X0145

Name of insured : CNS Electrical Pte Ltd  
Date of accident.: 29/01/2020

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

### Parts

No.	Qty	Part Description	Price (SGD)
1	1	FRT BUMPER <i>Disturb</i>	1,500.00 ✓
2	1	FRT BUMPER GUIDE LEFT <i>2/11</i>	30.00 ✓
3	1	FRT BUMPER SUPPORT LEFT <i>1/11</i>	45.00 ✓
4	1	FRT FENDER LH <i>Reg</i>	570.00 ✓
5	1	FRT FENDER LINER LH <i>new</i>	120.00 ✓
6	1	FRT HEADLIGHT LH <i>crack</i>	980.00 ✓
7	1	FRT FOG LAMP LH <i>new</i>	230.00 ✓
8	1	FRT BUMPER ABSORBER, IMPACT, LOWER <i>crack new</i>	140.00 ✓
9	1	FRT BUMPER ABSORBER, IMPACT <i>new</i>	450.00 ✓
10	1	FRT BUMPER CENTRE SUPPORT <i>crack</i>	55.00 ✓
11	1	RH INSERT <i>new crack</i>	230.00 ✓
12	1	LH INSERT <i>new</i>	230.00 ✓
13	1	FLAP, TOWING LUG, FRT BUMPER <i>new</i>	90.00 ✓
			<b>Parts Total: 4,670.00</b>
			<b>Less 10%: 467.00</b>
			<b>Total : 4,203.00</b>

2840

2556

### Labour

No.	Labour Description	Price (SGD)
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	2800.00 <i>650.</i>
2	Carry out spray painting on accident affected area. ( Frt bumper & Frt RH Fender )	2500.00 <i>550.</i>
3	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	150.00 <i>50.</i>
4	To conduct 4 wheel alignment	180.00 ✓
5	To conduct head light alignment <i>1750</i>	130.00 ✓
<b>Labour Total :</b>		<b>5,760.00</b>

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 (South Wing) Next to Vicom Building, Singapore 415933 Tel : 6844 1985 Fax : 6844 5185

**Other**

<u>No.</u>	<u>Other Description</u>	<u>Price (SGD)</u>
1	FRT BUMPER CLIP SET <i>Ne</i>	50.00 ✓
		50
	Other Total :	50.00

Total : \$10,013.00  
Gst (7%) : \$700.91  
**GRAND TOTAL: \$10,713.91**

**NB:** THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS. EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YC WILL BE INFORMED PRIOR TO ACTION TAKEN. **PARTS PRICES ARE SUBJECT TO CHANGES.**

Yours faithfully



Service Advisor  
Ronnie Tan  
DID: 6844 1985 Fax:6844 5185

*Adrian Lj*  
*R/B 05/02/20.*  
*03 Days.*

*total: 3856.*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: