



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2100890

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 09/02/2021
Reference CC6/FCI20002009/Uea3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. FBE 7823X
Insured Veh. SHC 901P
Claim No. D20001033MFSH
Policy No. D-18088937MFSH
Accident Date 31/01/2020
Inspection Date 05/02/2020

Description	Total
Survey Inspection	371.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	371.00
GST (7%)	25.97
Grand Total	396.97

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC6/FCI20002009/Uea3q2 Date: 09/02/2021 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 901P	Veh. Inspected	FBE 7823X	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D20001033MFSH	Excess (\$)	0.00	
Assign From	MERINA	Assign Date	05/02/2020	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CB400	c.c	399	
Engine No.	HIDDEN	Year of Reg.	2002	
Chassis No.	NC391034856	Colour	BLUE	
Odometer	-	Steering	AFFECTED	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	120/60 R17	BRIDGESTONE	6 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	160/60 R17	BRIDGESTONE	6 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	31/01/2020	Inspection Date	05/02/2020	
Survey held at	EROFIA MOTOR TRADING PTE LTD 1 KAKI BUKIT AVENUE 6 #02-62 SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBE 7823X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT FENDER	TO REPAIR SEE LABOUR	196.00	-
1	WINDSHIELD	SCRATCHED	185.00	185.00
1	HEADLAMP	SERVICEABLE	380.00	-
1	HEADLAMP BRACKET	NOT NECESSARY	65.00	-
1	FRONT BRAKE DISC	NOT NECESSARY	560.00	-
1	FRONT RIM SHAFT	SERVICEABLE	68.00	-
1	FRONT SPORT RIM	DENTED	1,100.00	885.00
1	METER	CRACKED	1,880.00	925.00
1	HANDLE-BAR	BENT	145.00	145.00
1	HANDLE-BAR END	CUT	30.00	30.00
1	SET HAND-GRIP	NOT NECESSARY	80.00	-
2	SIDE MIRRORS	CUT	190.00	190.00
1	CLUTCH LEVER	SCRATCHED	58.00	58.00
1	BRAKE LEVER	SCRATCHED	65.00	65.00
2	FRONT SIGNALS	CRACKED	352.00	352.00
1	FUEL TANK	TO REPAIR SEE LABOUR	1,415.00	-
1	FRONT FOOTREST-L/H	CUT	75.00	75.00
1	FRONT FOOTREST BRACKET	SERVICEABLE	245.00	-
1	GEAR PEDAL	NOT NECESSARY	95.00	-
1	REAR FOOTREST-L/H	CUT	70.00	70.00
1	TOP COWLING	CRACKED	280.00	280.00
1	REAR SIGNAL-L/H	CRACKED	176.00	176.00
1	REAR TAILBOARD	TO REPAIR SEE LABOUR	335.00	-
1	REAR FENDER	TO REPAIR SEE LABOUR	95.00	-
1	REAR TAILLAMP	NOT NECESSARY	280.00	-
1	FRT FORK OUTER R/H	CRACKED	785.00	785.00
	LESS 10% DISCOUNT		-920.50	-422.10
			8,284.50	3,798.90

Report Ref No. CC6/FCI20002009/Uea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	SET NUMBER PLATE (SN)	NOT NECESSARY	28.00	-
2	FORK OILS (SN)	NECESSARY	30.00	10.00
2	FORK OIL SEALS (SN)	NECESSARY (1 PC ONLY)	56.00	28.00
1	SET STEERING CONE (SN)	NECESSARY	80.00	80.00
1	E.R.P IU (SN)	SERVICEABLE	175.00	-
1	REAR BOX "KAPP" (SN)	CUT	750.00	600.00
1	REAR BOX BRACKET (SN)	BENT	100.00	100.00
1	SET ENGINE CRASH BAR (SN)	BENT	350.00	350.00
			1,569.00	1,168.00
	<u>LABOUR</u>			
	TO PROVIDE TOWING SERVICE.		50.00	35.00
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING.	NOT NECESSARY	80.00	-
	TO PROVIDE LABOUR.INCLUSIVE OF THE REPAIR OF FRONT FENDER,FUEL TANK,REAR TAILBOARD AND REAR FENDER.		480.00	350.00
	TO RESPRAY PAINTING.		500.00	280.00
			1,110.00	665.00
GRAND TOTAL			10,963.50	5,631.90
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,500.00

Report Ref No. CC6/FCI20002009/Uea3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. FBE 7823X

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. FBE 7823X

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

