

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

First

Owner : Muhammad Nifail Bin Zainal

Accident Date : 31-Jan-20

Vehicle No : FBE 7823 X

Vehicle Model : Honda CB400

Estimated Repair Costs

Qty	Description	Amount S(\$)
	<u>List Items</u>	
1	Front fender	\$ 12 196.00 X
1	Windshield	\$ 50 185.00 ✓
1	Headlamp	\$ 50 380.00 X
1	Headlamp bracket	\$ 17 65.00 X
1	Front brake disc	\$ 17 560.00 X
1	Front rim shaft	\$ 80 68.00 X
1	Front sport rim	\$ 12 1,100.00 ✓
1	Meter	\$ 925 1,880.00 ✓
1	Handle-bar	\$ 14 145.00 ✓
1	Handle-bar end	\$ 17 30.00 ✓
1	Hand-grip (1 set)	\$ 17 80.00 X
2	Side mirrors	\$ 190 190.00 ✓
1	Clutch lever	\$ 58 58.00 ✓
1	Brake lever	\$ 65 65.00 ✓
2	Front signals	\$ 352 352.00 ✓
1	Fuel tank	\$ 1,415 1,415.00 X
1	Front footrest -L/H	\$ 75 75.00 ✓
1	Front footrest bracket	\$ 245 245.00 X
1	Gear pedal	\$ 95 95.00 X
1	Rear footrest -L/H	\$ 70 70.00 ✓
1	Top cowling	\$ 280 280.00 ✓
1	Rear signal -L/H	\$ 176 176.00 ✓
1	Rear tailboard	\$ 335 335.00 X
1	Rear fender	\$ 95 95.00 X
1	Rear taillamp	\$ 17 280.00 X
		\$ 8,420.00
		\$ 842.00
		\$ 7,578.00

del fork outer R/H one ✓ 3785
Less 10%

not Added
LH
2/3 \$4500
4 am
5/2/20
The repairer

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting .
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

c/f: \$ 7,578.00

Special Nett Items

1	Number plate (1 set)	\$ 11	28.00	X
2	Fork oils	\$ 11	30.00	10
2	Fork oil seals	\$ 11	56.00	112
1	Steering cone (1 set)	\$ 11	80.00	✓
1	E.R.P IU	\$ 11	175.00	X
1	Rear box "KAPPA"	\$ 11	750.00	600
1	Rear box bracket	\$ 11	100.00	✓
1	Engine crash bar (1 set)	\$ 11	350.00	✓
		\$	1,569.00	

S/No.

Labour

1	To provide towing service.	\$	50.00	35
2	To check wiring and reset headlamp focusing	\$	11	80.00 X
3	To provide labour.	\$	480.00	350
4	To respray painting.	\$	500.00	280
		\$	1,110.00	

Grand Total

\$ 10,257.00


EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

5831-9
450152