



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 1067P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	890.00	890.00
1	REAR BUMPER CENTER BRACKET	NOT NECESSARY	138.50	-
2	REAR BUMPER SIDE RETAINER LH & RH @ \$50.00	BROKEN	100.00	100.00
2	REAR BUMPER SIDE REFLECTOR LH & RH @ \$45.20	NOT NECESSARY	90.40	-
1	REAR BUMPER TOW COVER	NOT NECESSARY	28.60	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	210.00	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	506.00	-
1	REAR END PANEL INNER GARNISH	NOT NECESSARY	191.00	-
	LESS 10% DISCOUNT		-215.45	-99.00
			1,939.05	891.00
<u>SPECIAL NETT ITEMS</u>				
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	60.00	-
1	REAR BUMPER CLIPS (SN)	NECESSARY	60.00	30.00
1	REAR END PANEL INNER GARNISH CLIPS (SN)	NOT NECESSARY	50.00	-
1	REVERSE SENSOR (SN)	SHORTED	300.00	200.00
			470.00	230.00
<u>LABOUR</u>				
	TO DISMANTLE, REPLACE& PANEL BEATING AFFECTED PARTS FOR REAR PORTION. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		800.00	300.00
	TO SPRAY PAINT ON AFFECTED AREAS FOR REAR PORTION.		800.00	300.00
	TO REMOVE / REFIT REAR UPHOLSTERY & ETC.	NOT NECESSARY	180.00	-
	TO REMOVE / REINSTALL REVERSE SENSORS.		100.00	30.00
	TO CHECK WIRING FOR REAR PORTION.		50.00	30.00
	TO APPLY ANTI-RUST ON AFFECTED AREAS.		100.00	30.00
			2,030.00	690.00
GRAND TOTAL			4,439.05	1,811.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,450.00



Report Ref No. CC4/FCI20002012/Eda3s2

A black ink signature of Chen Tsue Yee, consisting of several fluid, overlapping strokes.

CHEN TSUE YEE

Automotive Assessor

A black ink signature of Ho Leong Chuan, featuring a stylized 'H' and 'L' with a small '2' below.

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.