



華平汽車服務 HWA PENG AUTO SERVICE (1996)

70 Woodlands Industrial Park E9 Singapore 757836

TEL: 6365 6100 FAX: 6365 6101

Spray Painting • Panel Beating • Body Repair • Engine Tuning • Towing Service • Insurance Claim • L.T.A. Inspection Service
Co. Reg 52823719E

ESTIMATE REPORT

TW Premium Automobile Pte Ltd
C/o 70 Woodlands Industrial Park E9
Singapore 757836

Vehicle Number : SLR1067P
Make And Model : Mitsubishi Lancer
Date of Accident : 21 January 2020

S/No	Parts	QTY	Unit Price	List Price
1	Rear bumper ✓ DEF	1		\$ 890.00 ✓
2	Rear bumper center bracket × NN	1		\$ 138.50 ×
3	Rear bumper side retainer LH & RH ✓ BR	2	\$ 50.00	\$ 100.00 ✓
4	Rear bumper side reflector LH & RH × NN	2	\$ 45.20	\$ 90.40 ×
5	Rear bumper tow cover × NN	1		\$ 28.60 ×
6	Rear bumper reinforcement × NN	1		\$ 210.00 ×
7	Rear end panel × Repair	1		\$ 506.00 ×
8	Rear end panel inner garnish × NN	1		\$ 191.00 ×
		990		\$ 2,154.50
		-10%	Less 10%	\$ 215.45
		891	Total	\$ 1,939.05

Special Nett Item

9	Rear number plate		\$ 60.00 × NN
10	Rear bumper clips		\$ 60.00 30 ✓
11	Rear end panel inner garnish clips		\$ 50.00 × NN
12	Reverse sensor	230	\$ Short 300.00 200 ✓
			Total \$ 470.00

Labour & Misc Charges

To dismantle, replace & panel beating affected parts for rear portion.	\$ 800.00 300 ✓
To spray paint on affected areas for rear portion.	\$ 800.00 300 ✓
To remove/refit rear upholstery & etc.	\$ 180.00 ×
To remove/reinstall reverse sensors.	\$ 100.00 30 ✓
To check wiring for rear portion.	\$ 50.00 30 ✓
To apply anti-rust on affected areas.	\$ 100.00 30 ✓
	690
	Total \$ 2,030.00

Grand Total : \$ 4,439.05

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Steve (LKK)
05/02/20
Without Prejudice
2-3 repair days
L/S
Resurvey After Spray

P - 891
N - 230
L - 690
1811
L/S - 1448.80
= 1450

Acknowledged by Repairer

Signature: _____

Date: _____