

14 K



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road, Eunos Spring

#08-1339 Singapore 470130

Tel: 9450 7920

zoomautowerks@gmail.com

Car Number: GBD9996Y

Date: 05/02/2020

Model : Toyota Dyna

Damaged Area: (Rear Portion Damaged)

Repairer Estimation Cost of Repair :

Supplementary may be included during the cost of repair :

Parts / Material :

- 1 Rear Tailgate 1645-10
- 2 Rear Tailgate Latch
- 3 Rear Tailgate Side Member with Rub
- 4 Rear Tailgate Hinges
- 5 Rear Tailgate Lower Member 566-10
- 6 Taillamps 250-20
- 7 Taillamps Bracket
- 8 Rear Number Plate Bracket
- 9 Rear Number Plate Lamp
- 10 Rear Tyre Carrier

Quantity

	\$ 20/serf	1,945.20	
\$195.00 X 2 pcs	\$ 12	390.00	X
\$268.00 X 2 pcs	\$ 12	536.00	X
\$68.00 X 2 pcs	\$ 12	136.00	X
	\$ Serf	749.40	
\$375.00 X 2 pcs	\$ 1/serf	750.00	1PC
\$119.20 X 2 pcs	\$ 12	238.40	X
	\$ Serf	155.00	
	\$ 12	175.00	X
	\$ 12	385.00	X

Parts : \$ 5,460.00

Less Parts 25% : \$ 1,365.00

Total Parts : \$ 4,095.00

Special Net Items :

- 1 set
- Rear End Step Panel
 - Rear reverse sensor
 - Rear Dyna Sticker
 - 13 PAX Sticker
 - 70 KM/H Sticker
 - Rear Advertisement Sticker
 - Rear Number Plate

\$ Serf	680.00	250
\$ Shook	750.00	200
\$ 12	70.00	45
\$ 12	35.00	10
\$ 12	35.00	10
\$ 12	450.00	X
\$ Serf	35.00	15

Total S/N Parts : \$ 2,055.00

Labour :

- To Remove, Repair & Renew Rear Affected Accident Areas
- To Putty, Spray Paint on Affected Accident Areas
- To Check & Re-Connect all electrical wiring
- To Rust Proof Affected Areas

\$	1,200.00	680
\$	1,000.00	600
\$	50.00	30
\$	200.00	50

Total Labour : \$ 2,450.00

TOTAL PARTS : \$ 4,095.00

TOTAL SPECIAL NET ITEM : \$ 2,055.00

TOTAL LABOUR : \$ 2,450.00

TOTAL REPAIR COST : \$ 8,600.00

DATE OF SURVEY / INSPECTED:

RECOMMENDED PART BY PART / LUMP SUM :

RECOMMENDED NUMBER OF DAYS :

SURVEY BY / SURVEYOR FIRM :

RE-SURVEY DISMANTLE PARTS / BEFORE PAINT / AFTER PAINT :

Acknowledged by Repairer

Signature:

Date:

Not Authorised
deal
2/5 \$3050/
Hays.

P-2616-4
257
196230
385230
2-81