

ASS. REC. BY:

REF: CS/CT1 20002017/USF312

Special Instruction:

Surveyor: MarcusASSIGNMENT (Office)From (Person): Adeline chng of CT1 Date/Time: 5.2.2020 3:55pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJD 4635C Insured: SKD 658Bat Workshop m/s M/S Automobile Hub Tel: 97864483of 1 Kater Bukit Ave 6 #02-11 AutobayPolicy No: _____ Claim No: SJM 2017 200633

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 3.2.2020
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 5/2/2020 4:00pm Person Contacted: Mr Lim H.O.D. Endorsement: _____Vehicle IN/OUT

Date/Time	Action/Instruction (<input checked="" type="checkbox"/>) Estimate
	<u>SJD 4635C - NA / FWD 2000 1776 / 44</u> <u>DOA - 03/02/2020</u>
	<u>SKD 658B - NA / FWD 2000 1776 / 44</u> <u>DOA - 03/02/2020</u>

(08/11/13) wef

REF:

ASS. REC. BY: *marcus*

ASSIGNMENT

From: Date:

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Yr Regn:

Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In Order / Jammed / Leaked / Burnt orBrake: ☒ In Order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

BS / DUN / EXNOVA / GY / FS / LIZA / MD / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

20/2/20 100 23-3-2028 LTA 36579
 1/5 3300 confirmed with AM Xing
 C\$ 12,211.12 Red - 79%

RECEIVED 21 FEB 2020

Date/Time, File Pass to?

21/02/20

1) Typist
Date/Time, File Return to?

2)

☐ : Preli. Report☒ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) S + RS. SI

) Photos

) Others

TOTAL

Report Format:

Lump Sum / I.B.I: (\$ 3,300/- 45)

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

770

Summer Lee (LKK Auto)

From: Adeline Chng <adeline.chng@sg.cntaiping.com>
Sent: Wednesday, 5 February, 2020 3:55 PM
To: assignments
Cc: cindy.tan@kannansg.com.sg
Subject: FW: OUR REF: SNM20D200633/SKD658B/ADELINE & YOUR REF: f: KSG/5106/2020/N/ct

Without Prejudice

Dear Lkk

Please refer to below email and liaise with third party workshop accordingly.

Thank you.

Adeline Chng
Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6155 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

From: Cindy Tan [mailto:cindy.tan@kannansg.com.sg]
Sent: Wednesday, 5 February 2020 3:47 PM
To: Adeline Chng <adeline.chng@sg.cntaiping.com>; Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: RE: OUR REF: SNM20D200633/SKD658B/ADELINE & YOUR REF: f: KSG/5106/2020/N/ct

Dear Ms Adeline

WITHOUT PREJUDICE

RE: PROPERTY DAMAGE CLAIM
CLAIMANT : NG BOON KIM (NRIC NO.: SXXXX158E)
ACCIDENT INVOLVING VEHICLES NO. SJD 4635C (OWNER), SKD 658B & SKX 1387X
ALONG PIE TOWARDS JURONG ON 3 FEBRUARY 2020 AT 0700 HRS
PRE-REPAIR INSPECTION NOTICE

We refer to the above matter.

We are instructed to propose using Mr Marcus Chua as the single joint expert as listed in your said email.

Kindly contact Mr Lim at 9786 4483 to arrange for the pre-repair inspection soonest possible.

To: Adeline Chng <adeline.chng@sg.cntaiping.com>; cindy.tan@kannansg.com.sg
Subject: OUR REF: SNM20D200633/SKD658B/ADELINE & YOUR REF: f: KSG/5106/2020/N/ct

Dear Cindy,

We refer to your email on 4th February 2020.

Please be advised that we had already received from Vision Law LLC to conduct PRS.(see attached).

Kindly provide a copy of withdrawal letter from your client if there is change of lawyer.

Officer in charge on this case is Adeline Chng- DID 6389 6155.

Thank you.

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
Tel: (65) 63896116 | M: (65) 62247175 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Cindy Tan <cindy.tan@kannansg.com.sg>
Sent: Tuesday, February 4, 2020 12:05 PM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: RE: YRef: SKD 658B Oref: KSG/5106/2020/N/ct

Dear Sirs / Mdm

WITHOUT PREJUDICE

RE: PROPERTY DAMAGE CLAIM
CLAIMANT : NG BOON KIM (NRIC NO.: SXXXX158E)
ACCIDENT INVOLVING VEHICLES NO. SJD 4635C (OWNER), SKD 658B & SKX 1387X
ALONG PIE TOWARDS JURONG ON 3 FEBRUARY 2020 AT 0700 HRS
PRE-REPAIR INSPECTION NOTICE

We act for Mr Ng Boon Kim, the owner of motor vehicle No. SJD 4635C, which was involved in the aforesaid accident.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle at our clients' workshop. The details are as follows:-

Place: M/s Automobile Hub Enterprise
1 Kaki Bukit Avenue 6
#02-11 Autobay@Kaki Bukit
Singapore 417883

Contact Person: Mr Lim - 9786 4483

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Kindly revert.

Regards

Cindy Tan

M/S KANNAN SG
Advocates & solicitors
50 Chin Swee Road
#08-03 Thong Chai Building
Singapore 169874

TEL: (+65) 6429 0253
FAX: (+65) 6223 1660

IMPORTANT: THIS E-MAIL IS INTENDED ONLY FOR THE USE OF THE ADDRESSEE AND MAY CONTAIN CONFIDENTIAL INFORMATION AND/OR MAY BE COVERED BY PROFESSIONAL PRIVILEGE. IT MUST NOT BE READ, USED OR DISCLOSED BY ANY PERSON OTHER THAN THE ADDRESSEE(S) NAMED. IF YOU HAVE RECEIVED THIS E-MAIL IN ERROR, PLEASE NOTIFY US IMMEDIATELY BY TELEPHONE (COLLECT INTERNATIONAL CALL IF APPROPRIATE) AT (+65) 6429 0252 OR BY E-MAIL AND DELETE THE E-MAIL IMMEDIATELY. THANK YOU.

Millionaires are rioting:

Zhang's new project makes too many people rich

Stream Price Range Depreciation > 10 year Vehicle Type Submit

Advanced Search

Home » Used Cars » Bavarian Marques Pte Ltd » Honda Stream 1.8A X (COE till 09/2028)

Honda Stream 1.8A X (COE till 09/2028)

Overview Financial Insurance Accessories Similar Research Photos Map

BAVARIAN
MARQUES

für die Liebe von Autos

Price	\$52,800		
Depreciation	\$6,110 /yr	Reg Date	25-Sep-2008 (8yrs 7mths 18days COE left)
Mileage	210,000 km (18.5k /yr)	Manufactured	2008
Road Tax	\$1,174 /yr	Transmission	Auto
Dereg Value	\$28,832 as of today (change)	OMV	\$16,822
COE	\$33,377	ARF	\$14,411
Engine Cap	1,799 cc	Power	103.0 kW (138 bhp)
Curb Weight	1,350 kg	No. of Owners	3
Type of Vehicle	MPV		

Features

Powerful 1.8L 16V I-VTEC Engine, 5 Speed Auto, Dual Airbags, Immobilizer, Multifunction Steering, Climatic Aircon Control, Retractable Side Mirrors. View specs of the Honda Stream (2007-2014)

Accessories

Pioneer Fitted MP3/DVD Audio With Reverse Camera, Solar Films, Beautiful Black Colour Interior Leather, 16" Sports Rims.

Description

Reliable And Low Maintenance Cost. Own By Careful Owner. Most Popular Honda MPV For Your Family Usage! 100% Accident Free And No Modifications Done! Accident Free. Trade In/Consignment Available. Up To 80% Loan Of The Car Price Available. Contact Us For A Viewing Appointment!

Category

COE Car

Status

Available

Resources



Car Valuation - Free

Find out the market value of your existing car for free. Get started

Compare



Location Map

Shortlist Compare Add note
Report Error More Actions

Seller Information

Bavarian Marques Pte Ltd

71 vehicles for sale, 64 sold in past 3 mths

39 Woodlands Close #03-01/22

Mega@Woodlands

Tel: 67178811

Search cars nearby

bavarianmarques.com.sg

Qai

88148478

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 158E

Vehicle Details

Vehicle No.: SJD4635C

Vehicle to be Exported: No

Intended Deregistration Date: 06 Feb 2020

Vehicle Make: HONDA

Vehicle Model: STREAM 1.8X A

Primary Colour: Grey

Manufacturing Year: 2007

Engine No.: R18A1754727

Chassis No.: RN61049088

Maximum Power Output: 103.0 kW (138 bhp)

Open Market Value: \$15,585.00

Original Registration Date: 24 Mar 2008

First Registration Date: 24 Mar 2008

Transfer Count: 0

Actual ARF Paid: \$17,144.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 23 Mar 2028

COE Category: E - Open Category

COE Period(Years): 10

PQP Paid: \$44,998.00

COE Rebate Amount: \$36,579.00

Total Rebate Amount: \$36,579.00

The information contained herein is correct as at 06 Feb 2020

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/02/2020 13:55
Date Of Accident	03/02/2020 07:00
Exact Location Of Accident	PIE TWDS JURONG
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJD4635C
Insured/Policyholder	
Name Of Registered Owner	NG BOON KIM
NRIC No	SXXXX158E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97216069
Alternative Phone No	OFFICE-97216069

Vehicle Particulars

Manufacturer	HONDA
Model	STREAM
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2018-00003209-01
Cover Note Number	

Driver

Name of Driver	NG YUE TAT ALOYSIUS (HUANG YUDA)
NRIC No	SXXXX563I
Date Of Birth	31/12/1988
Occupation	INDOOR
Date Of Driving Pass	05/12/2007
Driving Experience	12 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-98379173
Fax Number	
Contact Number	OTHERS: 82188870

Address	49 JLN ARIF
Postcode	545103
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : RACHEL LEONG GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TRAVELLING ALONG PIE TWDS JURONG ON THE CENTER LANE, VEH INFRONT OF ME STOP, AS SUCH I FOLLOW TO STOP, ALL OF A SUDDEN, I FELT AN IMPACT FROM BEHIND, AFTER THE INCIDENT, I ALIGHTED FROM MY VEH AND REALIZED I WAS INVOLVED IN A 3 CAR CHAIN COLLISION ACCIDENT. VEH B FROM BEHIND COLLIDED INTO MY VEH REAR PORTION.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKD658B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SKX1387X

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN



A = 5JD 4635C
B = 5KD 6588
C = 5KX 1387X

217. 4 weeks. Increasing.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please Refer to statement

DECLARATION


NOTE: See the first page of the report for the title and the subject.

Date & Time

11/19/2017 10:10 AM

Symptoms:

Signs: 1-10% Na⁺



C71 S

Repair Estimate

not Authorized
Hater
6/1/20
Take the other repair
1/5 @ 3300
Hater.

Automobile Hub Enterprise

1 Kaki Bukit Avenue 6 #02-11 Autobay @ Kaki Bukit Singapore 417883
Tel: (65) 9786 4483 Fax: (65) 6509 6584 Email: autohub325@gmail.com

Vehicle No.: SJD4635C

Model: Honda Stream

Qty	Description	Amt S(\$)
	<u>List Items</u>	
1	Rear windscreen moulding	\$ 118.50
1	Rear tailgate	\$ 1,285.00
2	Rear tailgate dampers	\$ 297.00 X
1	Rear tailgate outer garnish	\$ 189.00 X
1	Rear tailgate inner lock	\$ 303.20 X
1	Rear tailgate inner trim board	\$ 489.50
1	Rear tailgate logo	\$ 45.00 X
1	Rear tailgate inner pull pocket	\$ 82.60 X
1	Rear tailgate weatherstrip	\$ 189.60 X
1	Rear tailgate "STREAM" emblem	\$ 68.50
1	Rear tailgate "RSZ" emblem	\$ 85.00 X
2	Rear taillamps	\$ 1,171.80 1PC
2	Rear taillamp panels	\$ 650.00 X
1	Rear end panel	\$ 685.00 X
1	Rear end panel inner garnish	\$ 212.60 X
1	Rear end panel inner member	\$ 559.00 X
1	Rear bumper	\$ 1,185.00
4	Rear bumper lower brackets	\$ 234.00 1PC
1	Rear bumper lower diffuser	\$ 680.00 X
2	Rear bumper reflectors	\$ 96.00 X
2	Rear bumper side retainers	\$ 97.00 4PC
1	Rear bumper tow hook cover	\$ 42.50
1	Rear bumper under cover	\$ 285.00 X
1	Rear floor panel	\$ 1,226.50 X
1	Rear floor board	\$ 286.00 X
1	Rear exhaust silencer	\$ 689.50 X
2	Rear exhaust mountings	\$ 57.00 X
1	Rear fender	\$ 981.60 X
1	Rear spare tyre carrier	\$ 326.50 X
1	Rear spare tyre lock catch	\$ 108.50 X
		\$ 12,726.40
		\$ 2,545.28
		\$ 10,181.12

Less 20%

LKK Auto Consultants hence notify the Repairer of the following:

- To return telematics spy unit
- To the pay manager part 4) copy the key
- Part 4) was subject to lockman
- Third party survey is on a "Without Prejudice" basis
- No litigation collection is allowed
- Supplementary service must be recognized and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2892
207
P-2313.60
S.N-280.00
L-1580.00
4153.60
20%
3312

Special Nett Items

1	Rear windscreen sealant	\$	net	80.00	40
1	Rear "PRIVATE HIRE" sticker	\$	NN	45.00	X
1	Rear bumper clip (1 set)	\$	net	45.00	40
1	Rear number plate with holder	\$	11	50.00	X
1	Rear reverse sensor (1 set)	\$	Shwld	350.00	200
1	Rear reverse camera	\$	src	480.00	X
1	Rear exhaust chrome tail pipe	\$	11	120.00	X
				\$	1,170.00

Labour Charges

1	To remove, replaced damaged lamps and check up rear wiring.	\$		80.00	20
2	To remove and refit inner garnishes.	\$		180.00	80
3	To remove and refit rear reverse sensor and camera.	\$		150.00	50
4	To transfer rear tailgate mechanism and wiring assembly.	\$		120.00	60
5	To remove and refit rear windscreen glass.	\$		180.00	120
6	To remove, refit and replace exhaust silencer and mountings.	\$	11	150.00	X
7	To apply undercoating.	\$		200.00	50
8	Panel beating, remove and replacing above parts.	\$		1,600.00	580
9	To respray painting.	\$		1,500.00	600
				\$	4,160.00

1580

ESTIMATE PARTS AND LABOUR TOTAL \$

\$ 15,511.12

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT120002017/USF3N2

Date: 25/02/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN30471719033
Claimant Vehicle No :	SJD4635C	Insured Vehicle No :	SKD658B
Date of Loss:	03/02/2020	Nature of Claim:	TP
		Claim No:	SNM20D200633C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJD4635C	Engine No:	R18A1754727
Make & Model:	HONDA STREAM, 1.8 X (A)	Chassis No:	RN61049088
Reg. Date:	24/03/2008 (Man. Year: 2007)	Odometer:	253540 km
Colour:	Brown		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/65R15	Rear Tyre Size:	205/65R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,351.12	2,593.60	8,757.52	77.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,160.00	1,560.00	2,600.00	62.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,511.12	4,153.60	11,357.52	73.22
Approved Total (Overridden) (S\$)		3,300.00		
Nett Amount (S\$)	15,511.12	3,300.00	12,211.12	78.72

INSPECTION

Date of Assignment:	05/02/2020	Automobile Hub Enterprise 1 KAKI BUKIT AVENUE 5, #2 -11 AUTOBAY @ KAKI BUKIT Singapore 417883
Date Inspected:	06/02/2020 Inspected At:	
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 25 Feb 2020)

Parts: M1-MPV HONDA STREAM 1.8 X (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJD4635C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	118.50 FL	*118.50 FL
2	1		*REAR TAILGATE	Badly Dented/Buckled	1,285.00 FL	*953.00 FL
3	2		*REAR TAILGATE DAMPERS	Not Necessary	297.00 FL	*- FL
4	1		*REAR TAILGATE OUTER GARNISH	Not Necessary	189.00 FL	*- FL
5	1		*REAR TAILGATE INNER LOCK	Shorted	303.20 FL	*303.20 FL
6	1		*REAR TAILGATE INNER TRIM BOARD	Deformed/Torn	489.50 FL	*285.10 FL
7	1		*REAR TAILGATE LOGO	Not Necessary	45.00 FL	*- FL
8	1		*REAR TAILGATE INNER PULL POCKET	Not Necessary	82.60 FL	*- FL
9	1		*REAR TAILGATE WEATHERSTRIP	Not Necessary	189.60 FL	*- FL
10	1		*REAR TAILGATE STREAM EMBLEM	Necessary	68.50 FL	*34.70 FL
11	1		*REAR TAILGATE RSZ EMBLEM	Not fitted	85.00 FL	*- FL
12	1		*REAR TAILLAMP	N/s Cracked	1,171.80 FL	*409.80 FL
13	2		*REAR TAILLAMP PANELS	Not Necessary	650.00 FL	*- FL
14	1		*REAR END PANEL	Repair	685.00 FL	*- FL
15	1		*REAR END PANEL INNER GARNISH	Not Necessary	212.60 FL	*- FL
16	1		*REAR END PANEL INNER MEMBER	Not Necessary	559.00 FL	*- FL
17	1		*REAR BUMPER	Distorted	1,185.00 FL	*665.40 FL
18	1		*REAR BUMPER LOWER BRACKETS (4 Pcs)	N/s Bent (1 Pc only)	234.00 FL	*55.00 FL
19	1		*REAR BUMPER LOWER DIFFUSER	Not fitted	680.00 FL	*- FL
20	2		*REAR BUMPER REFLECTORS	Not Necessary	96.00 FL	*- FL
21	1		*REAR BUMPER SIDE RETAINERS	N/s Bent	97.00 FL	*36.50 FL
22	1		*REAR BUMPER TOW HOOK COVER	Torn	42.50 FL	*30.80 FL
23	1		*REAR BUMPER UNDER COVER	Not Necessary	285.00 FL	*- FL
24	1		*REAR FLOOR PANEL	Not Necessary	1,226.50 FL	*- FL
25	1		*REAR FLOOR BOARD	Not Necessary	286.00 FL	*- FL
26	1		*REAR EXHAUST SILENCER	Not Necessary	689.50 FL	*- FL
27	2		*REAR EXHAUST MOUNTINGS	Not Necessary	57.00 FL	*- FL
28	1		*REAR FENDER	Not Necessary	981.60 FL	*- FL
29	1		*REAR SPARE TYRE CARRIER	Not Necessary	326.50 FL	*- FL
30	1		*REAR SPARE TYRE LOCK CATCH	Not Necessary	108.50 FL	*- FL
31	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
32	1		*REAR PRIVATE HIRE STICKER	Not Necessary	45.00 FS	*- FS
33	1		*SET REAR BUMPER CLIP	Necessary	45.00 FS	*40.00 FS
34	1		*REAR NUMBER PLATE WITH HOLDER	Not Necessary	50.00 FS	*- FS
35	1		*SET REAR REVERSE SENSOR	Shorted	350.00 FS	*200.00 FS
36	1		*REAR REVERSE CAMERA	Serviceable	480.00 FS	*- FS
37	1		*REAR EXHAUST CHROME TAIL PIPE	Not Necessary	120.00 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	13,896.40	3,172.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,545.28	578.40
Total Parts (\$\$)	11,351.12	2,593.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING	New	80.00	20.00
2	TO REMOVE AND REFIT INNER GARNISHES	New	180.00	80.00
3	TO REMOVE AND REFIT REAR REVERSE SENSOR AND CAMERA	New	150.00	50.00
4	TO TRANSFER REAR TAILGATE MECHANISM AND WIRING ASSEMBLY	New	120.00	60.00
5	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	120.00
6	TO REMOVE,REFIT AND REPLACE EXHAUST SILENCER AND MOUNTINGS	New	150.00	0.00
7	TO APPLY UNDERCOATING	New	200.00	50.00
8	PANEL BEATING,REMOVE AND REPLACING ABOVE PARTS	New	1,600.00	580.00
9	TO RESPRAY PAINTING	New	1,500.00	600.00
Gross Labour Cost (\$\$)			4,160.00	1,560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >