

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/AIG20002021/KEA3Q2

**Date:** 11/11/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100435443

**Claimant Vehicle No :** SHC5344P **Insured Vehicle No :** SKW3157K

Date of Loss: 01/02/2020 Nature of Claim: TP Claim No: 2577750251SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHC5344P**

Make & Model: RENAULT LATITUDE, 2.0 DCI AUTO D/AB 4DR (A) Engine No: M9R8839C001992

Reg. Date: 30/09/2014 (Man. Year: 2014) Chassis No: VF1ABL15AUC279353

Colour: Metallic White/Red Odometer: 608025 km

Engine Capacity: 1995 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16

Front Left Side: Sailun 8 mm Rear Left Side: Sailun 8 mm

Front Right Side: Sailun 8 mm Rear Right Side: Sailun 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	17,763.49	2,695.19	15,068.30	84.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	17,170.00	1,170.00	16,000.00	93.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>34,933.49</b>	<b>3,865.19</b>	<b>31,068.30</b>	<b>88.94</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,100.00</b>		
<b>(S\$)</b>	34,933.49	3,100.00	31,833.49	91.13
<b>+ GST 7.00/7.00% (S\$)</b>	2,445.34	217.00	2,228.34	91.13
<b>Nett Amount (S\$)</b>	<b>37,378.83</b>	<b>3,317.00</b>	<b>34,061.83</b>	<b>91.13</b>
<b>+ Loss of Use (4.0 x S\$50.00/day) (S\$)</b>		200.00		
<b>+ Car Rental (4.0 x S\$95.04/day) (S\$)</b>		380.16		
<b>+ Doc/Search Fee (S\$)</b>		7.49		
<b>Nett Liability (S\$)</b>		<b>3,904.65</b>		
<b>Global Sum Settlement (S\$)</b>		<b>3,900.00</b>		

### INSPECTION

Date of Assignment: 04/02/2020

Date Inspected: 04/02/2020 Inspected At:

Trans-cab Auto Services Pte Ltd  
No 2 Ang Mo Kio Street 63  
Singapore 569111

Estimated Period of Repair: 3.0 days

---

**Adjuster:** HOW MEI KWAN

**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DOOR PANEL REAR RH	Repair	758.70 FL	*- FL
2	1		*DOOR GUIDE REAR RH	Serviceable	136.40 FL	*- FL
3	1		*DOOR SEAL REAR RH	Serviceable	119.80 FL	*- FL
4	1		*DOOR WEATHERSTRIP REAR RH	Serviceable	311.60 FL	*- FL
5	1		*DOOR HANDLE OUTER REAR RH L70Y	Serviceable	42.10 FL	*- FL
6	1		*DOOR HANDLE CAP REAR RH L70Y	Serviceable	57.90 FL	*- FL
7	1		*DOOR REGULATOR REAR RH L70Y	Serviceable	758.10 FL	*- FL
8	1		*DOOR REGULATOR MOTOR REAR RH L70Y	Serviceable	450.60 FL	*- FL
9	1		*DOOR PANEL FRT RH	Bent	2,844.66 FL	*2,844.66 FL
10	1		*DOOR REGULATOR FRT RH	Serviceable	505.19 FL	*- FL
11	1		*DOOR REGULATOR MOTOR FRT RH	Serviceable	796.46 FL	*- FL
12	1		*DOOR REGULATOR GUIDE FRT RH	Serviceable	120.97 FL	*- FL
13	1		*DOOR HANDLE OUTER FRONT RH	Serviceable	477.76 FL	*- FL
14	1		*DOOR HANDLE CAP FRONT RH	Serviceable	35.52 FL	*- FL
15	1		*DOOR HANDLE MODULE FRT RH L70Y	Serviceable	133.60 FL	*- FL
16	1		*DOOR SEAL FRONT RH	Serviceable	72.82 FL	*- FL
17	1		*DOOR SEAL POWER FRONT RH	Serviceable	91.17 FL	*- FL
18	1		*DOOR WEATHERSTRIP FRONT RH	Serviceable	410.27 FL	*- FL
19	1		*DOOR MIRROR ASSY RH	Serviceable	1,483.40 FL	*- FL
20	1		*DOOR HARNESS WIRE RH	Serviceable	2,670.00 FL	*- FL
21	1		*ROCKER PANEL INNER GARNISH RH	Serviceable	466.51 FL	*- FL
22	1		*ROCKER PANEL INNER RH	Repair	1,024.79 FL	*- FL
23	1		*ROCKER PANEL OUTER RH	Repair	1,184.99 FL	*- FL
24	1		*ROCKER PANEL CENTER RH	Repair	990.25 FL	*- FL
25	1		*FENDER PANEL REAR RH	Repair	1,933.20 FL	*- FL
26	1		*WHEELARCH REAR RH	Serviceable	275.40 FL	*- FL
27	1		*DOOR CHECK BOLT	Serviceable	22.69 FS	*- FS
28	1		*DOOR GUIDE SCREW	Serviceable	10.85 FS	*- FS
29	1		*DOOR HINGE BOLT	Serviceable	10.85 FS	*- FS
30	1		*DOOR HINGE NUT RH	Serviceable	14.60 FS	*- FS
31	1		*DOOR CHECK BOLT	Serviceable	22.69 FS	*- FS
32	1		*DOOR CHECK NUT	Serviceable	3.75 FS	*- FS
33	1		*DOOR LOCK SCREW L70Y	Serviceable	6.12 FS	*- FS
34	1		*REAR RIGHT TYRE	Serviceable	300.00 FS	*- FS
35	1		*REAR RIGHT TYRE RIM	Serviceable	380.00 FS	*- FS
36	1		*REAR RIGHT TYRE RIM COVER	Serviceable	60.00 FS	*- FS
37	1		*FRONT DOOR STICKER TRANS-CAB	Necessary	80.00 FS	*60.00 FS
38	1		*FRONT DOOR STICKER CLASSIC	Necessary	80.00 FS	*15.00 FS
39	1		*REAR DOOR STICKER 6555-3333	Necessary	100.00 FS	*60.00 FS
40	2		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
41	1		*WINDSCREEN MOULDING	Not Necessary	120.00 FS	*- FS
42	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
43	1		*SET FENDER WHEELARCH REAR RH CLIP	Not Necessary	35.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>19,578.71</b>	<b>2,979.66</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	<b>1,815.22</b>	<b>284.47</b>
<b>Total Parts (\$\$)</b>	<b>17,763.49</b>	<b>2,695.19</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	7,500.00	400.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	7,500.00	660.00
3	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
4	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	0.00
5	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
6	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	170.00	0.00
7	TO TRANSFER OF REAR DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
8	TO TRANSFER OF REAR FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
9	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR	New	380.00	0.00
10	TO TRANSFER OF FRONT DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
11	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	30.00
12	TO REMOVE AND REFIT REAR W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	170.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>17,170.00</b>	<b>1,170.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >