

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5344P**AAD2002-010***Not Authorised
1/12/2014 \$ 31006*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHC 5344P

VF1ABL15AUC279353

RENAULT

LATITUDE

1.2.2020

AIG

30/9/2014

PART		LIST	
1	DOOR PANEL REAR RH	\$	758.70
1	DOOR GUIDE REAR RH	\$	136.40
1	DOOR SEAL REAR RH	\$	119.80
1	DOOR WHEATHERSTRIP REAR RH	\$	311.60
1	DOOR HANDLE OUTER REAR RH L70Y	\$	42.10
1	DOOR HANDLE CAP REAR RH L70Y	\$	57.90
1	DOOR REGULATOR REAR RH L70Y	\$	758.10
1	DOOR REGULATOR MOTOR REAR RH L70Y	\$	450.60
1	DOOR PANEL FRT RH	\$	2,844.66
1	DOOR REGULATOR FRT RH	\$	505.19
1	DOOR REGULATOR MOTOR FRT RH	\$	796.46
1	DOOR REGULATOR GUIDE FRT RH	\$	120.97
1	DOOR HANDLE OUTER FRONT RH	\$	477.76
1	DOOR HANDLE CAP FRONT RH	\$	35.52
1	DOOR HANDLE MODULE FRT RH L70Y	\$	133.60
1	DOOR SEAL FRONT RH	\$	72.82
1	DOOR SEAL LOWER FRONT RH	\$	91.17
1	DOOR WHEATHESTRIIP FRONT RH	\$	410.27
1	DOOR MIRROR ASSY RH	\$	1,483.40
1	DOOR HARNESS WIRE RH	\$	2,670.00
1	ROCKER PANEL INNER GARNISH RH	\$	466.51
1	ROCKER PANEL INNER RH	\$	1,024.79
1	ROCKER PANEL OUTER RH	\$	1,184.99
1	ROCKER PANEL CENTER RH	\$	990.25
1	FENDER PANEL REAR RH	\$	1,933.20
1	WHEELARCH REAR RH	\$	275.40

04 FEB 2020

Trans-cab Auto Services Pte Ltd**AAD2002-010**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5344P

TOTAL	\$	18,152.16
10%	\$	1,815.22
	\$	16,336.94

Special Nett

1	DOOR CHECK BOLT	\$	22.69	
1	DOOR GUIDE SCREW	\$	10.85	
1	DOOR HINGE BOLT	\$	10.85	
1	DOOR HINGE NUT RH	\$	14.60	
1	DOOR CHECK BOLT	\$	22.69	
1	DOOR CHECK NUT	\$	3.75	
1	DOOR LOCK SCREW L70Y	\$	6.12	
1	REAR RIGHT TYRE	\$	300.00	
1	REAR RIGHT TYRE RIM	\$	380.00	
1	REAR RIGHT TYRE RIM COVER	\$	60.00	
1	FRONT DOOR STICKER "Trans-Cab"	\$	80.00	60sm
1	FRONT DOOR STICKER "Classic"	\$	80.00	15sm
1	REAR DOOR STICKER "6555-3333"	\$	100.00	60sm
2	REAR WINDSCREEN SEALANT	\$	80.00	X
1	WINDSCREEN MOULDING	\$	120.00	X
1	REAR WINDSCREEN INNER SPONGE SEAL	\$	100.00	X
1SET	FENDER WHEELARCH REAR RH CLIP	\$	35.00	X
TOTAL	\$	1,426.57		

TOTAL PARTS \$ 17,763.51**LABOUR**

Panel beating, knocking and straightening the
necessary portion, remove and renewal of parts,
adjust and realign the same

\$ 7,500.00 4000

Putty and spray painting of the affected portion.

\$ 7,500.00 6600

To Check Electrical Lighting Concerned.

\$ 170.00 200

Trans-cab Auto Services Pte Ltd**AAD2002-010**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5344P

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn	380.00	X
To check steering geometry and computer wheel alignment	\$	nn	220.00	X
To transfer of tire, rim and on wheel balancing.	\$	nn	170.00	X
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	nn	170.00	X
To transfer of Rear Fender fittings, attachment and perform water seepage test.	\$	nn	170.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn	380.00	X
To transfer of Front door fittings, attachment and perform water seepage test.	\$		170.00	601
To rust-proofing of the affected areas.	\$		170.00	301
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	nn	170.00	X

TOTAL \$ **17,170.00****Over All Total** \$ **34,933.51****LUMP SUM (REPAIR DAY)****25 DAYS****3 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: