

VEHICLE NO : FBJ 3577G

Honda CB 400

31 Fork Stabilizer Bracket	1	250.00	✓
32 Fork Oil Seal	1 set	125.00	✓
33 Leg Shield - LH/RH	2	270.00	✓
34 Side Fairing Inner Panel	2	240.00	✓
35 Radiator Guard	1	220.00	✓
36 Front Mudguard Bracket	1	210.00	✓
37 Radiator Fan Cowling	1	180.00	✓
	Sub-Total	8,243.00	
	Less 10%	824.30	
	Sub-Total	7,418.70	

Nett Items

1 Towing fee	40.00	X
2 Remove & replace new parts, align & etc	350.00	200/-
3 Remove & replace fork assy, oil seal & top up fork oil	90.00	80/-
4 Remove & replace front rim, brake disc, brake caliper	150.00	30/-
5 Putty & respray paint & front rim	450.00	150/-
6 Check electrical wiring & connections	60.00	30/-
	Sub-Total	1,140.00
	Nett Total	8,558.70

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion.
Thank you

05/02/2020 @ 1600m

Not Author

2/Jan 5

S9 MOTOR TRADING PTE LTD

:LG

Ryan

LKK Auto

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To resurvey damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: