

Finalized 30/03/2020. /Dda3

S9 MOTOR TRADING PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 5 February 2020

To : LKK

By Fax: 6256-4315

Attn : Bryan Ang


Tel: 97237799

VEHICLE NO : FBJ 3577G

Honda CB 400

ACCIDENT DATE: 1 February 2020

Description	Qty	Quotation \$
1 Handle Bar o/s NW 1/2 set	2	235.00 ✓ 117.50
2 Handle Bar Stabilizer 1/2 set	1	185.00 ✓
3 Visor NW	1	235.00 X
4 Front Head Cowling - Panel broken	1	235.00 ✓
5 Head Lamp Assy broken	1	550.00 ✓
6 Head Lamp Stay 1/2 set	1	250.00 ✓
7 Mirror cut	1 set	220.00 ✓
8 Front Mudguard broken	1	255.00 ✓
9 Front Signal 1/2 destroyed o/s NW	2	180.00 ✓ 90.00
10 Brake Lever NW	1	68.00 X
11 Front L/RH Side Fairing crack / broken	1	310.00 ✓
12 Fork Tube 1/2 set	1	480.00 ✓
13 Fork Under Bracket Dam	1	220.00 ✓
14 Front Rim distorted	1	350.00 ✓
15 Front Brake Disc NW	1	235.00 X
16 Front Dimmer Light crack	1	235.00 ✓
17 Petrol Tank new	1	260.00 X
18 Gear Rod 1/2 set	1	105.00 ✓
19 Gear Pedal 1/2 set	1	75.00 ✓
20 Front LH Footrest 1/2 set / cut	1	85.00 ✓
21 Front LH Footrest Bracket 1/2 set	1	155.00 ✓
22 Engine Bracket broken	1	135.00 ✓
23 Rear Tail Panel new	1	165.00 X
24 Rear Pillion Footrest Bracket LH 1/2 set	1	155.00 ✓
25 Pillion Footrest 1/2 set	1	95.00 ✓
26 Rear Mudguard NW	1	195.00 X
27 Wheel Axle - Front distorted	1	125.00 ✓
28 Lower Engine Cover x2 broken	2	270.00 ✓
29 Front Brake Caliper NW	1	135.00 X
30 Radiator Assy punctured	1	550.00 ✓



VEHICLE NO : FBJ 3577G

Honda CB 400

31 Fork Stabilizer Bracket <i>ist</i>	1	250.00	✓
32 Fork Oil Seal <i>McC</i>	1 set	125.00	✓
33 Leg Shield - LH/RH <i>Cwt</i>	2	270.00	✓
34 Side Fairing Inner Panel <i>broken</i>	2	240.00	✓
35 Radiator Guard <i>ist</i>	1	220.00	✓
36 Front Mudguard Bracket <i>ist</i>	1	210.00	✓
37 Radiator Fan Cowling <i>broken</i>	1	180.00	✓
	Sub-Total	8,243.00	
	Less 10%	824.30	
	Sub-Total	7,418.70	

6742.50
6068.25

Nett Items

1 Towing fee <i>HN</i>		40.00	X
2 Remove & replace new parts, align & etc		350.00	200/-
3 Remove & replace fork assy, oil seal & top up fork oil		90.00	80/-
4 Remove & replace front rim, brake disc, brake caliper		150.00	30/-
5 Putty & respray paint & front rim		450.00	150/-
6 Check electrical wiring & connections		60.00	30/-
	Sub-Total	1,140.00	
	Nett Total	8,558.70	

490.00

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

6558.25

1/s 4800/-

Kindly revert upon completion.
Thank you

05/02/2020 @ 1600m

Not Author

S9 MOTOR TRADING PTE LTD

LG

*2/Jan 5
R
njan
LKK Auto*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To replace damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

[Handwritten signature]