Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111 Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7758X

AAD2002-001

Not Notherhol Resorry B4 pain

	Vehicle No.:		SHB 775	8X		
	Chassis No.:		JTDKB3FL		79618	
	Vehicle Make:		TOYOTA	20000	, 5010	
	Vehicle Model: 0.4 FEB 2020		PRIUS			
	Date of Accident :		2.2.2020			
	Third Party Insurer :		III			
	Date of Registration:		29/3/201	9		
	PART			LIST		
1	REAR BUMPER		\$	Bu	442.60	
1	REAR BUMPER RE-INFORCEMENT		\$	M	•332.70 🔀	,
1	REAR BUMPER TOWING COVER		\$	FL		
1	GUARD, REAR BUMPER, CENTER		\$	nu		_
1	REAR BUMPER SIDE RETAINER LH		\$	FL		
1	REAR BUMPER SIDE RETAINER RH		\$	1-	117.70 X	
1	REAR TAILGATE		\$	n	1,147.80	
1	REAR TAILGATE OUTER GARNISH		\$	JL	925.60	
1	REAR TAILGATE WEATHERSTRIP		\$	SL	372.30	
1	PANEL SUB-ASSY, BODY LOWER BACK		\$	n	650.30	
1	TAILLAMP LOWER RH		\$	Sy	502.00	
1	TAILLAMP UPPER RH		\$	54	451.80	
1	REAR BUMPER SIDE RH		\$	54	123.70	X
1	REAR BUMPER SIDE LH		\$	Sa	123.70	
1	TAILLAMP LOWER LH		\$	SL	502.00	
1	TAILLAMP UPPER LH		\$	Sa	443.30	
1	COVER, DECK TRIM, REAR		\$	ST	126.70	
1	COVER, FLOOR UNDER, NO 1		\$	SL	175.10	
1	COVER, FLOOR UNDER, NO 2		\$	Sz	241.90	
1	COVER, REAR FLOOR		\$	A	229.90	
	Т	OTAL	\$	7	,617.30	
		25%	\$	1	,904.33	
			\$	5	,712.98	

Special Nett

Trans-cab Auto Services Pte Ltd

AAD2002-001

No. 2 Ang Mo Kio Street 63 Singapore 569111 Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7758X

3110 /			
			C. 11 22
1SET	PARKING AID	\$	Sin 700.00 22asa_
1SET	REAR BUMPER CLIP	\$	66.00
1	REAR TAILGATE TOYOTA LOGO	\$	47.00
1	REAR TAILGATE WORDING 'PRIUS'	\$	200 52.90
1	REAR TAILGATE WORDING 'HYBRID'	\$	ルル 53.50
1	REAR TAILGATE STICKER 'TRANS-CAB'	\$	nn 80.00
1	REAR TAILGATE STICKER '6555-3333'	\$	1 80.00
1	REAR BUMPER PROTECTOR	\$	100.00 X
1	REAR WHEEL RIM	\$	1,879.40
1	REAR TYRE 195/65/15	\$	350.00
1	REAR WHEEL RIM COVER	\$	Sa 211.50
1	REAR RH BUMPER RETAINER CLIP	\$	35.00
1	REAR LH BUMPER RETAINER CLIP	\$	35.00
	TOTAL	\$	3,690.30
	TOTAL DADTO	¢	9,403.28
	TOTAL PARTS	<u> </u>	5,105.20
			5,103.20
	LABOUR		5,103.20
	LABOUR To transfer of Tailgate fittings, attachments and		
	LABOUR	\$	nn 170.00 X
	LABOUR To transfer of Tailgate fittings, attachments and perform water seepage test.		
	LABOUR To transfer of Tailgate fittings, attachments and perform water seepage test. To transfer of Rear Bumper fittings, attachments and	\$	nn 170.00 X
	LABOUR To transfer of Tailgate fittings, attachments and perform water seepage test.		
	LABOUR To transfer of Tailgate fittings, attachments and perform water seepage test. To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	nn 170.00 X
	LABOUR To transfer of Tailgate fittings, attachments and perform water seepage test. To transfer of Rear Bumper fittings, attachments and perform water seepage test. To transfer of rear end panel fittings, attachment and	\$	nn 170.00 X nn 170.00 X
	LABOUR To transfer of Tailgate fittings, attachments and perform water seepage test. To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	nn 170.00 X
	LABOUR To transfer of Tailgate fittings, attachments and perform water seepage test. To transfer of Rear Bumper fittings, attachments and perform water seepage test. To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn 170.00 X nn 170.00 X nn 170.00 X
	LABOUR To transfer of Tailgate fittings, attachments and perform water seepage test. To transfer of Rear Bumper fittings, attachments and perform water seepage test. To transfer of rear end panel fittings, attachment and	\$	nn 170.00 X nn 170.00 X
	LABOUR To transfer of Tailgate fittings, attachments and perform water seepage test. To transfer of Rear Bumper fittings, attachments and perform water seepage test. To transfer of rear end panel fittings, attachment and perform water seepage test. Putty And Spray Painting Of The Affected Portion.	\$	nn 170.00 X nn 170.00 X nn 170.00 X
	LABOUR To transfer of Tailgate fittings, attachments and perform water seepage test. To transfer of Rear Bumper fittings, attachments and perform water seepage test. To transfer of rear end panel fittings, attachment and perform water seepage test. Putty And Spray Painting Of The Affected Portion. To check steering geometry and computer wheel	\$ \$ \$	nn 170.00 X nn 170.00 X nn 170.00 X 6,000.00 2201
	LABOUR To transfer of Tailgate fittings, attachments and perform water seepage test. To transfer of Rear Bumper fittings, attachments and perform water seepage test. To transfer of rear end panel fittings, attachment and perform water seepage test. Putty And Spray Painting Of The Affected Portion.	\$	nn 170.00 X nn 170.00 X nn 170.00 X
	LABOUR To transfer of Tailgate fittings, attachments and perform water seepage test. To transfer of Rear Bumper fittings, attachments and perform water seepage test. To transfer of rear end panel fittings, attachment and perform water seepage test. Putty And Spray Painting Of The Affected Portion. To check steering geometry and computer wheel alignment	\$ \$ \$	nn 170.00 X nn 170.00 X nn 170.00 X 6,000.00 2201
	LABOUR To transfer of Tailgate fittings, attachments and perform water seepage test. To transfer of Rear Bumper fittings, attachments and perform water seepage test. To transfer of rear end panel fittings, attachment and perform water seepage test. Putty And Spray Painting Of The Affected Portion. To check steering geometry and computer wheel	\$ \$ \$	nn 170.00 X nn 170.00 X nn 170.00 X 6,000.00 2201

Trans-cab Auto Services Pte Ltd

AAD2002-001

No. 2 Ang Mo Kio Street 63 Singapore 569111 Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7758X

(PART-BY-PART) Repair Days		20 Days 2day,	
Over All Total		23,573.28	•
TOTAL	\$	14,170.00	
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	2001
To Check Electrical Lighting Concerned.		170.00	101
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.		~~ _{380.00}	X
To transfer of tire, rim and on wheel balancing.	\$	<i>№</i> 170.00	X
To reinstall rear bumper parking sensor.		170.00	501
To Rust-Proofing Of The Affected Areas.		170.00	X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: