

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7758X**AAD2002-001***Not Authored
Recovery B4 pain*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

04 FEB 2020

SHB 7758X

JTDKB3FU003079618

TOYOTA

PRIUS

2.2.2020

III

29/3/2019

PART		LIST	
1	REAR BUMPER	\$	<i>Bu</i> 442.60 ✓
1	REAR BUMPER RE-INFORCEMENT	\$	332.70 7
1	REAR BUMPER TOWING COVER	\$	<i>fu</i> 15.40 X
1	GUARD, REAR BUMPER, CENTER	\$	<i>fu</i> 576.30 ✓
1	REAR BUMPER SIDE RETAINER LH	\$	<i>fu</i> 116.50 X
1	REAR BUMPER SIDE RETAINER RH	\$	<i>fu</i> 117.70 X
1	REAR TAILGATE	\$	<i>fu</i> 1,147.80
1	REAR TAILGATE OUTER GARNISH	\$	<i>fu</i> 925.60
1	REAR TAILGATE WEATHERSTRIP	\$	<i>fu</i> 372.30
1	PANEL SUB-ASSY, BODY LOWER BACK	\$	<i>fu</i> 650.30
1	TAILLAMP LOWER RH	\$	<i>fu</i> 502.00
1	TAILLAMP UPPER RH	\$	<i>fu</i> 451.80
1	REAR BUMPER SIDE RH	\$	<i>fu</i> 123.70 } X
1	REAR BUMPER SIDE LH	\$	<i>fu</i> 123.70
1	TAILLAMP LOWER LH	\$	<i>fu</i> 502.00
1	TAILLAMP UPPER LH	\$	<i>fu</i> 443.30
1	COVER, DECK TRIM, REAR	\$	<i>fu</i> 126.70
1	COVER, FLOOR UNDER, NO 1	\$	<i>fu</i> 175.10
1	COVER, FLOOR UNDER, NO 2	\$	<i>fu</i> 241.90
1	COVER, REAR FLOOR	\$	<i>fu</i> 229.90

TOTAL	\$	7,617.30
25%	\$	1,904.33
	\$	5,712.98

Special Nett

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7758X**AAD2002-001**

1SET PARKING AID	\$	<i>Sn</i> 700.00 <i>220sn</i>	
1SET REAR BUMPER CLIP	\$	<i>nn</i> 66.00	
1 REAR TAILGATE TOYOTA LOGO	\$	<i>nn</i> 47.00	} X
1 REAR TAILGATE WORDING 'PRIUS'	\$	<i>nn</i> 52.90	
1 REAR TAILGATE WORDING 'HYBRID'	\$	<i>nn</i> 53.50	
1 REAR TAILGATE STICKER 'TRANS-CAB'	\$	<i>nn</i> 80.00	
1 REAR TAILGATE STICKER '6555-3333'	\$	<i>nn</i> 80.00	
1 REAR BUMPER PROTECTOR	\$	<i>nn</i> 100.00	
1 REAR WHEEL RIM	\$	<i>Sn</i> 1,879.40	
1 REAR TYRE 195/65/15	\$	<i>Sn</i> 350.00	
1 REAR WHEEL RIM COVER	\$	<i>Sn</i> 211.50	
1 REAR RH BUMPER RETAINER CLIP	\$	<i>nn</i> 35.00	
1 REAR LH BUMPER RETAINER CLIP	\$	<i>nn</i> 35.00	
TOTAL	\$	3,690.30	
TOTAL PARTS	\$	9,403.28	

LABOUR

To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	<i>nn</i> 170.00 X
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	<i>nn</i> 170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00 X
Putty And Spray Painting Of The Affected Portion.	\$	6,000.00 <i>2201</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7758X**AAD2002-001**

To Rust-Proofing Of The Affected Areas.	\$	<i>nn</i> 170.00	<i>X</i>
To reinstall rear bumper parking sensor.	\$	170.00	<i>501</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00	<i>X</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nn</i> 380.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>101</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	<i>2001</i>
TOTAL	\$	14,170.00	
Over All Total	\$	23,573.28	

(PART-BY-PART) Repair Days*20 Days**2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: