



**KAH MOTOR CO. SDN. BHD.**  
 (A Member of the Oriental Holdings Berhad)  
 Service and Body Repair  
 Tel: +65 6841 3838 Website: www.honda.com.sg  
 For 24-hours Roadside Assistance, Call 98203838

*Survivor Copy.*

# QUOTATION

GST Reg No.: M200050223  
 Company Ref. No.: S60FC1380G

**Customer** : FIRST CAPITAL INSURANCE LTD  
 36 ROBINSON ROAD  
 #16-01 CITY HOUSE SINGAPORE 068877  
 SINGAPORE 68877  
**Registration No** : FBN4845E  
**Chassis No** : LWBMC4695J1307803  
**Model** : CBF190WHG ZSI  
**Owner's Name** : WONG JIN WEI, SAMUEL  
**Ins Policy No.** :  
**Date of Accident** :

**Document No.** : SQT0000007 **Page** 1  
**Date** : 31. Jan 2020  
**Customer No.** : 620  
**Svc Advisor** :  
**Engine No** : MC46E5064016  
**Date | Time** : 31. Jan 2020 7:51:00 PM  
**Surveyor Name** :  
**Survey Date** :  
**Authorisation Date** :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	DATE OF ACCIDENT: 16.09.2019 POLICY NO.: SD18V12927/VMS/R00 DATE TOW/DRIVE IN: 03.10.2019 SURVEYOR NAME: DATE SURVEY: AUTHORISED BY: EXCESS: 3RD PARTY VEHICLE NO.: SHC8637A CASE REF.:						
A00016	TOWING FROM TRAFFIC POLICE TO BSS	0.7	50.00		35.00	2.45	37.45
070798	TO REMOVE ALL DAMAGED PARTS, NECESSARY ATTACHMENT,	3 4	280.00		1120.00	78.40	1198.40
A06020	USING MCS TO ERASE/RESET DTC CODE. NETT	2.4	50.00		120.00	8.40	128.40
070799	KAPPA K42 TOP BOX	1	92.30		92.30	6.46	98.76
					<b>Sum Labor</b>	<b>1367.30</b>	<b>95.71</b>
							<b>1,463.01</b>
50530-K70-600	BAR COMP., SIDE STAND	1	11.50		11.50	0.81	12.31
88210-K70-601	MIRROR COMP., R	1	24.60		24.60	1.72	26.32
88220-K70-601	MIRROR COMP., L	1	24.60		24.60	1.72	26.32
53175-KRF-C91	LEVER COMP., R HNDL	1	14.50		14.50	1.02	15.52
50200-K70-600ZC	SET ILLUST., R SHROUD	1	157.50		157.50	11.03	168.53
50300-K70-620ZC	SET ILLUST., L SHROUD	1	162.50		162.50	11.38	173.88
46500-K70-600	PEDAL, RR. BRAKE	1	23.90		23.90	1.67	25.57
24781-KR3-770	CHANGE RUBBER PEDAL	1	5.50		5.50	0.39	5.89
24705-KZG-900	PEDAL COMP., CHANGE	1	29.90		29.90	2.09	31.99
50661-KZG-900	RUBBER, MAIN STEP	1	6.50		6.50	0.46	6.96
50609-KZG-900	PLATE, STEP SET	1	2.50		2.50	0.18	2.68
50635-KZG-900	ARM, R, MAIN STEP	1	17.00		17.00	1.19	18.19
90311-KZG-900	COLLAR 6MM	2	1.50		3.00	0.11	1.61

LKK Auto Consultants hence notify the Repairer of the following:  
 • To resurvey before after spray painting  
 • To display damaged part(s) during resurvey  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No illegal modification(s) is allowed  
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

Printed on 31/1/2020 8:19:36 PM

This is a computer generated invoice. No signature is required

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



**KAH MOTOR CO. SDN. BHD.**  
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

# QUOTATION

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

<b>Customer</b>	: FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877 SINGAPORE 68877	<b>Document No.</b>	: SQT0000007	<b>Page</b>	2
<b>Registration No</b>	: FBN4845E	<b>Date</b>	: 31. Jan 2020	<b>Customer No.</b>	: 620
<b>Chassis No</b>	: LWBMC4695J1307803	<b>Svc Advisor</b>	:	<b>Engine No</b>	: MC46E5064016
<b>Model</b>	: CBF190WHG ZSI	<b>Engine No</b>	: MC46E5064016	<b>Date   Time</b>	: 31. Jan 2020 7:51:00 PM
<b>Owner's Name</b>	: WONG JIN WEI, SAMUEL	<b>Surveyor Name</b>	:	<b>Survey Date</b>	:
<b>Ins Policy No.</b>	:	<b>Authorisation Date</b>	:		
<b>Date of Accident</b>	:				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
92501-060160A	BOLT, HEX., CAP 6X1 <i>✓ 4 pc</i>	2	1.80		3.60 ✓	0.25	3.85
90118-MBW-000	BLT SPECIAL 5X14 <i>✓ 1 pc</i>	1	2.35		2.35 ✓	0.16	2.51
50711-KZG-900	ARM, R. PILLION STEP <i>✓ 1 pc</i>	1	18.00		18.00 ✓	1.26	19.26
50630-K70-600	HOLDER, R. PILLION STEP <i>✓ 1 pc</i>	1	50.80		50.80 ✓	3.56	54.36
18300-K70-600	MUFFLER COMP, EXH <i>✓ 1 pc</i>	1	377.00		377.00 ✓	26.39	403.39
18311-K70-600	COVER A, MUFFLER <i>✓ 1 pc</i>	1	11.70		11.70 ✓	0.82	12.52
18312-K70-600	COVER B, MUFFLER <i>✓ 1 pc</i>	1	31.50		31.50 ✓	2.21	33.71
61100-K70-600ZB	FENDER ASSY, FR <i>✓ 1 pc</i>	1	78.60		78.60 ✓	5.50	84.10
77216-K70-620ZB	COWL SET, R. RR. (WL) <i>✓ 1 pc</i>	1	43.50		43.50 ✓	3.05	46.55
77226-K70-620ZB	COWL SET, L. RR. (WL) <i>✓ 1 pc</i>	1	43.50		43.50 ✓	3.05	46.55
51435-K70-601	DAMPER COMP, R FRONT <i>✓ 1 pc</i>	1	176.00		176.00 ✓	12.32	188.32
53100-K70-600ZA	PIPE COMP., R. STEERING HANDLE*NH303M* <i>✓ 1 pc</i>	1	171.80		171.80 ✓	12.03	183.83
53107-K70-600	WEIGHT, STEERING HANDLE <i>✓ 2 pc</i>	2	4.80		9.60 ✓	0.67	10.28
	<i>throttle cable A &amp; B ✓ 1 pc</i>						
					<b>Sum Item</b>	<b>1499.96</b>	<b>105.04</b>

Survey By	<u>Gino Riqms - 82880282</u>			
Date & Time	<u>05/02/2020</u>	<b>Total Amount</b>	2,867.26	200.75
Excess	<u>Gino Riqms @ 1kk auto.com</u>	<b>Total (Inclusive of GST)</b>		<b>3,068.01</b>
Status	<u>4 Days.</u>			
Signature	_____			

*signal lamp base RH ✓ 1 pc*  
*" " lens RH ✓ 1 pc*

*3045.96*  
*3310.258*

Printed on 31/1/2020 8:19:36 PM  
This is a computer generated invoice. No signature is required.  
Part prices are subjected to change without notice.  
The above estimated cost of repair do not include any unforeseen damages  
GST Amount is calculated from individual line(s).  
An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00  
However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**BOON SIEW SINGAPORE PTE LTD**

370 Ubi Road 3 (Level 2) Singapore 408651

255 Alexandra Road Singapore 159937

Tel: +65 6339 9002 Fax: +65 6333 4332

**SERVICE PRE-INVOICE**

GST Registration No.: M2-0027502-X

Company Registration No.: 197701866M

Customer: 620 / FIRST CAPITAL  
 Chassis No: LWBMC4695J1307803  
 License No: FBN4845E  
 Mileage: 0  
 Engine No: MC46E5064016

Document No: SVO-UB0000938  
 Printed By: BWTOH  
 Order Date: 17. February 2020  
 Order Time: 10:46:53 AM  
 Service Advisor:

**FINALISED**Date: 20/2/20

*Att: Guo Qiang*  
*4 days repair.*

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	DATE OF ACCIDENT:16.09.2019						
	POLICY NO.:SD18V12927/VMS/R00						
	DATE TOW/DRIVE IN:03.10.2019						
	SURVEYOR NAME:LKK, GUO QIANG						
	DATE SURVEY:05.02.20						
	AUTHORISED BY:LKK, KHANCHNA/10.02.20						
	EXCESS:N.A						
	3RD PARTY VEHICLE NO.:SHC8637A						
	CASE REF.:CC4/FCI20002028/GKA3						
50530-K70-600	BAR COMP., SIDE STAND	1	11.50		11.50	0.81	12.31
88210-K70-601	MIRROR COMP,R	1	24.60		24.60	1.72	26.32
88220-K70-601	MIRROR COMP,L	1	24.60		24.60	1.72	26.32
50200-K70-620ZC	SET ILLUSTR, R SHROUD	1	196.00		196.00	13.72	209.72
50300-K70-620ZC	SET ILLUSTR,L SHROUD	1	162.50		162.50	11.38	173.88
46500-K70-600	PEDAL, RR. BRAKE	1	23.90		23.90	1.67	25.57
24781-KR3-770	CHANGE RUBBER PEDAL	1	5.50		5.50	0.39	5.89
24705-KZG-900	PEDAL COMP., CHANGE	1	29.90		29.90	2.09	31.99
50661-KZG-900	RUBBER, MAIN STEP	1	6.50		6.50	0.46	6.96
50609-KZG-900	PLATE, STEP SET	1	2.50		2.50	0.18	2.68
50635-KZG-900	ARM,R, MAIN STEP	1	17.00		17.00	1.19	18.19
90311-KZG-900	COLLAR 6MM	2	1.50		3.00	0.21	3.21
92501-060160A	BOLT,HEX.,CAP 6X1	2	1.80		3.60	0.25	3.85
90118-MBW-000	BLT SPECIAL 5X14	1	2.35		2.35	0.16	2.51
50711-KZG-900	ARM, R. PILLION STEP	1	18.00		18.00	1.26	19.26
50630-K70-600	HOLDER, R. PILLION STEP	1	50.80		50.80	3.56	54.36
18300-K70-600	MUFFLER COMP, EXH	1	377.00		377.00	26.39	403.39
18311-K70-600	COVER A, MUFFLER	1	11.70		11.70	0.82	12.52
18312-K70-600	COVER B, MUFFLER	1	31.50		31.50	2.21	33.71
61100-K70-620ZA	FENDER ASSY.,FR.	1	78.60		78.60	5.50	84.10
77216-K70-620ZB	COWL SET, R. RR. (WL)	1	43.50		43.50	3.05	46.55
77226-K70-620ZB	COWL SET, L. RR. (WL)	1	43.50		43.50	3.05	46.55
51400-K70-601	FORK ASSY, R FRONT	1	314.70		314.70	22.03	336.73
53100-K70-600ZA	PIPE COMP., R. STEERING HANDLE*NH303M*	1	171.80		171.80	12.03	183.83
53107-K70-600	WEIGHT, STEERING HANDLE	2	4.80		9.60	0.67	10.27
17910-K70-601	CABLE COMP A, THROT	1	17.00		17.00	1.19	18.19
17920-K70-601	CABLE COMP B, THROT	1	16.50		16.50	1.16	17.66
33400-K70-601	WINKER ASSY, RFR	1	122.80		122.80	8.60	131.40
50730-K70-600	HOLDER, R. MAIN	1	85.49		85.49	5.98	91.47
53178-KCS-W60	LEVER COP,L HNDL	1	22.50		22.50	1.58	24.08
	<b>SUM PARTS:</b>				<b>1,928.44</b>	<b>135.03</b>	<b>2,063.47</b>
A00016	027-UB TOWING FROM TRAFFIC POLICE TO BSS (RECEIPT NO. ....)	1	35.00		35.00	2.45	37.45
070798	027-UB TO REMOVE ALL DAMAGED PARTS, NECESSARY ATTACHMENT,	1	840.00		840.00	58.80	898.80

0.c

11.5+  
 24.6+  
 24.6+  
 196.+  
 162.5+  
 23.9+  
 5.5+  
 29.9+  
 6.5+  
 2.5+  
 17.+  
 3.+  
 3.6+  
 2.35+  
 18.+  
 50.8+  
 377.+  
 11.7+  
 31.5+  
 78.6+

43.5+  
 43.5+  
 314.7+  
 171.8+  
 9.6+ =

1,664.15\*

0.c

~~17.~~  
~~0.c~~

17.+  
 16.5+  
 122.8+  
 85.49+  
 22.5=  
 264.29\*

(\*)

0.c

35.+  
 840.+  
 120.+  
 92.3=  
 1,087.3\*

0.c

1,664.15+  
 264.29+  
 1,087.3=  
 3,015.74\*

P/v