



KAH MOTOR CO. SDN. BHD.
 (A Member of the Oriental Holdings Berhad)
 Service and Body Repair

Tel: +65 6841 3838 Website: www.honda.com.sg
 For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
 Company Ref. No.: S60FC1380G

Customer : FIRST CAPITAL INSURANCE LTD
 36 ROBINSON ROAD
 #16-01 CITY HOUSE SINGAPORE 068877
 SINGAPORE 68877

Registration No : FBN4845E
Chassis No : LWBMC4695J1307803
Model : CBF190WHG ZSI
Owner's Name : WONG JIN WEI, SAMUEL
Ins Policy No. :
Date of Accident :

Document No. : SQT0000007 Page 1
Date : 31. Jan 2020
Customer No. : 620
Svc Advisor :
Engine No : MC46E5064016
Date | Time : 31. Jan 2020 7:51:00 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc	Amount	0% GST Amount	Amount incld GST	
	DATE OF ACCIDENT:16.09.2019							
	POLICY NO.:SD18V12927/VMS/R00							
	DATE TOW/DRIVE IN:03.10.2019							
	SURVEYOR NAME:							
	DATE SURVEY:							
	AUTHORISED BY:							
	EXCESS:							
	3RD PARTY VEHICLE NO.:SHC8637A							
	CASE REF.:							
A00016	TOWING FROM TRAFFIC POLICE TO BSS	0.7	50.00		35.00	2.45	37.45	
070798	TO REMOVE ALL DAMAGED PARTS, NECESSARY ATTACHMENT,	3 4	280.00		1120.00	78.40	1198.40	
A06020	USING MCS TO ERASE/RESET DTC CODE. NETT	2.4	50.00		120.00	8.40	128.40	
070799	KAPPA K42 TOP BOX / Cut	1	92.30		92.30	6.46	98.76	
					Sum Labor	1367.30	95.71	1,463.01
50530-K70-600	BAR COMP., SIDE STAND / BT	1	11.50		11.50	0.81	12.31	
88210-K70-601	MIRROR COMP,R / Sant.	1	24.60		24.60	1.72	26.32	
88220-K70-601	MIRROR COMP,L / Sant.	1	24.60		24.60	1.72	26.32	
53175-KRF-C91	LEVER COMP, R HNDL / Cut.	1	14.50		14.50	1.02	15.52	
50200-K70-600ZC	SET ILLUST,R SHROUD / Sant.	1	157.50		157.50	11.03	168.53	
50300-K70-620ZC	SET ILLUST,L SHROUD / Sant.	1	162.50		162.50	11.38	173.88	
46500-K70-600	PEDAL, RR. BRAKE / BT.	1	23.90		23.90	1.67	25.57	
24781-KR3-770	CHANGE RUBBER PEDAL / Cut.	1	5.50		5.50	0.39	5.89	
24705-KZG-900	PEDAL COMP., CHANGE / BT.	1	29.90		29.90	2.09	31.99	
50661-KZG-900	RUBBER, MAIN STEP / Sant	1	6.50		6.50	0.46	6.96	
50609-KZG-900	PLATE, STEP SET /	1	2.50		2.50	0.18	2.68	
50635-KZG-900	ARM,R, MAIN STEP / BR	1	17.00		17.00	1.19	18.19	
90311-KZG-900	COLLAR 6MM / ABC	1	1.50		1.50	0.11	1.61	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before final pricing
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Printed on 31/1/2020 8:19:36 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE SINGAPORE 068877
SINGAPORE 68877

Registration No : FBN4845E

Chassis No : LWBMC4695J1307803

Model : CBF190WHG ZSI

Owner's Name : WONG JIN WEI, SAMUEL

Ins Policy No. :

Date of Accident :

Document No. : SQT0000007

Date : 31. Jan 2020

Customer No. : 620

Svc Advisor :

Engine No : MC46E5064016

Date | Time : 31. Jan 2020 7:51:00 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
92501-060160A	BOLT, HEX., CAP 6X1 <i>--- 4 pc</i>	2	1.80		3.60	0.25	3.85
90118-MBW-000	BLT SPECIAL 5X14 <i>--- 4 pc</i>	1	2.35		2.35	0.16	2.51
50711-KZG-900	ARM, R. PILLION STEP <i>--- 4 cut</i>	1	18.00		18.00	1.26	19.26
50630-K70-600	HOLDER, R. PILLION STEP <i>--- 4 cut</i>	1	50.80		50.80	3.56	54.36
18300-K70-600	MUFFLER COMP, EXH <i>--- cut?</i>	1	377.00		377.00	26.39	403.39
18311-K70-600	COVER A, MUFFLER <i>--- cut</i>	1	11.70		11.70	0.82	12.52
18312-K70-600	COVER B, MUFFLER <i>--- cut</i>	1	31.50		31.50	2.21	33.71
61100-K70-600ZB	FENDER ASSY, FR <i>--- cut</i>	1	78.60		78.60	5.50	84.10
77216-K70-620ZB	COWL SET, R. RR. (WL) <i>--- 4 cut</i>	1	43.50		43.50	3.05	46.55
77226-K70-620ZB	COWL SET, L. RR. (WL) <i>--- 4 cut</i>	1	43.50		43.50	3.05	46.55
51435-K70-601	DAMPER COMP, R FRONT <i>--- cut</i>	1	176.00		176.00	12.32	188.32
53100-K70-600ZA	PIPE COMP., R. STEERING HANDLE*NH303M* <i>--- BT</i>	1	171.80		171.80	12.03	183.83
53107-K70-600	WEIGHT, STEERING HANDLE <i>--- cut</i>	2	4.80		9.61	0.67	10.28
	<i>throttle cable A & B --- cut</i>						
					Sum Item	1499.96	105.04

Survey By Guo Qiang - 82880282

Date & Time 05/02/2020 Total Amount 2,867.26 200.75 3,068.01

Excess Guo Qiang @ 1kk auto.com Total (Inclusive of GST) 3,068.01

Status 4 Days.

Signature _____

signal lamp base RH --- 4 cut.

" " lens RH --- 4 cut.

Printed on 31/1/2020 8:19:36 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.